

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 2122900058 Email:

EMSLAttn: Commercial Lab Enterprise
270 Swinton Ave
Bronx, NY 10465

Fax: (718) 904-9117

Phone: 718-792-2832

Project: 80 North Moore Street NY NY

Customer ID: COMM56

Customer PO:

Received: 11/05/01 1:00 PM

EMSL Order: 030107492


EMSL Project ID:

Analysis Date: 11/5/01

**Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by
EPA 40 CFR Part 763 Final Rule (AHERA)**

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structure 0.5µ - 5µ ≥ 5µ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm ²) (S/cc)	Notes
575 030107492-0001	1300.00	0.1250	0	None Detected		0.0024	<8.00 <0.0024	
576 030107492-0002	1300.00	0.1250	0	None Detected		0.0024	<8.00 <0.0024	
577 030107492-0003	1300.00	0.1250	0	None Detected		0.0024	<8.00 <0.0024	
578 030107492-0004	1340.00	0.0625	1	None Detected		0.0046	<16.00 <0.0046	
579 030107492-0005	1310.00	0.0625	0	None Detected		0.0047	<16.00 <0.0047	
580 030107492-0006	1400.00	0.0625	0	None Detected		0.0044	<16.00 <0.0044	
581 030107492-0007	1400.00	0.0625	0	None Detected		0.0044	<16.00 <0.0044	
582 030107492-0008	1400.00	0.0625	0	None Detected		0.0044	<16.00 <0.0044	
583 030107492-0009	1390.00	0.0625	0	None Detected		0.0044	<16.00 <0.0044	
584 030107492-0010	1500.00	0.0625	4	None Detected		0.0041	<16.00 <0.0041	
585 030107492-0011	1500.00	0.0625	2	None Detected		0.0041	<16.00 <0.0041	

Thomas Michel (45)


 Laboratory Manager
 or other approved signatory

Disclaimers: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by EMSL. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysts' accuracy and precision) is available upon request.

Accredited for NVLAP PLM/TEM #101048-9, NY State ELAP #11503

TEMAHERA-1

1

CITY_21MC100_010315389

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 2122900058 Email:

EMSLAttn: Commercial Lab Enterprise
270 Swinton Ave
Bronx, NY 10465

Fax: (718) 904-9117

Phone: 718-792-2832

Project: 80 North Moore Street NY NY

Customer ID: COMM56

Customer PO:

Received: 11/05/01 1:00 PM

EMSL Order: 030107492

EMSL Project ID:

Analysis Date: 11/5/01

**Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by
EPA 40 CFR Part 763 Final Rule (AHERA)**

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structure 0.5µ - 5µ ≥ 5µ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm ²) (S/cc)	Notes
586 030107492-0012	1500.00	0.0625	0	None Detected		0.0041	<16.00 <0.0041	
587 030107492-0013	1500.00	0.0625	0	None Detected		0.0041	<16.00 <0.0041	
588 030107492-0014	1500.00	0.0625	0	None Detected		0.0041	<16.00 <0.0041	
589 030107492-0015	1520.00	0.0625	0	None Detected		0.0041	<16.00 <0.0041	
590 030107492-0016	1500.00	0.0625	0	None Detected		0.0041	<16.00 <0.0041	
591 030107492-0017	1500.00	0.0625	0	None Detected		0.0041	<16.00 <0.0041	
592 030107492-0018	1500.00	0.0625	0	None Detected		0.0041	<16.00 <0.0041	
593 030107492-0019	1500.00	0.0625	0	None Detected		0.0041	<16.00 <0.0041	
594 030107492-0020	1500.00	0.0625	0	None Detected		0.0041	<16.00 <0.0041	
595 030107492-0021	1500.00	0.0625	0	None Detected		0.0041	<16.00 <0.0041	
596 030107492-0022	1500.00	0.0625	0	None Detected		0.0041	<16.00 <0.0041	

Thomas Michel (45)

Laboratory Manager
or other approved signatory

Disclaimers: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mmi². This report may not be reproduced, except in full, without written approval by EMSL. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysis accuracy and precision) is available upon request.

Accredited for NVLAP PLMTEM #101048-9, NY State ELAP #11506

TEMAHERA-1

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 2122900058 Email:

EMSLAttn: Commercial Lab Enterprise
270 Swinton Ave
Bronx, NY 10465

Fax: (718) 904-9117

Phone: 718-792-2832

Project: 80 North Moore Street NY NY

Customer ID: COMM56

Customer PO:

Received: 11/05/01 1:00 PM

EMSL Order: 030107492

EMSL Project ID:

Analysis Date: 11/5/01

**Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by
EPA 40 CFR Part 763 Final Rule (AHERA)**

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structure 0.5µ - 5µ ≥ 5µ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm ²) (S/cc)	Notes
597 030107492-0023	1500.00	0.0625	0	None Detected		0.0041	<16.00 <0.0041	
598 030107492-0024	1540.00	0.0625	0	None Detected		0.0040	<16.00 <0.0040	
599 030107492-0025	1510.00	0.0625	0	None Detected		0.0041	<16.00 <0.0041	
600 030107492-0026	1600.00	0.0500	0	None Detected		0.0048	<20.00 <0.0048	
601 030107492-0027	1600.00	0.0500	0	None Detected		0.0048	<20.00 <0.0048	
602 030107492-0028	1600.00	0.0500	0	None Detected		0.0048	<20.00 <0.0048	
603 030107492-0029	1600.00	0.0500	0	None Detected		0.0048	<20.00 <0.0048	
604 030107492-0030	1610.00	0.0500	0	None Detected		0.0048	<20.00 <0.0048	
605 030107492-0031	1250.00	0.0625	1	None Detected		0.0049	<16.00 <0.0049	
606 030107492-0032	1250.00	0.0625	0	None Detected		0.0049	<16.00 <0.0049	
607 030107492-0033	1250.00	0.0625	0	None Detected		0.0049	<16.00 <0.0049	

Thomas Michel (45)

Laboratory Manager
or other approved signatory

Disclaimers: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by EMSL. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysts' accuracy and precision) is available upon request.

Accredited for NVLAP PLM/TEM #101048-9, NY State ELAP #1150G

TEMAHERA-1

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 212-290-0058 Email:



Attn: Commercial Lab Enterprise
270 Swinton Ave
Bronx, NY 10465

Fax: (718) 904-9117 Phone: 718-792-2632
Project: 80 North Moore Street NY NY

Customer ID: COMM56
Customer PO:
Received: 11/05/01 1:00 PM
EMSL Order: 030107492
EMSL Project ID:

Analysis Date: 11/5/01

**Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by
EPA 40 CFR Part 763 Final Rule (AHERA)**

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structure 0.5μ -5μ ≥ 5μ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm ²) (S/cc)	Notes
608 030107492-0034	1260.00	0.0625	0	None Detected		0.0049	<16.00 <0.0049	
609 030107492-0035	1260.00	0.0625	0	None Detected		0.0049	<16.00 <0.0049	
610 030107492-0036	1250.00	0.0625	2	None Detected		0.0049	<16.00 <0.0049	
611 030107492-0037	1250.00	0.0625	0	None Detected		0.0049	<16.00 <0.0049	
612 030107492-0038	1250.00	0.0625	0	None Detected		0.0049	<16.00 <0.0049	
613 030107492-0039	1250.00	0.0625	0	None Detected		0.0049	<16.00 <0.0049	
614 030107492-0040	1240.00	0.0750	0	None Detected		0.0041	<13.33 <0.0041	
615 030107492-0041	1250.00	0.0625	0	None Detected		0.0049	<16.00 <0.0049	
616 030107492-0042	1250.00	0.0625	0	None Detected		0.0049	<16.00 <0.0049	
617 030107492-0043	1240.00	0.0750	0	None Detected		0.0041	<13.33 <0.0041	
618 030107492-0044	1250.00	0.0625	0	None Detected		0.0049	<16.00 <0.0049	

Thomas Michel (45)

Laboratory Manager
or other approved signatory

Disclaimers: The laboratory is not responsible for data reported in structures/cc, which is dependant on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by EMSL. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory data) analysts' accuracy and precision) is available upon request.

Accredited for NVLAP PLM/TEM #101048-9, NY State ELAP #11505

TEMAHERA-1

CITY_21MC100_010315392