

228 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-0630

P.O. _____

WARREN & PANZER ENGINEERS, P.C.
AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

CLIENT: NYC DEP
PROJECT: WTC SAMPLING
LOCATION: _____

W&P FILE #: 1070-01-01
TURN AROUND: _____
TECHNICIAN: FESTY OSEMELENE

Analysis Method: PCM-7400
(circle one) TEM - AHERA
TEM - EPA LEVEL II

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE		TIME		TOTAL TIME	VOLUME (liters)	CONCENTR. (fib./cc.)	μm ²
				START	STOP	ON	OFF				
01	F. Blank	1								—	0.0
02	F. Blank	1								—	0.0
03	11	8		15	15	0805	0850	45	675	40.004	
04	15	8		15	15	0900	0945	45	675		
05	29	8		15	15	0955	1040	45	675		
06	20A	8		15	15	1050	1135	45	675		
07	21	8		15	15	1145	1230	45	675		
08	16	8		15	15	1240	1325	45	675		
09	12	8		15	15	1335	1420	45	675		

SAMPLED BY: FESTY OSEMELENE DATE: 05-08-02
SIGNATURE: _____
RELEASED BY: _____ DATE: _____
SIGNATURE: _____
RECEIVED BY: Abram Mullaikandor DATE: 05/09/02
SIGNATURE: [Signature]

N000548

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION