

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 212-290-0058 Email:

EMSL

Attn: JLC Environmental Consultants, Inc

200 Park Ave South
Suite 1106

New York, NY 10003

Fax: (212) 420-8092

Phone: 212-420-8119

Project: 01-2084-003 P.S. 64 300 E 6th St #3 of 5

Customer ID: JLCC50

Customer PO:

Received: 09/23/01 6:10 PM

EMSL Order: 030104828

EMSL Project ID:


Analysis Date: 9/24/2001

Fiber Analysis of Air Samples via NIOSH 7400, Revision 3, Issue 2, 8/15/94

Sample	Location	Sample Date	Volume	Fibers	Fields	LOD (fib/cc)	Fibers/ mm ³	Fibers/ cc	Notes
01 030104828-0001	South East Section of Roof	9/23/2001	1837.80	<5.5	100	0.001	<7.0	<0.001	
02 030104828-0002	South West Section of Roof	9/23/2001	1837.80	<5.5	100	0.001	<7.0	<0.001	
03 030104828-0003	Behind Bulk Head Door / Exit #1 / Roof	9/23/2001	1837.80	<5.5	100	0.001	<7.0	<0.001	
04 030104828-0004	Field blank	9/23/2001	0.00	<5.5	100		<7.0		Field Blank

Rey Cross

Analyst

Laboratory Manager
or other approved signatory

Limit of detection is 7 fibers/mm³. This laboratory is not responsible for data reported in fibers/cc, which is dependent on volume collected by non-laboratory personnel. This report relates only to the samples reported above. This report may not be reproduced, except in full, without written approval by EMSL.

Analysis performed by EMSL Manhattan (NY State ELAP #11506)

PCM 1

1