

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 212-290-0058 Email:

EMSLAttn: Pedneault Associates, Inc.
1815 Ninth Avenue
Bohemia, NY 11716

Fax: (831) 467-5905

Phone: 631-467-6477

Project: 01-2084-001 / DEP / PS 314K 330 59th St. Brooklyn, NY
Roof

Customer ID: PEDN50

Customer PO:

Received: 09/18/01 6:00 PM

EMSL Order: 030104451

EMSL Project ID:

Analysis Date: 9/18/2001

Fiber Analysis of Air Samples via NIOSH 7400, Revision 3, Issue 2, 8/15/94

Sample	Location	Sample Date	Volume	Fibers	Fields	LOD (flb/cc)	Fibers/ mm ³	Fibers/ cc	Notes
01 030104451-0001	South Section on Roof PS314	9/18/2001	1824.00	<5.5	100	0.001	<7.0	<0.001	
02 030104451-0002	West Section on Roof PS314	9/18/2001	1812.00	<5.5	100	0.001	<7.0	<0.001	
03 030104451-0003	East Section on Roof PS314	9/18/2001	1815.00	<5.5	100	0.001	<7.0	<0.001	
04 030104451-0004	Field Blank	9/18/2001	0.00	<5.5	100		<7.0		Field Blank

INSUFFICIENT BLANKS SUBMITTED

Thomas Michel

Analyst

Laboratory Manager
or other approved signatory

Limit of detection is 7 fibers/mm³. The laboratory is not responsible for data reported in fibers/cc, which is dependent on volume collected by non-laboratory personnel. This report relates only to the samples reported above. This report may not be reproduced, except in full, without written approval by EMSL.

Analysis performed by EMSL Manhattan (NY State E-LAP #11606)

PCN-1

1