

**New York Lab**

307 West 38th Street, New York, NY 10018

Phone: 212-290-0951 Fax: 212-290-0058 Email:

**EMSL**

Attn: JLC Environmental Consultants, Inc.  
200 Park Ave South  
Suite 1105  
New York, NY 10003

Fax: (212) 420-6092

Phone: 212-420-6119

Project: 01-2084-001 / DEP / 330-59th St PS 314K

Customer ID: JLCC50

Customer PO:

Received: 09/19/01 6:35 PM

EMSL Order: 030104540

EMSL Project ID:

Analysis Date: 9/19/2001

**Fiber Analysis of Air Samples via NIOSH 7400, Revision 3, Issue 2, 8/15/94**

| Sample               | Location                                       | Sample Date | Volume  | Fibers | Fields | LOD<br>(fib/cc) | Fibers/<br>mm <sup>2</sup> | Fibers/<br>cc | Notes       |
|----------------------|------------------------------------------------|-------------|---------|--------|--------|-----------------|----------------------------|---------------|-------------|
| 01<br>030104540-0001 | Ambient / Roof Top<br>NW side Near<br>Bulkhead | 9/19/2001   | 1800.00 | <5.5   | 100    | 0.001           | <7.0                       | <0.001        |             |
| 02<br>030104540-0002 | Ambient / Roof Top<br>W side of Roof           | 9/19/2001   | 1800.00 | <5.5   | 100    | 0.001           | <7.0                       | <0.001        |             |
| 03<br>030104540-0003 | Ambient / Roof Top<br>SE side of Roof          | 9/19/2001   | 1800.00 | <5.5   | 100    | 0.001           | <7.0                       | <0.001        |             |
| 04<br>030104540-0004 | Field blank                                    | 9/19/2001   | 0.00    | <5.5   | 100    |                 | <7.0                       |               | Field Blank |

George Boble

Analyst

Laboratory Manager  
or other approved signatory

Limit of detection is 7 fibers/mm<sup>2</sup>. The laboratory is not responsible for data reported in fibers/cc, which is dependent on volume collected by non-laboratory personnel. This report relates only to the samples reported above. This report may not be reproduced, except in full, without written approval by EMSL.  
Analysis performed by EMSL Manhattan (NY State ELAP #11506)

PCM 1

1