

**New York Lab**

307 West 38th Street, New York, NY 10018

Phone: 212-298-0041 Fax: 212-298-0058 Email:

**EMSL**Attn: Pedneault Associates, Inc.  
1815 Ninth Avenue  
Bohemia, NY 11716

Fax: (831) 487-8905

Phone: 831-487-8477

Project: 01-2084-001 / DEP / PS 314 K 330 59th St. Brooklyn, NY

Customer ID: PEDN50

Customer PO:

Received: 09/17/01 8:35 PM

EMSL Order: 030104380

EMSL Project ID:

Analysis Date: 9/17/01

**Fiber Analysis of Air Samples via NIOSH 7400, Revision 3, Issue 2, 8/15/94**

| Sample              | Location                                                 | Sample Date | Volume  | Fibers | Fields | LOD<br>(f/c) | Fibers/<br>mm <sup>3</sup> | Fibers/<br>cc | Notes       |
|---------------------|----------------------------------------------------------|-------------|---------|--------|--------|--------------|----------------------------|---------------|-------------|
| 1<br>030104380-0001 | 12 Ft of Door<br>Entrance on Roof PS<br>314K Stairwell 1 | 9/17/01     | 1806.00 | 8.5    | 100    | 0.001        | 10.83                      | 0.002         |             |
| 2<br>030104380-0002 | Center on Roof<br>PS314K                                 | 9/17/01     | 1818.00 | <3.5   | 100    | 0.001        | <7.0                       | <0.001        |             |
| 3<br>030104380-0003 | North Section on roof<br>PS314K                          | 9/17/01     | 1812.00 | 5.5    | 100    | 0.001        | 7.01                       | 0.002         |             |
| 4<br>030104380-0004 | Field Blank                                              | 9/17/01     | 0.00    | <5.5   | 100    |              | <7.0                       |               | Field Blank |

Ram Yalabandi

Analyst

Laboratory Manager  
or other approved signatory

Limit of detection is 7 fibers/mm<sup>3</sup>. The laboratory is not responsible for data reported in fibers/cc, which is dependent on volume collected by non-laboratory personnel. This report relates only to the samples reported above. This report may not be reproduced, except in full, without written approval by EMSL.  
Analysis performed by EMSL Manhattan (NY State ELAP #11505)

PCN-1

1