

New York Lab

307 West 39th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 212-290-0058 Email:



Attn: U.S. EPA - Residential
 HQ Financial Services Division
 1200 Pennsylvania Ave. NW Maildrop 2734R
 Washington, DC 20460

Fax: Phone:

Project: USPHS MISSION 12 RESIDENTIAL SAMPLING NEW
 YORK CITY BLDG 21/ 250 SOUTH END

Customer ID: USEPA44
 Customer PO: 2W-1104-NNLX
 Received: 12/06/01 7:20 PM

EMSL Order: 030109325
 EMSL Project ID:


Analysis Date: 12/8/01

Asbestos Analysis of Bulk Materials by PLM via the NY State ELAP 198.1 Method

Sample	Location	Appearance	Treatment	Non-Asbestos		Asbestos
				% Fibrous	% Non-Fibrous	% Type
RJSA-O-2B	OUTDOORS	Gray/Tan	Teased	25.00% Glass	33.70% Non-fibrous (other)	1.30% Chrysotile
030109325-0001		Fibrous Heterogeneous	Dissolved	40.00% Cellulose		

Williams John

Analyst


 Laboratory Manager
 or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government.

Analysis performed by EMSL Manhattan (NVLAP #01048-9), NY ELAP #1500

PLM PrintCount-1

1

CITY_21MC100_003034826