

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 2122000056 Email:

EMSL

Attn: U. S. EPA
HQ Financial Services Division
1200 Pennsylvania Ave. NW Maildrop 2734R
Washington, DC 20460

Customer ID: USEPA30
Customer PO: ZW-1104-NNLX
Received: 11/16/01 7:20 PM

Fax: Phone:
Project: USPHS Mission #12: Residential Sampling New York
City / Bldg 6 / 225 Rector Pl.

EMSL Order: 030108142
EMSL Project ID:

Analysis Date: 11/17/01

Asbestos Analysis of Bulk Materials by PLM via the NY State ELAP 198.1 Method

Sample	Location	Appearance	Treatment	Non-Asbestos		Asbestos
				% Fibrous	% Non-Fibrous	% Type
[R]JA-C-6 030108142-0001	Common Area	Brown Fibrous Heterogeneous	Teased Dissolved	10.00% Glass 30.00% Cellulose	60.00% Non-fibrous (other)	None Detected
[R]JA-R1-6 030108142-0002	Residence 1	Brown/Tan Fibrous Heterogeneous	Teased Dissolved	15.00% Hair 15.00% Glass 30.00% Cellulose	40.00% Non-fibrous (other)	None Detected
[R]JA-R2-6 030108142-0003	Residence 2	Brown/Tan Fibrous Heterogeneous	Teased Dissolved	10.00% Synthetic 15.00% Glass 40.00% Cellulose	35.00% Non-fibrous (other)	None Detected

Williams John

Analyst

Laboratory Manager
or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government.

Analysis performed by EMSL Manhattan (NVLAP #101046-9), NY ELAP 11506

PLM Print Count-1

1