NYC 9/11 Public Portal Document

file - Interim sampling result

New York Lab
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email:

Attn: U.S. EPA - Residential
HQ Financial Services Division
1200 Pennsylvania Ave. NW Maildrop 2734R
Washington, DC 20460

Fax: Phone:

Project: USPHS Mission #12 Residential Sampling New York City Bldg 6,7,12-23,26,29,31-34

Customer ID: USEPA44
Customer PO: 2W-1103-NNLX
Received: 12/13/01 2:05 PM

EMSL Order: 030109702
EMSL Project ID:

Analysis Date 12/14/01

Asbestos Analysis of Non-Friable Organically Bound materials by Transmission Electron Microscopy via NYS ELAP Method 198.4

SAMPLE ID	DESCRIPTION	APPEARANCE	MATRIX MATERIAL	NON-ASBESTOS FIBERS	ASBESTOS TYPES		TOTAL ASBESTOS
[R]VA-R1-7 030109702-0001	RESIDENCE 1		100.0	None		No Asbestos Detected	
[R]VA-R2-7 030109702-0002	RESIDENCE 2		100.0	None		No Asbestos Detected	
[R]SA-O-7 030109702-0003	OUTDOORS		98.3	None	1.7	Chrysotile	1.7
[R]VA-C-7 030109702-0004	COMMON AREA		100.0	None		No Asbestos Detected	
[R]VA-C-12 030109702-0005	COMMON AREA		100.0	None		No Asbestos Detected	
[R]VA-R1-12 030109702-0006	RESIDENCE 1		100.0	None		No Asbestos Detected	
[R]VA-R2-12 030109702-0007	RESIDENCE 2		100.0	None		No Asbestos Detected	
[R]VA-C-13 030109702-0008	COMMON AREA		100.0	None		No Asbestos Detected	
[R]VA-R1-13 030109702-0009	RESIDENCE 1		100.0	None		No Asbestos Detected	
[R]VA-R2-13 030109702-0010	RESIDENCE 2		100.0	None		No Asbestos Detected	
[R]VA-C-14 030109702-0011	COMMON AREA		100.0	None		No Asbestos Detected	

Analyst

Laboratory Manager
or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc.

ACCREDITATIONS: NVLAP #101048-0 and NY STATE ELAP #11506

NY-NOB-1

CITY_21MC100_003036347

NYC-WTC_000199806

NYC 9/11 Public Portal Document

New York Lab
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email:

Attn: U.S. EPA - Residential
HQ Financial Services Division
1200 Pennsylvania Ave, NW Maildrop 2734R
Washington, DC 20460

Fax: Phone:

Project: USPHS Mission #12 Residential Sampling New York City Bldg 6,7,12-23,26,29,31-34

Customer ID: USEPA44
Customer PO: 2W-1103-NNLX
Received: 12/13/01 2:05 PM

EMSL Order: 030109702
EMSL Project ID:

Analysis Date 12/14/01

Asbestos Analysis of Non-Friable Organically Bound materials by Transmission Electron Microscopy via NYS ELAP Method 198.4

SAMPLE ID	DESCRIPTION	APPEARANCE	MATRIX MATERIAL	NON-ASBESTOS FIBERS	ASBESTOS TYPES		TOTAL ASBESTOS
[R]VA-R1-14 030109702-0012	RESIDENCE 1		100.0	None		No Asbestos Detected	
[R]VA-R2-14 030109702-0013	RESIDENCE 2		100.0	None		No Asbestos Detected	
[R]SA-O-15 030109702-0014	OUTDOORS		98.1	None	1.9	Chrysotile	1.9
[R]VA-C-15 030109702-0015	COMMON AREA		100.0	None		No Asbestos Detected	
[R]VA-R1-15 030109702-0016	RESIDENCE 1		100.0	None	<1	Chrysotile	<1
[R]VA-R2-15 030109702-0017	RESIDENCE 2		100.0	None		No Asbestos Detected	
[R]VA-C-16 030109702-0018	COMMON AREA		100.0	None		No Asbestos Detected	
[R]VA-R2-16 030109702-0019	RESIDENCE 2		100.0	None		No Asbestos Detected	
[R]SA-O-16 030109702-0020	OUTDOORS		100.0	None		No Asbestos Detected	
[R]VA-C-17 030109702-0021	COMMON AREA		100.0	None		No Asbestos Detected	
[R]VA-R1-17 030109702-0022	RESIDENCE 1		100.0	None		No Asbestos Detected	

Analyst

Laboratory Manager
or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc.

ACCREDITATIONS: NVLAP #101048-0 and NY STATE ELAP #11505

NY OB-

CITY_21MC100_003036348

NYC-WTC_000199807