

***Residential Sampling Status - Category
by Building Number (Jan 7, 2002)***

The table below contains a summary of the asbestos results received as of Jan 7, for each of the 34 buildings sampled. Buildings 1-30 were sampled for asbestos concerns, buildings 31 - 34 represent background levels in unaffected NYC apartment buildings.

Code:

ND - Non-detect lab result
 NS - No sample provided to lab
 expecting - a result is still expected from the lab
 not exp'd - a result is not expected from the lab
 ins. mass - insufficient mass to analyze dust sample
 Waiting for lab results - Results are required for one or more analyses
 Review - Results obtained indicate a review is necessary to evaluated asbestos hazard
 No Asbestos Hazard - Asbestos not detected in dust or insufficient dust to collect a sample & low fiber concentration in air

Table Footnotes:

- *1 - Surface area covered for asbestos removal, no dust sample available
- *2 - No dust available to collect
- *3 - Unknown; reason was not specified on survey or chain of custody form
- *4 - No consent from building management to do monitoring in outdoor or common areas

Summary of results for buildings 1-30:

Number of buildings with 'No Asbestos Hazard'	= 15
Number of buildings 'Waiting for lab results'	= 8
Number of building where 'Review' is necessary	= 7

Summary of results for the residential units in buildings 1-30:

Total number of residential units	= 59
Number of units with 'No Asbestos Hazard'	= 40
Number of units 'Waiting for lab results'	= 13
Number of units where 'Review' is necessary	= 6