

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 212-290-0058 Email:

EMSL

Attn: CTSI-Consulting & Testing Services, Inc.
622 Georges Rd.
North Brunswick, NJ 08902

Fax: (732) 729-1803 Phone: 732-729-1800

Project: 111 Broadway/Entire Bldg/AQ

Customer ID: CTSI50
Customer PO:
Received: 10/21/01 9:10 PM
EMSL Order: 030106706
EMSL Project ID:
Analysis Date: 10/22/2001

Fiber Analysis of Air Samples via NIOSH 7400, Revision 3, Issue 2, 8/15/94

Sample	Location	Sample Date	Volume	Fibers	Fields	LOD (fib/cc)	Fibers/ mm ²	Fibers/ cc	Notes
01 030106706-0001	11th Fl-West/Hallway	10/21/2001	1680.00	<5.5	100	0.002	<7.0	<0.002	
02 030106706-0002	10th Fl-West/Hallway	10/21/2001	1800.00	<5.5	100	0.001	<7.0	<0.001	
03 030106706-0003	9th Fl-West/Hallway	10/21/2001	1680.00	<5.5	100	0.002	<7.0	<0.002	
04 030106706-0004	8th Fl-West/Hallway	10/21/2001	1800.00	<5.5	100	0.001	<7.0	<0.001	
05 030106706-0005	7th Fl-West/Hallway	10/21/2001	1820.00	<5.5	100	0.001	<7.0	<0.001	
06 030106706-0006	6th Fl-West/Hallway	10/21/2001	1815.00	<5.5	100	0.001	<7.0	<0.001	
07 030106706-0007	5th Fl-West/Hallway	10/21/2001	1920.00	<5.5	100	0.001	<7.0	<0.001	
08 030106706-0008	4th Fl-East/Hallway	10/21/2001	1680.00	<5.5	100	0.002	<7.0	<0.002	
09 030106706-0009	3rd Fl-East/Hallway	10/21/2001	1694.00	<5.5	100	0.002	<7.0	<0.002	
10 030106706-0010	2nd Fl-East/Hallway	10/21/2001	2054.00	<5.5	100	0.001	<7.0	<0.001	
11 030106706-0011	21st Fl-East/Hallway	10/21/2001	2040.00	<5.5	100	0.001	<7.0	<0.001	
12 030106706-0012	20th Fl-East/Hallway	10/21/2001	1936.00	<5.5	100	0.001	<7.0	<0.001	

Dawnette Branson

Analyst

Em B. B. B.
Laboratory Manager
or other approved signatory

Limit of detection is 7 fibers/mm². The laboratory is not responsible for data reported in fibers/cc, which is dependent on volume collected by non-laboratory personnel. This report relates only to the samples reported above. This report may not be reproduced, except in full, without written approval by EMSL.
Analysis performed by EMSL Manhattan (NY State ELAP #11506)

EMSL**New York Lab**

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 2122900058 Email:

Attn: CTSI-Consulting & Testing Services, Inc.
622 Georges Rd.
North Brunswick, NJ 08902

Fax: (732) 729-1803 Phone: 732-729-1800

Project: 111 Broadway/Entire Bldg/AQ

Customer ID: CTSI50

Customer PO:

Received: 10/21/01 9:10 PM

EMSL Order: 030106706

EMSL Project ID:

Analysis Date: 10/22/2001

Fiber Analysis of Air Samples via NIOSH 7400, Revision 3, Issue 2, 8/15/94

Sample	Location	Sample Date	Volume	Fibers	Fields	LOD (fib/cc)	Fibers/ mm ²	Fibers/ cc	Notes
13 030106706-0013	19th Fl-East/Hallway	10/21/2001	2160.00	<5.5	100	0.001	<7.0	<0.001	
14 030106706-0014	18th Fl-East/Hallway	10/21/2001	2160.00	<5.5	100	0.001	<7.0	<0.001	
15 030106706-0015	17th Fl-West/Hallway	10/21/2001	1800.00	<5.5	100	0.001	<7.0	<0.001	
16 030106706-0016	16th Fl-East/Hallway	10/21/2001	1920.00	<5.5	100	0.001	<7.0	<0.001	
17 030106706-0017	15th Fl-East/Hallway	10/21/2001	2160.00	<5.5	100	0.001	<7.0	<0.001	
18 030106706-0018	14th Fl-East/Hallway	10/21/2001	2178.00	<5.5	100	0.001	<7.0	<0.001	
19 030106706-0019	13th Fl-East/Hallway	10/21/2001	1920.00	<5.5	100	0.001	<7.0	<0.001	
20 030106706-0020	12th Fl-East/Hallway	10/21/2001	2160.00	<5.5	100	0.001	<7.0	<0.001	
21 030106706-0021	Blank	10/21/2001	0.00	<5.5	100		<7.0		Field Blank
22 030106706-0022	Blank	10/21/2001	0.00	<5.5	100		<7.0		Field Blank

Dawnette Branson

Analyst

Laboratory Manager
or other approved signatory

Limit of detection is 7 fibers/mm². The laboratory is not responsible for data reported in fibers/cc, which is dependent on volume collected by non-laboratory personnel. This report relates only to the samples reported above. This report may not be reproduced, except in full, without written approval by EMSL.

Analysis performed by EMSL Manhattan (NY State ELAP #11506)