

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 212-290-0058 Email:

EMSL

Attn: CTSI-Consulting & Testing Services, Inc.
622 George Rd.
North Brunswick, NJ 08902

Fax: (732) 729-1803 Phone: 732-729-1800

Project: 111-Broadway-Entire Bldg.


Customer ID: CTSI50
Customer PO:
Received: 11/14/01 10:27 PM
EMSL Order: 030108034
EMSL Project ID:
Analysis Date: 11/15/2001

Fiber Analysis of Air Samples via NIOSH 7400, Revision 3, Issue 2, 8/15/94

Sample	Location	Sample Date	Volume	Fibers	Fields	LOD (fib/cc)	Fibers/ mm ²	Fibers/ cc	Notes
01	21 Fl. S-E side	11/14/2001	2250.00	<5.5	100	0.001	<7.0	<0.001	
030108034-0001									
02	20 Fl. South Office	11/14/2001	2250.00	<5.5	100	0.001	<7.0	<0.001	
030108034-0002									
03	19 Fl. Corridor East	11/14/2001	1924.00	<5.5	100	0.001	<7.0	<0.001	
030108034-0003									
04	18 Fl. South Office	11/14/2001	2190.00	<5.5	100	0.001	<7.0	<0.001	
030108034-0004									
05	17 Fl. North Office	11/14/2001	2175.00	<5.5	100	0.001	<7.0	<0.001	
030108034-0005									
06	16 Fl. South side Office	11/14/2001	2161.00	<5.5	100	0.001	<7.0	<0.001	
030108034-0006									
07	15 Fl. Corridor East	11/14/2001	2175.00	<5.5	100	0.001	<7.0	<0.001	
030108034-0007									
08	14 Fl. Corridor West	11/14/2001	2160.00	<5.5	100	0.001	<7.0	<0.001	
030108034-0008									
09	13 Fl. Corridor West	11/14/2001	2160.00	<5.5	100	0.001	<7.0	<0.001	
030108034-0009									
10	12 Fl. East Office	11/14/2001	2160.00	<5.5	100	0.001	<7.0	<0.001	
030108034-0010									
11	11 Fl. Corridor East	11/14/2001	2130.00	<5.5	100	0.001	<7.0	<0.001	
030108034-0011									
12	10 Fl. South Office	11/14/2001	2130.00	<5.5	100	0.001	<7.0	<0.001	
030108034-0012									

Dawnette Branson

Analyst



Laboratory Manager
or other approved signatory

Limit of detection is 7 fibers/mm². The laboratory is not responsible for data reported in fibers/cc, which is dependent on volume collected by non-laboratory personnel. This report relates only to the samples reported above. This report may not be reproduced, except in full, without written approval by EMSL.

Analysis performed by EMSL Manhattan (NY State ELAP #11506)

PC01-1

1

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 212-290-0058 Email:

EMSL

Attn: CTSI-Consulting & Testing Services, Inc.
622 George Rd.
North Brunswick, NJ 08902

Fax: (732) 729-1803 Phone: 732-729-1800

Project: 111-Broadway-Entire Bldg.


Customer ID: CTSI50
Customer PO:
Received: 11/14/01 10:27 PM
EMSL Order: 030108034
EMSL Project ID:
Analysis Date: 11/15/2001

Fiber Analysis of Air Samples via NIOSH 7400, Revision 3, Issue 2, 8/15/94

Sample	Location	Sample Date	Volume	Fibers	Fields	LOD (fib/cc)	Fibers/ mm ²	Fibers/ cc	Notes
13	9 Fl. N-E Office	11/14/2001	2100.00	<5.5	100	0.001	<7.0	<0.001	
030108034-0013									
14	8 Fl. S-E Office	11/14/2001	2100.00	<5.5	100	0.001	<7.0	<0.001	
030108034-0014									
15	7 Fl. South Office	11/14/2001	2100.00	<5.5	100	0.001	<7.0	<0.001	
030108034-0015									
16	6 Fl. N-East Office	11/14/2001	2100.00	<5.5	100	0.001	<7.0	<0.001	
030108034-0016									
17	1st Fl. Lobby West	11/14/2001	2100.00	7.0	100	0.001	8.92	0.002	
030108034-0017									
18	Trinity level East	11/14/2001	2100.00	<5.5	100	0.001	<7.0	<0.001	
030108034-0018									
19	5 Fl. Corridor West	11/14/2001	2100.00	<5.5	100	0.001	<7.0	<0.001	
030108034-0019									
20	4 Fl. N-E side	11/14/2001	1820.00	<5.5	100	0.001	<7.0	<0.001	
030108034-0020									
21	3 Fl. West side	11/14/2001	2100.00	<5.5	100	0.001	<7.0	<0.001	
030108034-0021									
22	2 Fl. South Office	11/14/2001	1820.00	<5.5	100	0.001	<7.0	<0.001	
030108034-0022									
23	Blank	11/14/2001	0.00	<5.5	100		<7.0		Field Blank
030108034-0023									
24	Blank	11/14/2001	0.00	<5.5	100		<7.0		Field Blank
030108034-0024									

Dawnette Branson

Analyst



Laboratory Manager
or other approved signatory

Limit of detection is 7 fibers/mm². The laboratory is not responsible for data reported in fibers/cc, which is dependent on volume collected by non-laboratory personnel. This report relates only to the samples reported above. This report may not be reproduced, except in full, without written approval by EMSL.

Analysis performed by EMSL Manhattan (NY State ELAP #11506)

PCN-1

2