

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 2122900058 Email:

EMSL

Attn: CTSI-Consulting & Testing Services, Inc.
622 Georges Rd.
North Brunswick, NJ 08902

Fax: (732) 729-1803 Phone: 732-729-1800

Project: 115 Broadway Entire

Customer ID: CTSI50
Customer PO:
Received: 10/19/01 3:30 PM
EMSL Order: 030106586
EMSL Project ID:
Analysis Date: 10/20/2001

Fiber Analysis of Air Samples via NIOSH 7400, Revision 3, Issue 2, 8/15/94

Sample	Location	Sample Date	Volume	Fibers	Fields	LOD (fib/cc)	Fibers/ mm ²	Fibers/ cc	Notes
01 030106586-0001	20 Floor Conference Room	10/19/2001	1470.00	<5.5	100	0.002	<7.0	<0.002	
02 030106586-0002	17 Floor Corridor East	10/19/2001	1950.00	7.0	100	0.001	8.92	0.002	
03 030106586-0003	15 Floor Corridor West	10/19/2001	1638.00	12.0	100	0.002	15.29	0.004	
04 030106586-0004	14 Floor N-W Office Roof	10/19/2001	1200.00	13.0	100	0.002	16.56	0.005	
05 030106586-0005	12 Floor S-W Offices	10/19/2001	1845.00	<5.5	100	0.001	<7.0	<0.001	
06 030106586-0006	Lobby Middle	10/19/2001	2595.00	15.0	100	0.001	19.11	0.003	
07 030106586-0007	3 Floor Corridor Middle	10/19/2001	2210.00	18.0	100	0.001	22.93	0.004	
08 030106586-0008	5 Floor East side Room	10/19/2001	2210.00	7.0	100	0.001	8.92	0.002	
09 030106586-0009	7 Floor Middle North	10/19/2001	2550.00	16.0	100	0.001	20.38	0.003	
10 030106586-0010	9 Floor N-W side Office	10/19/2001	2040.00	16.0	100	0.001	20.38	0.004	
11 030106586-0011	Blank	10/19/2001	0.00	<5.5	100		<7.0		Field Blank
12 030106586-0012	Blank	10/19/2001	0.00	<5.5	100		<7.0		Field Blank

Thomas Michel

Analyst



Laboratory Manager
or other approved signatory

Limit of detection is 7 fibers/mm². The laboratory is not responsible for data reported in fibers/cc, which is dependent on volume collected by non-laboratory personnel. This report relates only to the samples reported above. This report may not be reproduced, except in full, without written approval by EMSL.

Analysis performed by EMSL Manhattan (NY State ELAP #11506)

NYCM

1