



THE CITY OF NEW YORK DEPARTMENT OF ENVIRONMENTAL PROTECTION
JOEL A. MIELE, SR., P.E. Commissioner

ROBERT C. AVALTRONI
Deputy Commissioner

PHONE (718) 595-4418
FAX (718) 595-4422

ASBESTOS ANALYTICAL REPORT

ASBESTOS CONTROL PROGRAM LABORATORY
96-05 HORACE HARDING EXPRESSWAY
CORONA, NEW YORK 11368
(718) 595-6309 FAX# (718) 595-6307

Bureau of
Air, Noise, & Hazardous
Materials

ELAP # 11045

TEST METHODS: 1) 40 CFR Part 763, Subpart F, App. A
2) Polarized Light Microscopy plus Stratified Point-Counting Method
3) EPA/600/R-93/116

Incident #:	WTC92301	Date Collected:	09/23/01
Inspector :		Received:	09/23/01
Premise :	WTC SAND AREAS	Analyzed:	09/23/01
Boro :	Manhattan		
Analyst :	L. ATTELONEY		

Client #:	1	2	3
DEP Sample #:	10923/A203001	10923/A203002	10923/A203003
Laboratory #:	10923/632	10923/633	10923/634
Location Sampled:	SANDY-SILT	SANDY-SILT	SANDY-SILT
Color:	TAN	TAN	TAN
Homogenous:	Yes	Yes	Yes
Asbestos Present:	No	No	No

Results (%)

Cellulose	1	Cellulose	5	Silicates	100
Fibrous glass	5	Fibrous glass	10		
Silicates	94	Silicates	85		

Comments:

Reviewed by:

L. Atteloney
Laboratory Director

This test report may not be reproduced except with the written approval of this laboratory. The test report relates only to the item(s) listed and does not represent a product endorsement by NVLAP or any other U.S. Government agency.

59-17 Junction Boulevard, 11th Floor, Corona, New York 11368-5107

