

VEHICLES DECONTAMINATED STARTING MAY 2002

Vehicle #	Pre-Test or Analysis Date	Results/Vendor	Decontaminated/Washed (Last Day)	Post-Test or Analysis Date	Results/Vendor	Comments
Engine 47 (Yes)	12/13/01	0% Asbestos KAM	07/11/02	07/18/02	< 436 (Str/cm ²) Cole Consulting	Wipe/Bulk Samples
Engine 3 (Yes)	01/17/02	Asbestos-Not Detected PESH	07/12/02	07/18/02	2182 (Str/cm ²) Cole Consulting Wipe Sample	Needs to be Redone
Ladder 12 (Yes)	01/17/02	Asbestos-Not Detected PESH	05/22/02	05/23/02 05/26/02	1.3% Chrysotile Cole Consulting 1.4% Chrysotile Cole Consulting	PESH-Inside Cab (Wipe/Bulk Samples) Cole-Inside Truck Cab and by the ladder on top Cole-Inside Collapse Unit (Wipe/Bulk Samples)
Ladder 12 (Yes)	06/10/02	< 117 Str/cm ² Cole Consulting	06/18/02	06/20/02	< 117 Str/cm ² Cole Consulting	Wipe/Bulk Samples
21 BN (Suburban/SUV) CM 99124	05/03/02	Positive Cole Consulting	05/09/02	05/25/02	Positive Cole Consulting	Chrysotile
Haz-Mat #1 IH 9601 (Yes)	05/13/02	0.1359(S/cc) Chrysotile Cole Consulting	05/16/02	05/25/02	< 0.0076(S/cc) Cole Consulting	Air Samples
Engine 54	05/30/02	Asbestos-None	06/24/02	07/02/02	822 Str/cm ²	Pre-Test (Air

Prepared by: Mohammed.

		Detected Cole Consulting			Chrysotile Cole Consulting	Sampling) Post-Test (Wipe/Bulk Samples)
GM 9739 (Suburban)			05/30/02			
Engine 240			06/25/02	07/02/02	< 117 Str/cm ² Cole Consulting	Wipe/Bulk Samples
Ladder 21			07/12/02	07/22/02	Asbestos not detected Cole Consulting	Wipe/Bulk Samples
Ladder 24			07/17/02	07/22/02	Asbestos not detected Cole Consulting	Wipe/Bulk Samples
Ladder 7	01/15/02 02/13/02	Asbestos-Not Detected 0.0345(S/cc) Chrysotile	07/17/02 02/16/02**	07/22/02	Asbestos not detected Cole Consulting	Wipe/Bulk Samples
Ladder 2				08/07/02	Asbestos not detected Cole Consulting	Wipe/Bulk Samples
Ladder 25				08/07/02	Asbestos not detected Cole Consulting	Wipe/Bulk Samples
Ladder 35			08/01/02	08/07/02	Asbestos not detected Cole Consulting	Wipe/Bulk Samples
Engine 74				08/07/02	Asbestos not detected	Wipe/Bulk Samples

					Cole Consulting	
Engine 5				08/07/02	Asbestos not detected Cole Consulting	Wipe/Bulk Samples
GM 9804 Suburban				08/07/02	Asbestos not detected Cole Consulting	Wipe/Bulk Samples

Note:- (Yes) indicates that Air Samples were taken from the Building/Station House.

** Previously decontaminated on that date.