

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 2122900058 Email:

EMSL

Attn: F. Salemi
 CTSI-Consulting & Testing Services, Inc.
 622 Georges Rd.
 North Brunswick, NJ 08902

Fax: (732) 729-1803 Phone: 732-729-1800

Project: NYU 200 WATER STREET

Customer ID: CTSI50

Customer PO:

Received: 09/15/01 10:00 PM

EMSL Order: 030104335

EMSL Project ID:

Analysis Date: 9/16/01

Asbestos Analysis via Polarized Light Microscopy, Qualitative

Sample	Location	Appearance	Treatment	Result	Notes
200W-1805-001 #30104335-0001	Window Sill, Floor			None Detected	
200W-1804-001 #30104335-0002	Window Sill, Floor Bedroom			None Detected	
200W-1803-001 #30104335-0003	Window Sill, Floor			None Detected	
200W-1806-001 #30104335-0004	Window Sill			None Detected	
200W-1605-001 #30104335-0005	Window Sill			None Detected	
200W-1604-001 #30104335-0006	Window Sill Bedroom			None Detected	
200W-1602-001 #30104335-0007	Window Sill			None Detected	
200W-1610-001 #30104335-0008	Window Sill			Not Submitted	
200W-1615-001 #30104335-0009	Window Sill Back Bedroom			None Detected	
200W-1614-001 #30104335-0010	Window Sills			None Detected	

Dan Osborne

Analyst

Laboratory Manager
or other approved signatory

EMSL recommends that soil samples reported as "NO" be tested by the EPA Screening Method/Qualitative. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government.

LABORATORY #101048-S and NY STATE ELAP #11506

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 212-290-0060 Email:

EMSL

Attn: F. Salami
 CTSI Consulting & Testing Services, Inc.
 622 Georges Rd.
 North Brunswick, NJ 08902
 Fax: (732) 729-1803 Phone: 732-729-1800
 Project: NYU 200 WATER STREET

Customer ID: CTS150
 Customer PO:
 Received: 09/15/01 10:00 PM
 EMSL Order: 030104335
 EMSL Project ID:
 Analysis Date: 9/16/01

Asbestos Analysis via Polarized Light Microscopy, Qualitative

Sample	Location	Appearance	Treatment	Result	Notes
200W-408-001 030104335-0011	Window Sill			None Detected	
200W-407-001 030104335-0012	Window Sill			None Detected	
200W-406-001 030104335-0013	Window Sill			None Detected	
200W-405-001 030104335-0014	Window Sill			None Detected	
200W-403-001 0104335-0015	Window Sill Bedroom			None Detected	
200W-404-001 030104335-0016	Window Sill Floor (4th Floor)			None Detected	
200W-401-001 030104335-0017	Window Sill			None Detected	
200W-429-001 030104335-0018	Window Sill			None Detected	
200W-430-001 030104335-0019	Window Sill			None Detected	
200W-427-001 030104335-0020	Window Sill			None Detected	



Dan Osborne

Analyst

Laboratory Manager
 or other approved signatory

EMSL recommends that soil samples reported as "ND" be tested by the EPA Screening Method/Qualitative. The above report relates only to the items tested. This report may not be reproduced except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government.

ACCREDITATIONS: NVLAP #101048-9 and NY STATE ELAP #11505

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-298-0051 Fax: 212-298-0058 Email:

EMSL

Attn: F. Salami
 CTSI-Consulting & Testing Services, Inc.
 522 Georges Rd.
 North Brunswick, NJ 08802

Fax: (732) 729-1803

Phone: 732-729-1800

Project: NYU 200 WATER STREET

Customer ID: CTSI50

Customer PO:

Received: 09/15/01 10:00 PM

EMSL Order: 030104335

EMSL Project ID:

Analysis Date: 9/16/01

Asbestos Analysis via Polarized Light Microscopy, Qualitative

Sample	Location	Appearance	Treatment	Result	Notes
200W-421-001 030104335-0021	Window Sill			None Detected	
200W-424-001 030104335-0022	Window Sill			None Detected	
200W-2605-001 030104335-0023	Window Sill			None Detected	
200W-2604-001 030104335-0024	Window Sill			None Detected	
200W-2603-001 030104335-0025	Window Sill/Floor			None Detected	
200W-2602-001 030104335-0026	Window Sill			None Detected	
200W-2601-001 030104335-0027	Window Sill			None Detected	
200W-2616-001 030104335-0028	Window Sill			None Detected	
200W-2615-001 030104335-0029	Window Sill			None Detected	
200W-2406-001 030104335-0030	Window Sill			None Detected	

Dan Osborne

Analyst

Laboratory Manager
or other approved signatory

EMSL recommends that soil samples reported as "ND" be tested by the EPA Screening Method Qualitative. The above report relates only to the items tested. This report may not be reproduced except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government.

APCR 87-1003 NVLAP #101048-9 and NY STATE ELAP #11505

New York Lab

307 West 35th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 212-290-0058 Email:

EMSL

Attn: F. Salemi
CTSI-Consulting & Testing Services, Inc.
822 Georges Rd.
North Brunswick, NJ 08902

Fax: (732) 729-1803

Phone: 732-729-1800

Project: NYU 200 WATER STREET

Customer ID: CTSI50

Customer PO:

Received: 09/15/01 10:00 PM

EMSL Order: 030104335

EMSL Project ID:

Analysis Date: 9/16/01

Asbestos Analysis via Polarized Light Microscopy, Qualitative

Sample	Location	Appearance	Treatment	Result	Notes
200W-2415-001 030104335-0031	Bedroom Window Sill/Floor			None Detected	
200W-2416-001 030104335-0032	Window Sill/Floor			None Detected	
200W-2206-001 030104335-0033	Window Sill/Floor/Desk			None Detected	
200W-2205-001 030104335-0034	Window Sill/Floor/Desk			None Detected	
200W-2204-001 030104335-0035	Window Sill/Floor/Desk edroom			None Detected	
200W-2203-001 030104335-0036	Window Sill (Bedroom)			None Detected	
200W-2214-001 030104335-0037	Window Sill Backside			None Detected	
200W-2215-001 030104335-0038	Window Sill Backside edroom			None Detected	
200W-2006-001 030104335-0039	Window Sill Bedroom			None Detected	
200W-2004-001 030104335-0040	Window Sill/Floor Bedroom			None Detected	

Dan Osborne

Analyst



Laboratory Manager
or other approved signatory

EMSL recommends that soil samples reported as "ND" be tested by the EPA Screening Method/Qualitative. The above report relates only to the items tested. This report may not be reproduced except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government.

NOT FOR USE IN NVLAP #101048-9 and NY STATE ELAP #11506

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 212-290-0058 Email:

EMSL

Attn: F. Salami
 CTSI-Consulting & Testing Services, Inc.
 922 Georges Rd.
 North Brunswick, NJ 08902
 Fax: (732) 729-1803 Phone: 732-729-1800
 Project: NYU 200 WATER STREET

Customer ID: CTSI50
 Customer PO:
 Received: 09/15/01 10:00 PM
 EMSL Order: 030104335
 EMSL Project ID:
 Analysis Date: 9/16/01

Asbestos Analysis via Polarized Light Microscopy, Qualitative

Sample	Location	Appearance	Treatment	Result	Notes
200W-2005-001 030104335-0041	Window Sill/Floor			None Detected	
200W-2002-001 030104335-0042	Window Sill/Floor			None Detected	
200W-2001-001 030104335-0043	Window Sill/Floor			None Detected	
200W-1806-001 030104335-0044	Window Sill/Floor			None Detected	
200W-3001-001 030104335-0045	Window Sill			None Detected	
200W-3009-001 030104335-0046	Window Sill			None Detected	
200W-3016-001 030104335-0047	Window Sill			None Detected	
200W-2806-001 030104335-0048	Window Sill			None Detected	
200W-2805-001 030104335-0049	Window Sill			None Detected	
200W-2804-001 030104335-0050	Window Sill Bedroom			None Detected	

Dan Osborne

Analyst



Laboratory Manager
 or other approved signatory

EMSL recommends that soil samples reported as "ND" be tested by the EPA Screening Method Qualitative. The above report relates only to the items tested. This report may not be reproduced except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government.

NY STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
 NY STATE ELAP #11508

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 212-290-0058 Email:



Attn: F. Salami
 CTSI-Consulting & Testing Services, Inc.
 822 Georges Rd.
 North Brunswick, NJ 08902
 Fax: (732) 729-1803 Phone: 732-729-1800
 Project: NYU 200 WATER STREET

Customer ID: CTS150
 Customer PO:
 Received: 09/15/01 10:00 PM
 EMSL Order: 030104335
 EMSL Project ID:
 Analysis Date: 9/16/01

Asbestos Analysis via Polarized Light Microscopy, Qualitative

Sample	Location	Appearance	Treatment	Result	Notes
200W-PH13-001 030104335-0061	Window Sill			None Detected	
200W-3006-001 030104335-0062	Window Sill			None Detected	
200W-3003-001 030104335-0063	Window Sill from WTC (Bedroom)			Not Submitted	
200W-3005-001 030104335-0064	Window Sill from WTC (Bedroom)			None Detected	
200W-425-001 030104335-0065	Window Sill			None Detected	

Dan Osborne

Analyst

Laboratory Manager
 or other approved signatory

EMSL recommends that soil samples reported as "ND" be tested by the EPA Screening Method/Qualitative. The above report relates only to the items tested. This report may not be reproduced except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government.

NYLAP #101045-B and NY STATE ELAP #11508

New York Lab

307 West 28th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 212-290-0058 Email:

EMSL

Attn: F. Salami
 CTSI-Consulting & Testing Services, Inc.
 822 Georges Rd.
 North Brunswick, NJ 08902
 Fax: (732) 729-1803 Phone: 732-729-1800
 Project: NYU 200 WATER STREET

Customer ID: CTSI50
 Customer PO:
 Received: 09/15/01 10:00 PM
 EMSL Order: 030104335
 EMSL Project ID:
 Analysis Date: 9/16/01

Asbestos Analysis via Polarized Light Microscopy, Qualitative

Sample	Location	Appearance	Treatment	Result	Notes
200W-2803-001 030104335-0051	Window Sill Bedroom			None Detected	
200W-2802-001 030104335-0052	Window Sill			None Detected	
200W-2818-001 030104335-0053	Window Sill			None Detected	
200W-2818-001 030104335-0054	Window Sill Bedroom			None Detected	
200W-2806-001 030104335-0055	Window from WTC			None Detected	
200W-PH01-001 030104335-0056	Window Sill Facing WTC			None Detected	
200W-PH04-001 030104335-0057	Window Sill Facing WTC			None Detected	
200W-PH06-001 030104335-0058	Window Sill Facing WTC			None Detected	
200W-PH18-001 030104335-0059	Window Sill Facing WTC			Not Submitted	
200W-PH17-001 030104335-0060	Window Sill Facing WTC			Not Submitted	

Dan Osborne

Analyst



Laboratory Manager
 or other approved signatory

EMSL recommends that soil samples reported as "ND" be tested by the EPA Screening Method/Qualitative. The above report relates only to the items tested. This report may not be reproduced except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government.

CR-101-0104335-0058 and NY STATE ELAP #11508