

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 212-290-0058 Email:

EMSL

Attn: Boris Shamaiov
 CTSI-Consulting & Testing Services, Inc.
 622 Georges Rd.
 North Brunswick, NJ 08902

Fax: (732) 729-1803 Phone: 732-729-1800

Project: NYU / 200 Water St.

Customer ID: CTSI50
 Customer PO:
 Received: 09/16/01 7:41 AM
 EMSL Order: 030104298
 EMSL Project ID:
 Analysis Date: 9/15/01

Asbestos Analysis via Polarized Light Microscopy, Qualitative

Sample	Location	Appearance	Treatment	Result	Notes
200-2703-38 030104298-0001	Apt 2703 - Living Room			None Detected	
200-2703-39 030104298-0002	Apt 2703 - Mid Bedroom			None Detected	
200-2716-45 030104298-0003	Apt 2716 - Bedroom			None Detected	
200-2717-47 030104298-0004	Apt 2717 - Bedroom			None Detected	
200-2718-49 030104298-0005	Apt 2718 - Bedroom			None Detected	
200-2503-54 030104298-0006	Apt 2503 - Mid Bedroom			None Detected	
200-2503-55 030104298-0007	Apt 2503 - Left Bedroom			None Detected	
200-2515-58 030104298-0008	Apt 2515 - Left Bedroom			None Detected	
200-2516-59 030104298-0009	Apt 2516 - Living Room			None Detected	
200-2517-61 030104298-0010	Apt 2517 - Living Room			None Detected	

Williams John

Analyst

Laboratory Manager
or other approved signatory

EMSL recommends that soil samples reported as "ND" be tested by the EPA Screening Method/Qualitative. The above report relates only to the items tested. This report may not be reproduced, in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NYLAP nor any agency of the United States Government.

NYLAP #101048-9 and NY STATE ELAP #11505

09/16/2001 08:15 212-290-0058

EMSL MANHATTAN

PAGE 02/06

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 212-290-0058 Email:

EMSL

Attn: Boris Shamalov
CTSI-Consulting & Testing Services, Inc.
622 Georges Rd
North Brunswick, NJ 08902
Fax: (732) 729-1803 Phone: 732-729-1800
Project: NYU / 200 Water St.

Customer ID: CTSI50
Customer PO:
Received: 09/18/01 7:41 AM
EMSL Order: 030104298
EMSL Project ID:
Analysis Date: 9/15/01

Asbestos Analysis via Polarized Light Microscopy, Qualitative

Sample	Location	Appearance	Treatment	Result	Notes
200-2517-62 030104298-0011	Apt 2517 - Bedroom			None Detected	
200-2518-63 030104298-0012	Apt 2518 - Bedroom			None Detected	
200-2518-64 030104298-0013	Apt 2518 - Living Room			None Detected	

Williams John

Analyst



Laboratory Manager
or other approved signatory

EMSL recommends that soil samples reported as "ND" be tested by the EPA Screening Method/Qualitative. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government.

LABORATORY CONDITIONS INVOLVED: 101048-9 and NY STATE ELAP #11508