

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 212-290-0058 Email:

EMSL

Attn: CTSI-Consulting & Testing Services, Inc.
622 Georges Rd.
North Brunswick, NJ 08902
Fax: (732) 729-1803 Phone: 732-729-1800
Project: NYU / 200 Water Street

Customer ID: CTSI50
Customer PO:
Received: 09/15/01 10:00 PM
EMSL Order: 030104311
EMSL Project ID:
Analysis Date: 9/16/01

Asbestos Analysis via Polarized Light Microscopy, Qualitative

Sample	Location	Appearance	Treatment	Result	Notes
200 W 2310 -001 030104311-0001	Inside Room 2310 Window Ledae			None Detected	
200 W 2304 -002 030104311-0002	Inside Room 2304 Window Ledae			None Detected	
200 W 2302 -004 030104311-0003	Inside Room 2302 Window Ledae			None Detected	
200 W 2301 -005 030104311-0004	Inside Room 2301 Window Ledae			None Detected	
200 W 2105 -011 030104311-0005	Inside Room 2105 Window Ledae			None Detected	
200 W 2104 -012 030104311-0006	Inside Room 2104 Window Ledae			None Detected	
200 W 2103 -013 030104311-0007	Inside Room 2103 Window Ledae & Radiator			None Detected	
200 W 2102 -014 030104311-0008	Inside Room 2102 Window Ledae & Sill			None Detected	

Alex Chechelovski

Analyst

Laboratory Manager
or other approved signatory

EMSL recommends that soil samples reported as "ND" be tested by the EPA Screening Method/Qualitative. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government.

EMSL is an ISO 9001:2000 NVLAP #101048-9 and NY STATE ELAP #11505

New York Lab

307 West 38th Street, New York, NY 10018

Phone: 212-290-0051 Fax: 212-290-0058 Email:

EMSLAttn: CTSI-Consulting & Testing Services, Inc.
622 Georges Rd.
North Brunswick, NJ 08902

Fax: (732) 729-1803

Phone: 732-729-1800

Project: NYU / 200 Water Street

Customer ID: CTSI50

Customer PO:

Received: 09/15/01 10:00 PM

EMSL Order: 030104305

EMSL Project ID:

Analysis Date: 9/16/01

Asbestos Analysis via Polarized Light Microscopy, Qualitative

Sample	Location	Appearance	Treatment	Result	Notes
200 1702-03 030104305-0001	Apt 1702 Bedroom Window top			None Detected	
200 1703-04 030104305-0002	Apt 1703 Living Room Window top			None Detected	
200 1717-10 030104305-0003	Apt 1717 Living Room Window top			None Detected	
200 1717-11 030104305-0004	Apt 1717 Bedroom Window top			None Detected	
200 1718-12 030104305-0005	Apt 1718 Living Room Window top			None Detected	
200 1718-13 030104305-0006	Apt 1718 Living Room Window top			None Detected	
200 1902-16 030104305-0007	Apt 1902 Bedroom Window top			None Detected	
200 1904-20 030104305-0008	Apt 1904 Bedroom Window top			None Detected	
200 1905-21 030104305-0009	Apt 1905 Studio Window top			None Detected	
200 1918-23 030104305-0010	Apt 1918 Bedroom Window top			None Detected	

Jim Hall

Analyst

Laboratory Manager
or other approved signatory

EMSL recommends that soil samples reported as "ND" be tested by the EPA Screening Method/Qualitative. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government.

COMPLIANCE: NYS #101048-9 and NY STATE ELAP #11506