

ATC Associates

104 East 25 Street, New York, NY 10010

Phone: (212) 353-8280 Fax: (212) 353-8306



Attn: John Anuforo

Cole Consulting Corp.

2269 Saw Mill River Road

Elmsford NY 10523

Fax: (914) 345-0045

Phone: (914) 345-6000

Received: 5/31/02

8:00:00 AM

ATC Group #: 7916

Analysis Date: 5/31/02


Project: BAT #35

760 Broadway, Brooklyn

**Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed
by EPA 40 CFR Part 763 Final Rule (AHERA)**

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structures		Analytical Sensitivity (S/cc)	Asbestos Concentration		Notes
					0.5µ-5	5µ		(S/mm²)	(S/cc)	
1 7916 -1 Vehicle # 256	450.00	0.1124	0	None Detected	0	0	0.0076	<8.90	<0.0076	Fiber Glass - None Detected Silicon - None Detected
2 7916 -2 Vehicle # 264	450.00	0.1124	0	None Detected	0	0	0.0076	<8.90	<0.0076	Fiber Glass - None Detected Silicon - None Detected
3 7916 -3 Vehicle # 478	450.00	0.1124	0	None Detected	0	0	0.0076	<8.90	<0.0076	Fiber Glass - None Detected Silicon - None Detected

ROMAN PEYSAKHOV

Analyzed by: 

MICHAEL A. GORYCKI, Ph.D.

Approved by: 

Disclaimer: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by ATC Associates Inc. This report may not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. This reports relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysis' accuracy and precision) is available upon request.

Accredited for NVLAP PLM/TEM #101187-0, NY State ELAP #10879