New York Lab
307 West 36th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900458 Email:

EMSL

Attn: Industrial Hygiene Consultants
251 Park Street
Upper Montclair, NJ 07043
Fax: (973) 509-1954 Phone: 212-267-6841
Project: 1015011 / / 333 Rector Place, Apt

Customer ID: IHC50
Customer PO:
Received: 10/17/01 1:30 PM
EMSL Order: 030106408
EMSL Project ID:
Analysis Date: 10/17/01

Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

				Non-Asbestos			Asbestos
Sample	Location	Appearance	Treatment	% Fibrous		% Non-Fibrous	% Type
A-1 030106408-0001	Apt / Settled dust on desk	Tan Fibrous Heterogeneous	Teased Dissolved	30% Glass 25% Cellulose		43% Non-fibrous (other)	2% Chrysotile
A-2 030106408-0002	Apt / Settled dust on window panel	Tan Fibrous Heterogeneous	Teased Dissolved	35% Glass 25% Cellulose		40% Non-fibrous (other)	<1% Chrysotile
A-3 030106408-0003	Apt / Fibrous bundle in drawer	Tan Fibrous Homogeneous	Teased Dissolved	98% Cellulose		2% Non-fibrous (other)	None Detected

PRIVILEGED
AND
CONFIDENTIAL

Analyst(s)
Williams John (3)

Laboratory Manager
or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government.
Analysis performed by EMSL Manhattan (NVLAP #101048-0), NY ELAP 11506