NYC 9/11 Public Portal Document

ASBESTOS ANALYTICAL REPORT

DEP

DIVISION OF EMERGENCY RESPONSE AND TECHNICAL ASSESSMENT
ASBESTOS LABORATORY
96-05 HORACE HARDING EXPRESSWAY
CORONA, NEW YORK 11368
(718) 595-6309 FAX# (718) 595-6307

ELAP # 11045

TEST METHODS : 1) 40 CFR Part 763, Subpart F, App. A
2) Polarized Light Microscopy plus Stratified Point-Counting Method
3) EPA/600/R-93/116

Incident #: TRU0273MN03
Inspector : R. Rammohan
Premise : 114 Liberty Street
Boro : Manhattan
Analyst : G. Roman

Date Collected: 03/27/03
Received: 03/27/03
Analyzed: 03/27/03

Client # :

DEP Sample # : 30327/A078005A

Laboratory # : 30327/377A

Location Sampled: On drop ceiling

Color : Light brown

Homogenous: No
Asbestos Present: No

Results - (%)		
	Matrix	88
	Fibrous	2
	Quartz	10

Comments: This report has results for the brown cementitious material.

Reviewed by: _____
Laboratory Director

This test report may not be reproduced except with the written approval of this laboratory. The test report relates only to the item(s) listed and does not represent a product endorsement by NVLAP or any other U.S. Government agency.

CITY_DEP_WORBY_CANNATA_SUBP_000019749

NYC-WTC_000209387