

ASBESTOS BULK SAMPLE RESULTS UNIT VENTILATORS

SAMPLE LOCATION	ANALYTICAL RESULTS
Unit Ventilator – Room 911	No Asbestos Detected
Unit Ventilator – Room 938	No Asbestos Detected
Unit Ventilator – Room 333	No Asbestos Detected
Unit Ventilator – Room 251	No Asbestos Detected
Unit Ventilator – Room 1006	No Asbestos Detected
Unit Ventilator – Room 826	No Asbestos Detected
Unit Ventilator – Room 731	No Asbestos Detected
Unit Ventilator – Room 646	No Asbestos Detected
Unit Ventilator – Room 451	No Asbestos Detected
Unit Ventilator – Room 525	No Asbestos Detected