

ATC Associates

104 East 25 Street, New York, NY 10010

Phone: (212) 353-8280

Fax: (212) 353-8306



Attn: Mr. Bernard Orlan
 N.Y.C. Board of Education
 28-11 Queens Plaza North
 Long Island City, NY 11101

Received: 1/27/02 11:50:00 PM

ATC Group #: 6481

Analysis Date: 1/28/02

Fax: (212) 475-4122 Phone: (212) 477-8941

Project: NYC-BOE Leadership HS
 90 Trinity Place, New York, NY

Asbestos Analysis via Transmission Electron Microscopy ASTM Method D5755-95

<i>Sample</i>	<i>Area Sampled (cm²)</i>	<i>Asbestos Type(s)</i>	<i>Asbestos Structures</i>	<i>Sensitivity (str/cm²)</i>	<i>Concentration (str/cm²)</i>	<i>Comments</i>
90-01 6481 -1	100	None Detected	0	873	<873	
90-02 6481 -2	100	None Detected	0	873	<873	
90-03 6481 -3	100	None Detected	0	873	<873	
90-04 6481 -4	100	None Detected	0	873	<873	
90-05 6481 -5	100	None Detected	0	873	<873	
90-06 6481 -6	100	None Detected	0	873	<873	
90-07 6481 -7	100	None Detected	0	873	<873	
90-08 6481 -8	100	None Detected	0	873	<873	

MARK PEYSAKHOV

Analyzed by:

MICHAEL A. GORYCKI, Ph.D.

Approved by:

The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by ATC Associates, Inc.

Attn: Mr. Bernard Orlan
 N.Y.C. Board of Education
 28-11 Queens Plaza North
 Long Island City, NY 11101

Received: 1/27/02 11:50:00 PM

ATC Group #: 6481

Analysis Date: 1/28/02

Fax: (212) 475-4122 Phone: (212) 477-8941

Project: NYC-BOE Leadership HS
 90 Trinity Place, New York, NY

Asbestos Analysis via Transmission Electron Microscopy ASTM Method D5755-95

Sample	Area Sampled (cm ²)	Asbestos Type(s)	Asbestos Structures	Sensitivity (str/cm ²)	Concentration (str/cm ²)	Comments
90-09 6481 -9	100	None Detected	0	873	<873	
90-010 6481 -10	100	None Detected	0	873	<873	
90-011 6481 -11	100	None Detected	0	873	<873	
90-012 6481 -12	100	None Detected	0	873	<873	
90-013 6481 -13	100	None Detected	0	873	<873	
90-014 6481 -14	100	None Detected	0	873	<873	

MARK PEYSAKHOV

Analyzed by:



MICHAEL A. GORYCKI, Ph.D.

Approved by:



The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by ATC Associates, Inc.