

# **ATC ASSOCIATES, INC.** **INDOOR AIR QUALITY FIELD REPORT**

Page 4 of 10

Time: 7:20 AM LOCATION: 100 Trinity Place /HS for Economics And Finances DATE: 5-17-02 PROJECT NO: 15-19125-0291

| Location                        | Oxygen (%) | Temperature (°F)                    | Relative Humidity (%) | Carbon Dioxide (ppm)       | Carbon Monoxide (ppm) | Respirable Particulate (µg/m³) | TVOC (ppm) |
|---------------------------------|------------|-------------------------------------|-----------------------|----------------------------|-----------------------|--------------------------------|------------|
| IN STAIRWELL B 10TH FLOOR       | ○          | 74.2                                | 44.6                  | 412                        | 1                     | 19                             | ○          |
| IN STAIRWELL B 9TH FLOOR        | ○          | 74.6                                | 44.9                  | 461                        | 1                     | 18                             | ○          |
| IN STAIRWELL B 2ND FLOOR        | ○          | 73.7                                | 43.9                  | 455                        | 1                     | 11                             | ○          |
|                                 |            |                                     |                       |                            |                       |                                |            |
|                                 |            |                                     |                       |                            |                       |                                |            |
|                                 |            |                                     |                       |                            |                       |                                |            |
|                                 |            |                                     |                       |                            |                       |                                |            |
|                                 |            |                                     |                       |                            |                       |                                |            |
|                                 |            |                                     |                       |                            |                       |                                |            |
|                                 |            |                                     |                       |                            |                       |                                |            |
|                                 |            |                                     |                       |                            |                       |                                |            |
| Guideline levels<br>ASHRAE/AIHA |            | 68 – 75°F/winter<br>73-79 °F/summer | 30-60%                | Outdoor level<br>+ 700 ppm | 9 ppm                 | 65 ug/m³                       | 1 ppm      |

Comments: NA

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: [Signature] Date: 5-17-02

CITY\_21MC100\_002882242

**ATC ASSOCIATES, INC.**  
**INDOOR AIR QUALITY FIELD REPORT**

Page 1 of 10

Time: 8:00 AM LOCATION: 100 Trinity Place /HS for Economics And Finances DATE: 5-17-02 PROJECT NO: 15-19125-0291

| Location                        | Occupant | Temperature (°F)                    | Relative Humidity (%) | Carbon Dioxide (ppm)       | Carbon Monoxide (ppm) | Respirable Particulate (ug/m <sup>3</sup> ) | TVOCs (ppm) |
|---------------------------------|----------|-------------------------------------|-----------------------|----------------------------|-----------------------|---------------------------------------------|-------------|
| Out Doors EXIT MAIN ENTRY       | 0        | 75.6                                | 46.7                  | 467                        | 1                     | 60                                          | 0           |
| Out Doors EXIT MAIN ENTRY SOUTH | 0        | 75.9                                | 46.7                  | 492                        | 1                     | 60                                          | 0           |
| Out Doors EXIT MAIN ENTRY NORTH | 0        | 75.7                                | 46.7                  | 454                        | 1                     | 60                                          | 0           |
| 10TH FLOOR HALLWAY              | 0        | 78.5                                | 44.6                  | 491                        | 1                     | 15                                          | 0           |
| LIBRARY                         | 2        | 78.6                                | 44.1                  | 561                        | 1                     | 14                                          | 0           |
| R-1006                          | 0        | 78.3                                | 44.5                  | 429                        | 1                     | 16                                          | 0           |
| STAIRCASE A 9TH FLOOR           | 0        | 77.3                                | 44.9                  | 501                        | 1                     | 15                                          | 0           |
| 9TH FLOOR HALLWAY               | 0        | 76.4                                | 41.9                  | 570                        | 1                     | 16                                          | 0           |
| R-915                           | 0        | 76.3                                | 41.8                  | 496                        | 1                     | 17                                          | 0           |
| Rm- 933                         | 0        | 76.1                                | 42.6                  | 477                        | 1                     | 18                                          | 0           |
| Guideline levels<br>ASHRAE/AIHA |          | 68 - 75°F/winter<br>73-79 °F/summer | 30-60%                | Outdoor level<br>+ 700 ppm | 9 ppm                 | 65 ug/m <sup>3</sup>                        | 1 ppm       |

Comments:

NA

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature:

*[Signature]*

Date:

5-17-02

**ATC ASSOCIATES, INC.**  
**INDOOR AIR QUALITY FIELD REPORT**

Page 2 of 10

Time: 8:40 AM LOCATION: 100 Trinity Place /HS for Economics And Finances DATE: 5-17-02 PROJECT NO: 15-19125-0291

| Location                        | Occupants | Temperature (°F)                    | Relative Humidity (%) | Carbon Dioxide (ppm)       | Carbon Monoxide (ppm) | Respirable Particulate (ug/m <sup>3</sup> ) | TVOCs (ppm) |
|---------------------------------|-----------|-------------------------------------|-----------------------|----------------------------|-----------------------|---------------------------------------------|-------------|
| Room 914                        | 6         | 80.7                                | 42.6                  | 641                        | 1                     | 16                                          | 0           |
| STAIRCASE B<br>8TH FLOOR        | 0         | 80.6                                | 42.1                  | 541                        | 1                     | 19                                          | 0           |
| 8TH FLOOR<br>HALLWAY            | 0         | 79.2                                | 41.6                  | 501                        | 1                     | 16                                          | 0           |
| Kitchen                         | 3         | 78.9                                | 41.0                  | 601                        | 1                     | 11                                          | 0           |
| CAFETERIA                       | 2         | 79.9                                | 41.1                  | 595                        | 1                     | 8                                           | 0           |
| STAIRCASE A<br>7TH FLOOR        | 0         | 76.9                                | 42.3                  | 499                        | 1                     | 10                                          | 0           |
| 7TH FLOOR<br>HALLWAY            | 0         | 80.0                                | 41.3                  | 513                        | 1                     | 11                                          | 0           |
| Room 706                        | 3         | 80.8                                | 41.3                  | 660                        | 1                     | 16                                          | 0           |
| Room 704                        | 22        | 80.9                                | 39.2                  | 1091                       | 1                     | 15                                          | 0           |
| Room 703                        | 15        | 80.5                                | 38.9                  | 1151                       | 1                     | 16                                          | 0           |
| Guideline levels<br>ASHRAE/AIHA |           | 68 - 75°F/winter<br>73-79 °F/summer | 30-60%                | Outdoor level<br>+ 700 ppm | 9 ppm                 | 65 ug/m <sup>3</sup>                        | 1 ppm       |

Comments: NA

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: [Signature] Date: 5-17-02

# ATC ASSOCIATES, INC. INDOOR AIR QUALITY FIELD REPORT

Page 3 of 10

Time: 9:00 AM LOCATION: 100 Trinity Place /HS for Economics And Finances DATE: 5-17-02 PROJECT NO: 15-19125-0291

| Location                        | Occupants | Temperature (F)                     | Relative Humidity (%) | Carbon Dioxide (ppm)       | Carbon Monoxide (ppm) | Respirable Particulates (ug/m <sup>3</sup> ) | TVOCs (ppm) |
|---------------------------------|-----------|-------------------------------------|-----------------------|----------------------------|-----------------------|----------------------------------------------|-------------|
| STAIRCASE B<br>6TH FLOOR        | 0         | 77.5                                | 38.7                  | 549                        | 1                     | 16                                           | 0           |
| 6TH FLOOR<br>HALLWAY            | 4         | 80.9                                | 38.2                  | 861                        | 1                     | 10                                           | 0           |
| Room 604                        | 23        | 81.6                                | 39.4                  | 1044                       | 1                     | 16                                           | 0           |
| Room 605                        | 19        | 81.3                                | 39.3                  | 1018                       | 1                     | 10                                           | 0           |
| Room 606                        | 21        | 81.0                                | 38.2                  | 1054                       | 1                     | 10                                           | 0           |
| Room 608                        | 7         | 81.2                                | 38.9                  | 963                        | 1                     | 6                                            | 0           |
| STAIRCASE A<br>5TH FLOOR        | 0         | 81.5                                | 38.6                  | 669                        | 1                     | 10                                           | 0           |
| 5TH FLOOR<br>HALLWAY            | 1         | 79.9                                | 38.4                  | 549                        | 1                     | 12                                           | 0           |
| Room 509                        | 23        | 80.6                                | 40.1                  | 1031                       | 1                     | 13                                           | 0           |
| Room 507                        | 20        | 80.7                                | 40.0                  | 1138                       | 1                     | 10                                           | 0           |
| Guideline levels<br>ASHRAE/AIHA |           | 68 - 75°F/winter<br>73-79 °F/summer | 30-60%                | Outdoor level<br>+ 700 ppm | 9 ppm                 | 65 ug/m <sup>3</sup>                         | 1 ppm       |

Comments: NA

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: [Signature] Date: 5-17-02

CITY\_21MC100\_002882245

# ATC ASSOCIATES, INC. INDOOR AIR QUALITY FIELD REPORT

Page 4 of 10

Time: 9:20 AM LOCATION: 100 Trinity Place /HS for Economics And Finances DATE: 5-17-02 PROJECT NO: 15-19125-0291

| Location                        | Occupants | Temperature (°F)                    | Relative Humidity (%) | Carbon Dioxide (ppm)       | Carbon Monoxide (ppm) | Respirable Particulate (ug/m <sup>3</sup> ) | TVOCs (ppm) |
|---------------------------------|-----------|-------------------------------------|-----------------------|----------------------------|-----------------------|---------------------------------------------|-------------|
| Rm 504                          | 0         | 80.6                                | 38.0                  | 610                        | 1                     | 16                                          | 0           |
| STAIRCASE B<br>4TH FLOOR        | 0         | 80.1                                | 38.7                  | 865                        | 1                     | 20                                          | 0           |
| 4TH FLOOR<br>HALLWAY            | 0         | 81.3                                | 38.4                  | 641                        | 1                     | 12                                          | 0           |
| Rm 405                          | 30        | 81.5                                | 40.4                  | 1003                       | 1                     | 10                                          | 0           |
| Rm 406                          | 32        | 81.5                                | 40.0                  | 1124                       | 1                     | 17                                          | 0           |
| Rm 410                          | 30        | 81.2                                | 40.1                  | 1189                       | 1                     | 10                                          | 0           |
| Rm 409                          | 22        | 81.5                                | 39.3                  | 1020                       | 1                     | 10                                          | 0           |
| STAIRCASE "A"<br>3RD FLOOR      | 0         | 78.8                                | 39.4                  | 530                        | 1                     | 14                                          | 0           |
| Room 307                        | 28        | 81.6                                | 44.1                  | 1057                       | 1                     | 19                                          | 0           |
| Room 404                        | 6         | 81.6                                | 40.1                  | 810                        | 1                     | 11                                          | 0           |
| Guideline levels<br>ASHRAE/AIHA |           | 68 - 75°F/winter<br>73-79 °F/summer | 30-60%                | Outdoor level<br>+ 700 ppm | 9 ppm                 | 65 ug/m <sup>3</sup>                        | 1 ppm       |

Comments: N/A

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: [Signature] Date: 5-17-02

**ATC ASSOCIATES, INC.**  
**INDOOR AIR QUALITY FIELD REPORT**

Page 5 of 10

Time: 9:40 AM LOCATION: 100 Trinity Place /HS for Economics And Finances DATE: 5-17-02 PROJECT NO: 15-19125-0291

| Location                          | Occupants | Temperature (°F)                    | Relative Humidity (%) | Carbon Dioxide (ppm)       | Carbon Monoxide (ppm) | Respirable Particulate (ug/m <sup>3</sup> ) | TVOCs (ppm) |
|-----------------------------------|-----------|-------------------------------------|-----------------------|----------------------------|-----------------------|---------------------------------------------|-------------|
| STAIRCASE B<br>2ND FLOOR          | 0         | 78.6                                | 40.7                  | 496                        | 1                     | 15                                          | 0           |
| Room 207                          | 0         | 81.5                                | 39.7                  | 610                        | 1                     | 16                                          | 0           |
| Room 204                          | 2         | 78.7                                | 37.3                  | 649                        | 1                     | 10                                          | 0           |
| 2ND FLOOR HALLWAY<br>SOUTHSIDE    | 1         | 77.9                                | 38.8                  | 506                        | 1                     | 16                                          | 0           |
| GIM                               | 0         | 76.5                                | 36.4                  | 501                        | 1                     | 10                                          | 0           |
| AUDITORIUM                        | 10        | 76.8                                | 42.7                  | 770                        | 1                     | 8                                           | 0           |
| 1ST FLOOR LOBBY                   | 0         | 76.8                                | 43.9                  | 803                        | 1                     | 9                                           | 0           |
| Out Doors EXT MAIN ENTRY          | 0         | 81.7                                | 36.9                  | 437                        | 1                     | 65                                          | 0           |
| Out Doors EXT MAIN ENTRY<br>SOUTH | 0         | 81.9                                | 36.2                  | 439                        | 1                     | 70                                          | 0           |
| Out Doors EXT MAIN ENTRY<br>NORTH | 0         | 81.9                                | 36.4                  | 421                        | 1                     | 66                                          | 0           |
| Guideline levels<br>ASHRAE/AIHA   |           | 68 - 75°F/winter<br>73-79 °F/summer | 30-60%                | Outdoor level<br>+ 700 ppm | 9 ppm                 | 65 ug/m <sup>3</sup>                        | 1 ppm       |

Comments: N/A

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: [Signature] Date: 5-17-02

**ATC ASSOCIATES, INC.**  
**INDOOR AIR QUALITY FIELD REPORT**

Page 6 of 10

Time: 12:12 pm LOCATION: 100 Trinity Place /HS for Economics And Finances DATE: 5-17-02 PROJECT NO: 15-19125-0291

| Location                        | Occupants | Temperature (°F)                    | Relative Humidity (%) | Carbon Dioxide (ppm)       | Carbon Monoxide (ppm) | Respirable Particulate (ug/m <sup>3</sup> ) | TVOCs (ppm) |
|---------------------------------|-----------|-------------------------------------|-----------------------|----------------------------|-----------------------|---------------------------------------------|-------------|
| Out Doors EXT MAIN ENTRY        | 0         | 79.5                                | 50.8                  | 491                        | 1                     | 46                                          | 0           |
| Out Doors EXT MAIN ENTRY SOUTH  | 0         | 79.5                                | 50.8                  | 498                        | 1                     | 48                                          | 0           |
| Out Doors EXT MAIN ENTRY NORTH  | 0         | 79.5                                | 50.8                  | 492                        | 1                     | 46                                          | 0           |
| 10TH FLOOR HALLWAY              | 0         | 79.1                                | 45.1                  | 526                        | 1                     | 16                                          | 0           |
| LIBRARY                         | 0         | 79.6                                | 44.9                  | 591                        | 1                     | 11                                          | 0           |
| R 1006                          | 0         | 78.9                                | 45.6                  | 441                        | 1                     | 8                                           | 0           |
| STAIRCASE A 9TH FLOOR           | 0         | 78.1                                | 42.1                  | 581                        | 1                     | 9                                           | 0           |
| 9TH FLOOR HALLWAY               | 0         | 76.9                                | 43.6                  | 526                        | 1                     | 10                                          | 0           |
| Rm 915                          | 12        | 77.1                                | 43.1                  | 891                        | 1                     | 11                                          | 0           |
| Rm 933                          | 0         | 77.6                                | 43.9                  | 491                        | 1                     | 12                                          | 0           |
| Guideline levels<br>ASHRAE/AIHA |           | 68 - 75°F/winter<br>73-79 °F/summer | 30-60%                | Outdoor level<br>+ 700 ppm | 9 ppm                 | 65 ug/m <sup>3</sup>                        | 1 ppm       |

Comments: NA

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: [Signature]Date: 5-17-02

# ATC ASSOCIATES, INC. INDOOR AIR QUALITY FIELD REPORT

Page 7 of 10

Time: 12<sup>26</sup>pm LOCATION: 100 Trinity Place /HS for Economics And Finances DATE: 5/7/02 PROJECT NO: 15-19125-0291

| Location                        | Occupants | Temperature (°F)                    | Relative Humidity (%) | Carbon Dioxide (ppm)       | Carbon Monoxide (ppm) | Respirable Particulate (ug/m <sup>3</sup> ) | TVOCs (ppm) |
|---------------------------------|-----------|-------------------------------------|-----------------------|----------------------------|-----------------------|---------------------------------------------|-------------|
| Rm 904                          | 10        | 80.1                                | 42.1                  | 710                        | 1                     | 14                                          | 0           |
| STAIRCASE B<br>8TH FLOOR        | 0         | 80.6                                | 43.1                  | 526                        | 1                     | 15                                          | 0           |
| 8TH FLOOR<br>HALLWAY            | 0         | 79.9                                | 42.7                  | 514                        | 1                     | 12                                          | 0           |
| Kitchen                         | 3         | 79.9                                | 43.3                  | 669                        | 1                     | 10                                          | 0           |
| CAFETERIA                       | 4         | 78.8                                | 42.9                  | 701                        | 1                     | 13                                          | 0           |
| STAIRCASE A<br>7TH FLOOR        | 0         | 77.1                                | 43.3                  | 437                        | 1                     | 15                                          | 0           |
| Room 706                        | 10        | 80.9                                | 42.1                  | 710                        | 1                     | 11                                          | 0           |
| Room 704                        | 22        | 81.1                                | 42.3                  | 1113                       | 1                     | 8                                           | 0           |
| Room 703                        | 30        | 81.6                                | 42.9                  | 1261                       | 1                     | 10                                          | 0           |
| 7TH FLOOR HALLWAY               | 0         | 80.9                                | 42.3                  | 461                        | 1                     | 12                                          | 0           |
| Guideline levels<br>ASHRAE/AIHA |           | 68 - 75°F/winter<br>73-79 °F/summer | 30-60%                | Outdoor level<br>+ 700 ppm | 9 ppm                 | 65 ug/m <sup>3</sup>                        | 1 ppm       |

Comments: NA

The assessed location(s) ☐ Does ☐ Does not meet established indoor air quality guidelines.

Signature: [Signature] Date: 5/7/02

CITY\_21MC100\_002882249

**ATC ASSOCIATES, INC.**  
**INDOOR AIR QUALITY FIELD REPORT**

Page 8 of 10

Time: 12<sup>46</sup>pm LOCATION: 100 Trinity Place /HS for Economics And Finances DATE: 5-17-02 PROJECT NO: 15-19125-0291

| Location                        | Occupant | Temperature (°F)                    | Relative Humidity (%) | Carbon Dioxide (ppm)       | Carbon Monoxide (ppm) | Respirable Particulate (ug/m <sup>3</sup> ) | TVOCs (ppm) |
|---------------------------------|----------|-------------------------------------|-----------------------|----------------------------|-----------------------|---------------------------------------------|-------------|
| STAIRCASE B<br>6TH FLOOR.       | 0        | 80.9                                | 39.6                  | 561                        | 1                     | 17                                          | 0           |
| 6TH FLOOR.<br>HALLWAY           | 0        | 81.1                                | 39.3                  | 572                        | 1                     | 11                                          | 0           |
| Room 604                        | 0        | 81.9                                | 39.9                  | 429                        | 1                     | 17                                          | 0           |
| Room 605                        | 21       | 81.3                                | 40.1                  | 1121                       | 1                     | 10                                          | 0           |
| Room 608                        | 16       | 81.6                                | 39.6                  | 1026                       | 1                     | 11                                          | 0           |
| STAIRCASE A<br>6TH FLOOR.       | 0        | 81.6                                | 39.1                  | 471                        | 1                     | 8                                           | 0           |
| 5TH FLOOR Room<br>509           | 0        | 80.1                                | 40.4                  | 486                        | 1                     | 10                                          | 0           |
| Room 606                        | 30       | 79.9                                | 39.6                  | 1067                       | 1                     | 16                                          | 0           |
| 5TH FLOOR<br>HALLWAY            | 0        | 80.2                                | 41.3                  | 491                        | 1                     | 16                                          | 0           |
| Room 507                        | 21       | 81.1                                | 41.1                  | 1131                       | 1                     | 10                                          | 0           |
| Guideline levels<br>ASHRAE/AIHA |          | 68 – 75°F/winter<br>73-79 °F/summer | 30-60%                | Outdoor level<br>+ 700 ppm | 9 ppm                 | 65 ug/m <sup>3</sup>                        | 1 ppm       |

Comments: N/A

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: [Signature] Date: 5-17-02

# ATC ASSOCIATES, INC. INDOOR AIR QUALITY FIELD REPORT

Page 9 of 10

Time: 1:00 pm LOCATION: 100 Trinity Place /HS for Economics And FinancesDATE: 5/7/02 PROJECT NO: 15-19125-0291

| Location                        | Occupants | Temperature (°F)                    | Relative Humidity (%) | Carbon Dioxide (ppm)       | Carbon Monoxide (ppm) | Respirable Particulate (ug/m <sup>3</sup> ) | TVOCs (ppm) |
|---------------------------------|-----------|-------------------------------------|-----------------------|----------------------------|-----------------------|---------------------------------------------|-------------|
| Room 504                        | 0         | 81.1                                | 39.0                  | 465                        | 1                     | 14                                          | 0           |
| STAIRCASE B- 4TH FLOOR          | 0         | 81.2                                | 39.6                  | 477                        | 1                     | 19                                          | 0           |
| 4TH FLOOR HALLWAY               | 0         | 82.3                                | 39.9                  | 501                        | 1                     | 16                                          | 0           |
| Room 404                        | 22        | 81.9                                | 41.4                  | 1021                       | 1                     | 10                                          | 0           |
| Room 405                        | 31        | 81.6                                | 40.3                  | 1261                       | 1                     | 12                                          | 0           |
| Room 406                        | 26        | 81.3                                | 39.8                  | 1091                       | 1                     | 16                                          | 0           |
| Room 410                        | 0         | 81.6                                | 39.6                  | 471                        | 1                     | 12                                          | 0           |
| Room 409                        | 0         | 79.6                                | 39.8                  | 461                        | 1                     | 11                                          | 0           |
| STAIRCASE A 3RD FLOOR           | 1         | 81.3                                | 44.6                  | 510                        | 1                     | 14                                          | 0           |
| Room 307                        | 0         | 81.4                                | 41.1                  | 445                        | 1                     | 8                                           | 0           |
| Guideline levels<br>ASHRAE/AIHA |           | 68 - 75°F/winter<br>73-79 °F/summer | 30-60%                | Outdoor level<br>+ 700 ppm | 9 ppm                 | 65 ug/m <sup>3</sup>                        | 1 ppm       |

Comments: NA

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: [Signature]Date: 5/7/02

# ATC ASSOCIATES, INC. INDOOR AIR QUALITY FIELD REPORT

Page 10 of 10

Time: 1:30 PM LOCATION: 100 Trinity Place /HS for Economics And Finances DATE: 5-17-02 PROJECT NO: 15-19125-0291

| Location                          | Occupant | Temperature (°F)                    | Relative Humidity (%) | Carbon Dioxide (ppm)       | Carbon Monoxide (ppm) | Respirable Particulate (ug/m <sup>3</sup> ) | TVOCs (ppm) |
|-----------------------------------|----------|-------------------------------------|-----------------------|----------------------------|-----------------------|---------------------------------------------|-------------|
| STAIRCASE B<br>2ND FLOOR          | 0        | 79.6                                | 41.6                  | 510                        | 1                     | 16                                          | 0           |
| Room 207                          | 0        | 81.9                                | 39.9                  | 560                        | 1                     | 11                                          | 0           |
| Room 204                          | 10       | 79.6                                | 39.9                  | 819                        | 1                     | 8                                           | 0           |
| 2ND FLOOR HALLWAY<br>NORTHSIDE    | 1        | 78.8                                | 38.7                  | 509                        | 1                     | 10                                          | 0           |
| Gym                               | 0        | 77.6                                | 37.6                  | 426                        | 1                     | 14                                          | 0           |
| AUDITORIUM                        | 10       | 76.6                                | 46.6                  | 791                        | 1                     | 10                                          | 0           |
| 1ST FLOOR LOBBY                   | 4        | 76.5                                | 46.3                  | 858                        | 1                     | 12                                          | 0           |
| Out Doors EXT MAIN<br>ENTRY       | 0        | 78.2                                | 51.3                  | 493                        | 1                     | 65                                          | 0           |
| Out Doors EXT MAIN ENTRY<br>SOUTH | 0        | 79.2                                | 51.3                  | 496                        | 1                     | 68                                          | 0           |
| Out Doors EXT MAIN ENTRY<br>NORTH | 0        | 78.2                                | 51.3                  | 501                        | 1                     | 69                                          | 0           |
| Guideline levels<br>ASHRAE/AIHA   |          | 68 - 75°F/winter<br>73-79 °F/summer | 30-60%                | Outdoor level<br>+ 700 ppm | 9 ppm                 | 65 ug/m <sup>3</sup>                        | 1 ppm       |

Comments: NA

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: [Signature]

Date: 5-17-02

**ATC ASSOCIATES, INC.**  
**INDOOR AIR QUALITY FIELD REPORT**

Page 1 of 9

Time: 5:36 pm LOCATION: 100 TRINITY PLACE DATE: 5/17/02 PROJECT NO: 15-19125-0290

| Location                        | Occupants | Temperature (°F)                    | Relative Humidity (%) | Carbon Dioxide (ppm)       | Carbon Monoxide (ppm) | Respirable Particulates (ug/m <sup>3</sup> ) | TVOCs (ppm) |
|---------------------------------|-----------|-------------------------------------|-----------------------|----------------------------|-----------------------|----------------------------------------------|-------------|
| IN STAIRWELL B 6TH FLOOR        | 0         | 80.9                                | 46.9                  | 526                        | 1                     | 19                                           | 0           |
| IN STAIRWELL B 7TH FLOOR        | 0         | 80.1                                | 46.5                  | 499                        | 1                     | 21                                           | 0           |
| IN STAIRWELL B 3RD FLOOR        | 0         | 80.6                                | 45.8                  | 510                        | 1                     | 21                                           | 0           |
|                                 |           |                                     |                       |                            |                       |                                              |             |
|                                 |           |                                     |                       |                            |                       |                                              |             |
|                                 |           |                                     |                       |                            |                       |                                              |             |
|                                 |           |                                     |                       |                            |                       |                                              |             |
|                                 |           |                                     |                       |                            |                       |                                              |             |
|                                 |           |                                     |                       |                            |                       |                                              |             |
|                                 |           |                                     |                       |                            |                       |                                              |             |
| Guideline levels<br>ASHRAE/AIHA |           | 68 – 75°F/winter<br>73-79 °F/summer | 30-60%                | Outdoor level<br>+ 700 ppm | 9 ppm                 | 65 ug/m <sup>3</sup>                         | 1 ppm       |

Comments: NA

The assessed location(s) ( ) Does ( ) Does not meet established indoor air quality guidelines.

Signature: [Signature] Date: 5/17/02