

Asbestos Report

ASBESTOS REPORTS

Notes

- All bulk/wipe samples were analyzed by PLM.
- Area air samples were analyzed by PCM (point counting of fibers) or TEM (fiber ID).

	Location	Monitoring	Result	Structure	Comment
1	66 John St./59 Maiden Lane	Air	Negative	Okay	
2	60 Board St./33 Beaver			Okay. Pre-existing condition shows cracks.	Memo/Report pending
3	32-42 Broadway	Air	Negative	Okay	
4	80 Maiden Lane	Air	Negative	Okay	
5	2 Washington/17 Battery Place	*Bulk	Negative	Okay	Due to tenant complains the site is being re-sampled.
6	2 Rector St.	Air	Negative	Okay	
7	11 Park Place	Air	Negative	Okay	
8	150 William St.	Air	Negative	Okay	
9	40 Worth	Air	Negative	Okay	
10	110 William St.	Bulk/ Air	Negative	Okay	
11	100 Church	Bulk	Positive	Damage (broken windows etc.).	Abatement warranted
12	346 Broadway				
13	75 Park Place				
14	250 Broadway				
15	61 Broadway				
16	136 Church				

17	60 Hudson	Bulk/Air	Negative/Not enough info to make an appropriate determination	Okay	
18	52 Duane St.				
19	225 Broadway				
20	93 Worth				
	Location	Monitoring	Result	Structure	Comment
21	55 6th Ave				
22	156 William St.				
23	365 Broadway				
24	255 E. Houston				
25	100 Gold				
26	180 Suffolk				
27	180 Water				
28	275 Clinton				
29	125 Worth				
30	161 William St.				
31	250 Church	Bulk/Air	Negative	Okay	
32	349 Broadway				
33	42 South St.				
34	71-73 Worth				
35	253 Broadway				
36	Pier 26				