

SciLab Job #: 201092765

Client Name: Hygienetics Environmental, Inc.

Table I

Summary of Transmission Electron Microscopy (TEM) Results for Asbestos (air)

2060.035/NY#39438; Stellar Management; Two Rector Street, NY, NY / AIR QUALITY MONITORING / Various Floors

P. 02/04
212 679 9392

SciLab Sample #	Client Sample #	Dilution Factor	Air Filtered (liters)	Area Analyzed (sq. mm.)	* Analytical Sensitivity (struc/cc air)	Asbestos Structures Detected (Microns)			Structure Density (struc/sq. mm.)		Structure Concentration (struc/cc air)		Type of Asbestos
						0.5-5.0	>5.0	Total	>5.0	Total	>5.0	Total	
01	092101851-01 North Corner - 8th Floor		800	.1	0.0048	0.0	0.0	0.0	<10	<10	<0.0048	<0.0048	NSD
02	092101851-03 Northwest Corner - 8th Floor		731	.1	0.0053	0.0	0.0	0.0	<10	<10	<0.0053	<0.0053	NSD
03	092101851-23 Center at File Cabinets, Hall - 6th Floor		700	.1	0.0055	0.0	0.0	0.0	<10	<10	<0.0055	<0.0055	NSD

TEM AIR

9/22/01

3 SAMPLES

-NSD-

SCIENTIFIC LABS

24:42
SEP-22-2001

concentration represented by the detection of 1 structure

* not analyzed

SD: No Asbestos Structures Detected

Reviewed By: _____; Analyzed By: Alexsandr Barengolts Date: 9/22/01

VLAP#: 200546-0

CITY_21MC100_008870468