

P.T.&L. Environmental Services

Air Sample Record & Chain of Custody

411 Sette Drive, Paramus, New Jersey 07652-2912 • 201-262-4141

ASBESTOS OSHA

For NIOSH Methodologies

Line No.	Lab. No.	Worker Name	Monitored	Pump	Initial Flow	Mean	Time On	Total	Total	Sample
	Sample No.	Social Security No.	Activity	No.	Final Flow	Flow	Time Off	Time	Volume	Results
					(L/Min.)	(L/Min.)	(24-hr)	(Min)	(L)	(ug/m ³)
	0053A	Corner of Greenwich & Murray	B	1	4	4	20.50	295	1180	
		"Sign-in/out"			4	4	1.45			
	0054A	Middle trailer		2	4	4	19.55	350	1400	
					4	4	1.45			
	0055	Middle trailer		3	4	4	19.55	350	1400	
					4	4	1.45			
	0056	Field Blank	-	-	-	-	-	-	-	
	0057	Field Blank	-	-	-	-	-	-	-	
	0058	Corner of Greenwich & Murray		1	4	4	1.45	300	1200	
		"Sign-in/out"			4	4	6.45			
	0059	Middle trailer		2	4	4	1.45	300	1200	BDL
					4	4	6.45			
	0060	Middle trailer		3	4	4	1.45	300	1200	
					4	4	6.45			
	129342									
	129343									
	129344									

N: Asbestos / Fibers by PCM Total No. of Samples: 8 (eight) Job Number: PC 17781
 NU: 7400 Turnaround Time: 48 Std. = 72 hrs. Job Name: WTC 5,6,7
 M: <1.2um, 25mm, CE Calibration Method: Rotometer Job Location: Greenwich
 E: 0.5 Technician: Eugene Reydobay
 129347: 16.0 Laboratory Name: EAS
 129348: 400 (@ 0.1 f/cc) Laboratory Address: 4 Westchester Plaza Work Area: 2
 129349: Adj. to 100 - 1,300 f/mm² Elmsford, NY 10523-1610 Contractor: SEASONS
 A: 2 to 10 per set Laboratory Telephone: (914) 592-8380 Date: 9/23/01
 M: n/s (2 per batch) Laboratory Fax: (914) 592-8956 Page 1 of 1

Bulk Sample required?:

Yes ☐ No ☒

Relinquished By		Received By		Organization or Affiliation	Date of Transfer	Time of Transfer	Reason for Transfer
Print	Sign	Print	Sign				

Fax results promptly to the attention of David Harris at (201) 262-6778 or _____

G:\APPS\MSOFFICE\MTF\RM\ASR\COCK.XLS

Shift #6

Dry.