

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 2 of 12TIME 8:00LOCATION Stuyvesant H.S. (M477) DATE 5/21/02 PROJECT NO. 19125-0246

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
<i>Outside</i>		<i>56.1</i>	<i>33.4</i>	<i>354</i>	<i>0</i>	<i>15</i>	<i>0</i>
<i>1st floor Hallway, North</i>	<i>10</i>	<i>67.2</i>	<i>30.3</i>	<i>454</i>	<i>0</i>	<i>7</i>	<i>0</i>
<i>Auditorium</i>		<i>67.7</i>	<i>30.0</i>	<i>448</i>	<i>0</i>	<i>10</i>	<i>0</i>
<i>1st fl. lobby</i>	<i>6</i>	<i>68.4</i>	<i>31.4</i>	<i>516</i>	<i>0</i>	<i>8</i>	<i>0</i>
<i>125</i>	<i>30</i>	<i>70.5</i>	<i>32.8</i>	<i>722</i>	<i>0</i>	<i>10</i>	<i>0</i>
<i>129</i>	<i>30</i>	<i>71.2</i>	<i>33.6</i>	<i>843</i>	<i>0</i>	<i>11</i>	<i>0</i>
<i>132</i>		<i>70.8</i>	<i>31.9</i>	<i>713</i>	<i>0</i>	<i>9</i>	<i>0</i>
<i>133</i>	<i>30</i>	<i>71.6</i>	<i>32.7</i>	<i>824</i>	<i>0</i>	<i>10</i>	<i>0</i>
<i>Hallway by 133</i>	<i>2</i>	<i>71.2</i>	<i>30.7</i>	<i>675</i>	<i>1</i>	<i>8</i>	<i>0</i>
<i>Stair West side</i>		<i>71.8</i>	<i>30.1</i>	<i>504</i>	<i>1</i>	<i>7</i>	<i>0</i>
Guideline levels ASHRAE/AHIA/EPA		68 -75°F/winter 73 -79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) ☐ Does ☐ Does not meet established indoor air quality guidelines.Signature: *H. H. H.* Date: *5/21/02*

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 2 of 12TIME 8:30

LOCATION

Stuyvesant H.S (M47F)

DATE

5/21/02

PROJECT NO.

19125-0246

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
<i>2nd fl. lobby</i>	<i>4</i>	<i>69.8</i>	<i>30.0</i>	<i>536</i>	<i>0</i>	<i>8</i>	<i>0</i>
<i>213 m. office</i>		<i>70.1</i>	<i>30.4</i>	<i>613</i>	<i>0</i>	<i>8</i>	<i>0</i>
<i>211 G. office</i>	<i>3</i>	<i>70.6</i>	<i>30.8</i>	<i>736</i>	<i>0</i>	<i>10</i>	<i>0</i>
<i>260</i>		<i>69.5</i>	<i>30.1</i>	<i>642</i>	<i>0</i>	<i>11</i>	<i>0</i>
<i>229</i>	<i>30</i>	<i>70.8</i>	<i>31.2</i>	<i>865</i>	<i>0</i>	<i>13</i>	<i>0</i>
<i>231</i>	<i>30</i>	<i>71.2</i>	<i>31.4</i>	<i>884</i>	<i>0</i>	<i>14</i>	<i>0</i>
<i>233</i>	<i>30</i>	<i>71.4</i>	<i>31.4</i>	<i>892</i>	<i>0</i>	<i>13</i>	<i>0</i>
<i>235</i>	<i>25</i>	<i>70.9</i>	<i>31.0</i>	<i>796</i>	<i>0</i>	<i>10</i>	<i>0</i>
<i>236 Gd. office</i>	<i>2</i>	<i>71.2</i>	<i>32.3</i>	<i>715</i>	<i>0</i>	<i>9</i>	<i>0</i>
<i>237</i>	<i>25</i>	<i>70.8</i>	<i>32.0</i>	<i>861</i>	<i>0</i>	<i>10</i>	<i>0</i>
Guideline levels ASHRAE/ATIA/EPA		68 -75°F/winter 73 -79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: _____

H. Soley

Date: _____

5/21/02

ATC ASSOCIATES, INC.

Page 3 of 12TIME 8:50

INDOOR AIR QUALITY FIELD REPORT

LOCATION Stuyvesant H.S. (M477) DATE 5/21/02 PROJECT NO. 19125-0246

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
<u>3rd fl. Hallway</u>	<u>3</u>	<u>70.6</u>	<u>29.8</u>	<u>672</u>	<u>1</u>	<u>7</u>	<u>0</u>
<u>3rd fl. Gym</u>	<u>30</u>	<u>71.0</u>	<u>32.6</u>	<u>736</u>	<u>1</u>	<u>14</u>	<u>0</u>
<u>303</u>	<u>30</u>	<u>70.5</u>	<u>33.1</u>	<u>825</u>	<u>0</u>	<u>11</u>	<u>0</u>
<u>305</u>	<u>25</u>	<u>71.2</u>	<u>30.4</u>	<u>806</u>	<u>0</u>	<u>10</u>	<u>0</u>
<u>307</u>	<u>30</u>	<u>70.4</u>	<u>31.8</u>	<u>895</u>	<u>0</u>	<u>12</u>	<u>0</u>
<u>313</u>	<u>30</u>	<u>71.6</u>	<u>32.0</u>	<u>912</u>	<u>0</u>	<u>10</u>	<u>0</u>
<u>315</u>	<u>25</u>	<u>71.2</u>	<u>32.1</u>	<u>897</u>	<u>0</u>	<u>13</u>	<u>0</u>
<u>327</u>	<u>25</u>	<u>70.5</u>	<u>32.6</u>	<u>884</u>	<u>0</u>	<u>11</u>	<u>0</u>
<u>329</u>	<u>30</u>	<u>70.8</u>	<u>33.4</u>	<u>905</u>	<u>1</u>	<u>10</u>	<u>0</u>
<u>333</u>	<u>30</u>	<u>71.2</u>	<u>33.7</u>	<u>914</u>	<u>0</u>	<u>10</u>	<u>0</u>
Guideline levels ASHRAE/AIHA/EPA		68 - 75°F/winter 73 - 79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) ☐ Does ☐ Does not meet established indoor air quality guidelines.Signature: H. H. Long Date: 5/21/02

CITY_21MC100_003797567

ATC ASSOCIATES, INC.

Page 4 of 62

TIME 9:15

INDOOR AIR QUALITY FIELD REPORT

LOCATION Stuyvesant H.S. (M477) DATE 5/21/02 PROJECT NO. 19125-0246

Location	Occup.	Temperature ("F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOC's (ppm)
335	25	71.2	33.6	896	0	11	0
336 Ph. office		68.4	30.1	673	1	15	0
337	30	70.4	34.2	839	0	13	0
338 Ph. lab		68.6	30.6	645	1	16	0
339	30	70.7	33.8	842	1	12	0
350		69.5	31.2	776	1	15	0
351		70.1	30.6	762	0	15	0
4th fl. Hallway	6	70.3	30.2	755	1	12	0
401	2	71.3	29.9	817	0	10	0
402 office		71.6	30.4	784	0	9	0
Guideline levels ASHRAE/AHIA/EPA		68 -75°F/winter 73 -79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) ☐ Does ☐ Does not meet established indoor air quality guidelines.Signature: H. Lopez Date: 5/21/02

ATC ASSOCIATES, INC.

Page 5 of 12TIME 3:40

INDOOR AIR QUALITY FIELD REPORT

LOCATION Stuyvesant H.S (M477) DATE 5/21/02 PROJECT NO. 19125-0246

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
403	20	71.6	33.6	785	1	10	0
404		70.8	30.1	709	1	9	0
405	30	72.3	34.8	862	0	12	0
407	25	72.0	33.5	833	0	11	0
411	15	71.2	32.6	816	0	12	0
413		70.8	31.8	801	0	9	0
427	30	71.9	35.1	915	0	14	0
429		70.3	32.0	820	1	10	0
431	30	71.4	34.9	941	1	12	0
433	10	70.8	31.8	772	0	11	0
Guideline levels ASHRAE/AHIA/EPA		68 - 75°F/winter 73 - 79°F/summer	30-60%	Outdoor level + 700'ppm	9 ppm	65 ug/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: H. Anderson Date: 5/21/02

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 6 of 12

TIME 10:05

LOCATION Stuyvesant HS (M477) DATE 5/21/02 PROJECT NO. 19125-0246

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
435	30	72.4	35.2	896	0	12	0
436	20	70.6	34.1	861	0	10	0
437	4	70.8	32.6	743	1	13	0
439		71.0	31.5	725	0	11	0
440		70.2	30.8	719	0	12	0
5th Fl Hallway	25	71.8	32.4	885	0	10	0
Cafeteria	50	72.3	34.8	945	0	14	0
503		71.0	30.9	856	1	10	0
505	3	71.6	31.2	831	0	11	0
507		70.8	30.5	826	0	10	0
Guideline levels ASHRAE/ATIA/EPA		68-75°F/winter 73-79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³ 24-hour average	1 ppm

Comments:

The assessed location(s) () Does () Does not meet established indoor air quality guidelines.

Signature: H. H. H. Date: 5/24/02

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 7 of 12TIME 10:30LOCATION Stuyvesant H.S (M4TH) DATE 5/21/02 PROJECT NO. 19125-0246

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
511	5	70.2	35.1	765	0	8	0
513	10	71.0	34.6	791	0	9	0
525	25	71.7	33.8	844	0	9	0
6th fl. Hallway	4	71.5	31.5	773	0	10	0
6th fl. Gym	30	72.6	36.1	927	1	14	0
601 office	1	71.4	31.8	834	0	9	0
615 library	15	72.5	32.8	855	1	7	0
627	30	72.1	33.5	976	0	12	0
629	25	71.9	36.1	920	0	11	0
635	20	71.6	35.2	918	1	10	0
Guideline levels ASHRAE/AHIA/EPA		68 - 75°F/winter 73 - 79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) ☐ Does ☐ Does not meet established indoor air quality guidelines.Signature: H. Soley Date: 5/21/02

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 8 of 12TIME 10:55LOCATION Stuyvesant H.S (M477) DATE 5/21/02 PROJECT NO. 19125-0246

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOC's (ppm)
636	30	72.6	33.6	1014	0	12	0
638	30	72.5	34.8	1026	0	11	0
639	30	71.9	35.2	997	0	10	0
640	25	71.4	32.9	984	0	12	0
Stair West side	1	72.3	29.7	740	0	10	0
7th floor Hallway	4	71.9	30.1	804	1	11	0
701 office	1	72.3	30.4	820	0	10	0
702 office	1	71.6	30.6	786	0	9	0
703 lab	3	70.8	32.5	761	1	14	0
704 office	1	71.4	31.4	752	0	9	0
Guideline levels ASHRAE/AHIA/EPA		68 - 75°F/winter 73 - 79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) ☐ Does ☐ Does not meet established indoor air quality guidelines.Signature: H. Long Date: 5/21/02

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 9 of 12TIME 1:20LOCATION Stuyvesant H.S (M477) DATE 5/21/02 PROJECT NO. 19125-00246

Location	Occup.	Temperature ("F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
715	30	72.4	30.8	1062	0	12	0
717	25	71.8	29.6	1020	0	10	0
726 S.R	6	71.6	32.9	972	0	9	0
727 lab	25	70.9	30.1	985	0	14	0
736	30	72.0	33.2	1031	0	11	0
737	30	72.4	32.9	1042	0	12	0
738	25	71.8	32.4	1005	0	15	0
739	30	71.6	33.6	1072	0	14	0
740	30	72.2	34.2	1106	0	11	0
Stair West side	1	72.5	30.1	742	0	9	0
Guideline levels ASHRAE/AIAA/EPA		68 -75°F/winter 73 -79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) ☐ Does ☐ Does not meet established indoor air quality guidelines.Signature: H. A. Joy Date: 5/21/02

CITY_21MC100_003797573

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 10 of 12TIME 11:45LOCATION Stuyvesant H.S (M47F) DATE 5/21/02 PROJECT NO. 19125-0246

Location	Occup.	Temperature ("F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
<u>8th fl. Hallway</u>	<u>7</u>	<u>71.6</u>	<u>29.2</u>	<u>762</u>	<u>0</u>	<u>10</u>	<u>0</u>
<u>801 office</u>	<u>1</u>	<u>72.3</u>	<u>30.2</u>	<u>803</u>	<u>0</u>	<u>11</u>	<u>0</u>
<u>807 F. lab</u>		<u>72.0</u>	<u>31.6</u>	<u>859</u>	<u>1</u>	<u>14</u>	<u>0</u>
<u>804</u>	<u>30</u>	<u>72.6</u>	<u>32.7</u>	<u>1126</u>	<u>0</u>	<u>17</u>	<u>0</u>
<u>826 s. cl.</u>	<u>5</u>	<u>72.4</u>	<u>31.8</u>	<u>942</u>	<u>0</u>	<u>12</u>	<u>0</u>
<u>827 G.L.</u>	<u>20</u>	<u>71.8</u>	<u>34.6</u>	<u>976</u>	<u>1</u>	<u>10</u>	<u>0</u>
<u>835</u>	<u>30</u>	<u>72.6</u>	<u>35.2</u>	<u>997</u>	<u>0</u>	<u>12</u>	<u>0</u>
<u>836</u>	<u>30</u>	<u>72.8</u>	<u>34.8</u>	<u>1019</u>	<u>0</u>	<u>11</u>	<u>0</u>
<u>840</u>	<u>30</u>	<u>71.9</u>	<u>33.9</u>	<u>1087</u>	<u>0</u>	<u>10</u>	<u>0</u>
<u>Stair West side</u>	<u>4</u>	<u>71.4</u>	<u>29.8</u>	<u>971</u>	<u>0</u>	<u>9</u>	<u>0</u>
Guideline levels ASHRAE/AIHA/EPA		68 -75°F/winter 73 -79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) ☐ Does ☐ Does not meet established indoor air quality guidelines.Signature: H. A. Long Date: 5/21/02

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 11 of 12TIME 12:10LOCATION Stuyvesant H.S. (M477) DATE 5/21/02 PROJECT NO. 19125-0246

Location	Occup.	Temperature ("F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates(ug/m ³)	TVOCs (ppm)
<u>9th Fl. Hallway</u>	<u>10</u>	<u>71.8</u>	<u>30.8</u>	<u>745</u>	<u>0</u>	<u>9</u>	<u>0</u>
<u>901 office</u>		<u>72.1</u>	<u>31.4</u>	<u>802</u>	<u>0</u>	<u>8</u>	<u>0</u>
<u>902</u>	<u>25</u>	<u>71.9</u>	<u>34.6</u>	<u>961</u>	<u>0</u>	<u>12</u>	<u>0</u>
<u>925 lab</u>	<u>20</u>	<u>71.6</u>	<u>32.7</u>	<u>1041</u>	<u>1</u>	<u>12</u>	<u>0</u>
<u>926 s. C</u>	<u>6</u>	<u>71.3</u>	<u>35.6</u>	<u>930</u>	<u>0</u>	<u>11</u>	<u>0</u>
<u>935</u>	<u>30</u>	<u>72.4</u>	<u>36.1</u>	<u>1077</u>	<u>0</u>	<u>13</u>	<u>0</u>
<u>936</u>	<u>30</u>	<u>72.2</u>	<u>35.4</u>	<u>1116</u>	<u>1</u>	<u>14</u>	<u>0</u>
<u>938 s. R.</u>	<u>5</u>	<u>71.9</u>	<u>34.6</u>	<u>925</u>	<u>0</u>	<u>12</u>	<u>0</u>
<u>939</u>	<u>30</u>	<u>72.1</u>	<u>33.8</u>	<u>1127</u>	<u>0</u>	<u>13</u>	<u>0</u>
<u>940</u>	<u>30</u>	<u>71.8</u>	<u>35.1</u>	<u>1165</u>	<u>1</u>	<u>12</u>	<u>0</u>
Guideline levels ASHRAE/AIHA/EPA		68 -75°F/winter 73 -79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) ☐ Does ☐ Does not meet established indoor air quality guidelines.Signature: H. Aubrey Date: 5/21/02

ATC ASSOCIATES, INC.
INDOOR AIR QUALITY FIELD REPORT

Page 12 of 12

TIME 12:35

LOCATION Stuyvesant H.S. (M477) DATE 5/21/02 PROJECT NO. 19125-0246

Location	Occup.	Temperature (°F)	Relative Humidity (%)	Carbon Dioxide (ppm)	Carbon Monoxide (ppm)	Respirable Particulates (ug/m ³)	TVOCs (ppm)
<u>10th fl. Hallway</u>	<u>10</u>	<u>72.6</u>	<u>30.8</u>	<u>874</u>	<u>0</u>	<u>10</u>	<u>0</u>
<u>1001</u>	<u>30</u>	<u>72.8</u>	<u>35.4</u>	<u>1175</u>	<u>0</u>	<u>12</u>	<u>0</u>
<u>1004</u>	<u>25</u>	<u>72.0</u>	<u>34.5</u>	<u>1142</u>	<u>0</u>	<u>11</u>	<u>0</u>
<u>1006</u>	<u>30</u>	<u>72.4</u>	<u>33.8</u>	<u>1181</u>	<u>0</u>	<u>11</u>	<u>0</u>
<u>1007</u>	<u>30</u>	<u>73.1</u>	<u>35.6</u>	<u>1170</u>	<u>0</u>	<u>13</u>	<u>0</u>
<u>1009</u>	<u>25</u>	<u>73.4</u>	<u>34.7</u>	<u>1166</u>	<u>0</u>	<u>12</u>	<u>0</u>
<u>1010</u>	<u>20</u>	<u>72.8</u>	<u>35.2</u>	<u>1142</u>	<u>0</u>	<u>10</u>	<u>0</u>
<u>1017</u>	<u>30</u>	<u>72.6</u>	<u>34.6</u>	<u>1130</u>	<u>0</u>	<u>14</u>	<u>0</u>
<u>1024</u>	<u>20</u>	<u>71.9</u>	<u>33.9</u>	<u>1126</u>	<u>0</u>	<u>13</u>	<u>0</u>
<u>Outside</u>		<u>63.8</u>	<u>31.8</u>	<u>402</u>	<u>0</u>	<u>18</u>	<u>0</u>
Guideline levels ASHRAE/AHIA/EPA		68 -75°F/winter 73 -79°F/summer	30-60%	Outdoor level + 700 ppm	9 ppm	65 ug/m ³ 24-hour average	1 ppm

Comments: _____

The assessed location(s) ☐ Does ☐ Does not meet established indoor air quality guidelines.

Signature: H. [Signature] Date: 5/21/02

CITY_21MC100_003797576