

DRAFT

Attachment 2
Laboratory Analysis Data for Air Samples
FDNY

FDNY World Trade Center Vehicles - SAMPLING REPORT

Date	Vendor	Eng./Ladder Co.	Sample Type	Comments	Results
11/21/01	ATC	Ladder 21	Asbestos Dust / Debris	9 samples	<1%
11/21/01	ATC	Squad 41	Asbestos Dust / Debris	9 samples	<1%
				All samples tested Negative for Asbestos	
11/23/01	ATC	Eng.Co.226	Asbestos / Bulk Sample	12 samples	<1% nd
11/28/01	ATC	na	Asbestos Dust / Debris	13 samples - All samples tested Negative for	nd
				asbestos content	
12/4/01	ATC	Eng.Co.217	Asbestos Dust / Debris	Sample # 5 - contained asbestos	2.10%
12/7/01	ATC	Ladder 131	Asbestos Dust	*Positive - for asbestos content-cabinet/floor	1.8%,1.3%,1.8%
12/13/01	KAM Consultants	Eng.Co.47	Wipe / Bulk Sample	Interior/Exterior (6samples) Asbestos=0%	0%
12/20/01	KAM Consultants	Eng.Co.214	Wipe / Bulk Sample	Interior/Exterior (6samples) Asbestos=0%	0%
1/2/02	KAM Consultants	#54 Paidge Ave	Bulk Sample	6 samples - 2 indicated asbestos less than 1%	<1%
1/25/02	KAM Consultants	Eng.Co.235	Wipe	Interior/Exterior (6samples) Asbestos=0%	0%
1/31/02	KAM Consultants	Eng.Co.217	Air Monitoring	Inside Crew Cabin	<0.01 f/cc
1/31/02	KAM Consultants	Eng.Co.163	Air Monitoring	Inside Crew Cabin	<0.01 f/cc
1/31/02	KAM Consultants	MP8904D	Air Monitoring	Inside Crew Cabin	<0.01 f/cc
1/31/02	KAM Consultants	Field Bank	Air Monitoring	Inside Crew Cabin	<0.055 f/field
2/6/02	KAM Consultants	QHC -H Bldg	Bulk Sample	Vehicle #776 - hood,intake box, interior f/b	Asbestos 0%
2/8/02	KAM Consultants	Eng.Co.279	Asbestos Air Monitoring	Drivers Cabin/Inside/Outside/Frt/Bck/Sides	<0.01f/cc
				Asbestos =0% Field Bank	<0.055 f/field
2/12/02	KAM Consultants	Eng.Co.211	Air Monitoring/Bulk Samp	Cabin Front/Back	Asb.0%,<0.01 f/cc
2/12/02	KAM Consultants	Eng.Co.9	Air Monitoring/Bulk Samp	Cabin Front/Back	Asb.0%,<0.01 f/cc
2/12/02	KAM Consultants	Eng.Co.16	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0056
2/12/02	KAM Consultants	Fleet Gar. EC279	Asbestos/Fiberglass/Silica	Inside Crew Cabin EC 279	<0.0044
2/12/02	KAM Consultants	Ladder Co. 7	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0067
2/13/02	KAM Consultants	Eng.Co.23	Asbestos/Fiberglass/Silica	Truck Cabin	<0.0040
2/13/02	KAM Consultants	Ladder Co. 15	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0063
2/13/02	KAM Consultants	Eng.Co.24	Asbestos/Fiberglass/Silica	Truck's Cabin	<0.0040
2/13/02	KAM Consultants	Eng.Co.226	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0045
2/13/02	KAM Consultants	Eng.Co.5	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0052
2/13/02	KAM Consultants	Eng.Co.7	Asbestos/Fiberglass/Silica	Inside Crew Cabin Asb.0.0345 CHR/ FG <0.0049 / Sil.<0.0049	
2/14/02	KAM Consultants	Eng.Co.205	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0050
2/14/02	KAM Consultants	Eng.Co. 211	Asbestos/Fiberglass/Silica	Cabin	<0.0050
		Ladder Co. 119	Asbestos/Fiberglass/Silica	Cabin	<0.0050

FDNY World Trade Center Vehicles - SAMPLING REPORT

Date	Vendor	Eng./Ladder Co.	Sample Type	Comments	Results
2/14/02	KAM Consultants	Eng.Co.201	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0048
2/14/02	KAM Consultants	Ladder Co.131	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/14/02	KAM Consultants	Ladder Co.114	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0050
2/14/02	KAM Consultants	Eng.Co.207	Asbestos/Fiberglass/Silica	Cabin	<0.0050
2/14/02	KAM Consultants	Eng.Co.239	Asbestos/Fiberglass/Silica	EC239	<0.0050
2/14/02	KAM Consultants	Eng.Co.228	Asbestos/Fiberglass/Silica	EC228	<0.0050
2/15/02	KAM Consultants	EMS Gar. 58th St	Asbestos/Fiberglass/Silica	Inside Car 778, Inside Car 716, Inside Trk 825	<0.0049
2/15/02	KAM Consultants	Eng.Co.220	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/15/02	KAM Consultants	Eng.Co.240	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/15/02	KAM Consultants	Eng.Co.219	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/15/02	KAM Consultants	Ladder Co.122	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/15/02	KAM Consultants	Eng.Co.224	Asbestos/Fiberglass/Silica	Inside Crew Cabin - Spare Apparatus tested	<0.0049
2/15/02	KAM Consultants	Eng.Co.209	Asbestos/Fiberglass/Silica	Inside Truck's Cabin	<0.0049
2/15/02	KAM Consultants	Ladd.1/ EC 7	Asbestos/Fiberglass/Silica	Battalion Chief Suburban, LC 1 Truck	<0.0049
2/15/02	KAM Consultants	Eng.Co.280	Asbestos/Fiberglass/Silica	Inside Truck's Cabin	<0.0049
2/15/02	KAM Consultants	Ladder Co. 104	Asbestos/Fiberglass/Silica	Inside Cabin	<0.0049
2/15/02	KAM Consultants	Eng.Co.221	Asbestos/Fiberglass/Silica	Inside Cabin	<0.0049
2/15/02	KAM Consultants	Ladder Co.102	Asbestos/Fiberglass/Silica	Inside Truck's Cabin	<0.0049
2/16/02	KAM Consultants	Eng.Co.9	Asbestos/Fiberglass/Silica	Asbestos 0.2317 CHR, FG 0.0267, Silica <0.0089	
2/16/02	KAM Consultants	Ladder Co.6	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/16/02	KAM Consultants	Satellite 1	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/16/02	KAM Consultants	Ladder Co. 20	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/16/02	KAM Consultants	Eng.Co.55	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/16/02	KAM Consultants	Eng.Co.505	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/16/02	KAM Consultants	Eng.Co.500	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/16/02	KAM Consultants	Ladder Co.5	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0048
2/16/02	KAM Consultants	Ladder Co.8	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/16/02	KAM Consultants	Eng.Co.4	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0042
2/16/02	KAM Consultants	Eng.Co. 10	Asbestos/Fiberglass/Silica	Inside Crew Cabin - Test was conducted in quarters of Eng.Co. 4 and Ladder 14	<0.0049
2/16/02	KAM Consultants	Eng.Co. 6	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/16/02	KAM Consultants	Eng.Co. 7	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
				Apparatus #8923 was tested at 59 Paidge Ave	
2/17/02	KAM Consultants	Eng.Co. 14	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/17/02	KAM Consultants	Ladder Co.3	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049

FDNY World Trade Center Vehicles - SAMPLING REPORT

Date	Vendor	Eng./Ladder Co.	Sample Type	Comments	Results
2/17/02	KAM Consultants	Ladder Co.12	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0048
2/17/02	KAM Consultants	Eng.Co. 3	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/17/02	KAM Consultants	Eng.Co.18	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0048
2/17/02	KAM Consultants	Ladder Co.1	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/17/02	KAM Consultants	Ladder Co.18	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0048
2/17/02	KAM Consultants	Eng.Co.15	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0048
2/17/02	KAM Consultants	Eng.Co. 28	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/17/02	KAM Consultants	Eng.Co. 26	Asbestos/Fiberglass/Silica	Asbestos 0.1632CHR, FG 0.0178, Silica <0.0089	
2/17/02	KAM Consultants	Ladder Co. 9	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0048
2/17/02	KAM Consultants	Eng.Co. 33	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0050
2/17/02	KAM Consultants	Ladder Co. 11	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/18/02	KAM Consultants	Ladder Co. 21	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0050
2/18/02	KAM Consultants	Ladder Co. 24	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/18/02	KAM Consultants	Ladder Co. 2	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0050
2/18/02	KAM Consultants	Eng.Co. 65	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/18/02	KAM Consultants	Eng.Co. 8	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/18/02	KAM Consultants	Eng.Co. 34	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/18/02	KAM Consultants	Eng.Co. 1	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/18/02	KAM Consultants	Eng.Co. 54	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/18/02	KAM Consultants	Ladder Co. 4	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/18/02	KAM Consultants	Ladder Co. 21	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0050
2/19/02	KAM Consultants	Ladder Co. 25	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/19/02	KAM Consultants	Eng.Co. 58	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/19/02	KAM Consultants	Ladder Co. 16	Asbestos/Fiberglass/Silica	Inside Truck #SL9414	<0.0049
2/19/02	KAM Consultants	Eng.Co. 39	Asbestos/Fiberglass/Silica	Inside Truck #MP8815	<0.0049
2/19/02	KAM Consultants	Eng.Co. 37	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/19/02	KAM Consultants	Eng.Co. 74	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/19/02	KAM Consultants	Eng.Co. 76	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/19/02	KAM Consultants	Ladder Co. 22	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/20/02	KAM Consultants	Eng.Co. 259	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/20/02	KAM Consultants	Ladder Co. 128	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/20/02	KAM Consultants	Ladder Co. 138	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0048
2/20/02	KAM Consultants	Ladder Co. 116	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/20/02	KAM Consultants	Eng.Co. 261	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/20/02	KAM Consultants	Eng.Co.258	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/20/02	KAM Consultants	Ladder Co. 115	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/20/02	KAM Consultants	Eng.Co. 264	Asbestos/Fiberglass/Silica	Inside Truck #SP98033	<0.0049
2/20/02	KAM Consultants	Eng.Co. 328	Asbestos/Fiberglass/Silica	Inside Truck #SP98038	<0.0049

FDNY World Trade Center Vehicles - SAMPLING REPORT

Date	Vendor	Eng./Ladder Co.	Sample Type	Comments	Results
2/20/02	KAM Consultants	Eng.Co. 260	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/20/02	KAM Consultants	Ladder Co. 136	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/21/02	KAM Consultants	Ladder Co.47	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/21/02	KAM Consultants	Squad Co. 41	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/21/02	KAM Consultants	Eng.Co. 64	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0050
2/21/02	KAM Consultants	Rescue Co. # 3	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/21/02	KAM Consultants	Eng. Co. 241	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/21/02	KAM Consultants	Ladder Co.161	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/21/02	KAM Consultants	Eng. Co. 35	Asbestos/Fiberglass/Silica	Inside Truck #35 SP99913	<0.0049
2/21/02	KAM Consultants	Eng.Co. 94	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/21/02	KAM Consultants	Eng. Co. 50	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/21/02	KAM Consultants	Eng.Co. 83	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0050
2/21/02	KAM Consultants	Ladder Co. 48	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/21/02	KAM Consultants	Eng.Co. 68	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/21/02	KAM Consultants	Reserve Pumper	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/22/02	KAM Consultants	Ladder #133	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/22/02	KAM Consultants	Squad #288	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/22/02	KAM Consultants	Eng.Co. 277	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0050
2/22/02	KAM Consultants	Eng.Co. 231	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0050
2/22/02	KAM Consultants	Eng.Co. 310	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/22/02	KAM Consultants	Eng.Co. 233	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/22/02	KAM Consultants	Rescue Co. # 1	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0047
2/22/02	KAM Consultants	Eng.Co. 262	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/22/02	KAM Consultants	Eng.Co. 311	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/23/02	KAM Consultants	Eng.Co. 22	Asbestos/Fiberglass/Silica	Positive for Asbestos 0.0433 Fiberglass <0.0048 Silica <0.0048	
2/23/02	KAM Consultants	Eng.Co. 53	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/23/02	KAM Consultants	Eng.Co. 43	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/23/02	KAM Consultants	Eng.Co. 44	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/23/02	KAM Consultants	Ladder Co. 35	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0048
2/23/02	KAM Consultants	Ladder Co. 13	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/23/02	KAM Consultants	Eng.Co. 40	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0050
2/23/02	KAM Consultants	Eng.Co. 21	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/23/02	KAM Consultants	Eng.Co. 72	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/23/02	KAM Consultants	Eng.Co. 9	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/23/02	KAM Consultants	Eng.Co. 26	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/24/02	KAM Consultants	Eng.Co. 212	Asbestos/Fiberglass/Silica	Eng.212 Spare-Foam Truck 212 only tested	<0.0049
2/24/02	KAM Consultants	Eng.Co. 281	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/24/02	KAM Consultants	Eng.Co. 284	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0050

FDNY World Trade Center Vehicles - SAMPLING REPORT

Date	Vendor	Eng./Ladder Co.	Sample Type	Comments	Results
2/24/02	KAM Consultants	Eng.Co. 229	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/24/02	KAM Consultants	Eng.Co. 278	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0050
2/24/02	KAM Consultants	Squad 252	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/24/02	KAM Consultants	Eng.Co. 230	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/24/02	KAM Consultants	Ladder Co. 149	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0048
2/24/02	KAM Consultants	Eng.Co. 216	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/24/02	KAM Consultants	Eng.Co. 249	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/24/02	KAM Consultants	Squad 18	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/25/02	KAM Consultants	Ladder 17	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/25/02	KAM Consultants	Eng.Co. 60	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/25/02	KAM Consultants	Ladder 54	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/25/02	KAM Consultants	Field Comm.Unit	Asbestos/Fiberglass/Silica	In Operation Area Reg.# 8509	<0.0049
2/25/02	KAM Consultants	Ladder Co. 14	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/25/02	KAM Consultants	Ladder Co. 26	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0050
2/25/02	KAM Consultants	Field Comm.Unit	Asbestos/Fiberglass/Silica	In Operation Area Reg.#FM01028	<0.0050
2/26/02	KAM Consultants	Eng.Co. 276	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/26/02	KAM Consultants	Eng.Co. 246	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/26/02	KAM Consultants	Eng.Co. 318	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/26/02	KAM Consultants	Ladder Co. 166	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/26/02	KAM Consultants	Eng.Co. 210	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/26/02	KAM Consultants	Eng.Co. 36	Asbestos/Fiberglass/Silica	Inside Truck #36 SP9309	<0.0049
2/26/02	KAM Consultants	Eng.Co. 47	Asbestos/Fiberglass/Silica	Inside Truck #47 SP9413	<0.0049
2/26/02	KAM Consultants	Ladder Co. 78	Asbestos/Fiberglass/Silica	Inside Crew Cabin - test done on spare apparat.	<0.0049
2/26/02	KAM Consultants	Ladder Co. 148	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/26/02	KAM Consultants	Eng.Co. 282	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/26/02	KAM Consultants	Eng.Co. 160	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/27/02	KAM Consultants	Eng.Co. 247	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/27/02	KAM Consultants	Eng.Co. 71	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/27/02	KAM Consultants	Ladder Co.55	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/27/02	KAM Consultants	Eng.Co.91	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/27/02	KAM Consultants	Batt. #3	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/27/02	KAM Consultants	Batt.#11	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/28/02	KAM Consultants	Eng.Co. 217	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/28/02	KAM Consultants	Eng.Co.227	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/28/02	KAM Consultants	Batt.#10	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
2/28/02	KAM Consultants	Batt.#8	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/1/02	KAM Consultants	Eng.Co.235	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/1/02	KAM Consultants	Ladder Co.124	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049

FDNY World Trade Center Vehicles - SAMPLING REPORT

Date	Vendor	Eng./Ladder Co.	Sample Type	Comments	Results
3/1/02	KAM Consultants	Eng.Co.218	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0050
3/1/02	KAM Consultants	Eng.Co. 271	Asbestos/Fiberglass/Silica	Inside Crew Cabin (Spare apparatus Mp8917)	<0.0049
3/1/02	KAM Consultants	Mobile Comm.Ctr	Asbestos/Fiberglass/Silica	Driver Cabin	<0.0049
3/1/02	KAM Consultants	Mobile Comm.Ctr	Asbestos/Fiberglass/Silica	Operations Area-Center Reg.# FT9502	<0.0049
3/2/02	KAM Consultants	Batt.#38	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/2/02	KAM Consultants	Eng.Co.238	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/2/02	KAM Consultants	Batt.#41	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/2/02	KAM Consultants	Batt.#39	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/2/02	KAM Consultants	Batt.#42	Asbestos/Fiberglass/Silica	Inside Truck Cabin	<0.0048
3/2/02	KAM Consultants	Batt.#31	Asbestos/Fiberglass/Silica	Inside Cabin	<0.0049
3/2/02	KAM Consultants	Batt.#40	Asbestos/Fiberglass/Silica	Inside Truck Cabin	<0.0049
3/2/02	KAM Consultants	Batt.#32	Asbestos/Fiberglass/Silica	Inside Truck Cabin	<0.0048
3/3/02	KAM Consultants	Eng.Co. 312	Asbestos/Fiberglass/Silica	Sattelite 4	<0.0049
3/3/02	KAM Consultants	Eng.Co. 325	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/3/02	KAM Consultants	Eng.Co.156	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/3/02	KAM Consultants	Eng.Co. 152	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/3/02	KAM Consultants	Rescue Co.5	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/3/02	KAM Consultants	Ladder Co.163	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/3/02	KAM Consultants	Ladder Co.84	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/3/02	KAM Consultants	Eng.Co.164	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/3/02	KAM Consultants	Eng.Co.307	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/3/02	KAM Consultants	Eng.Co.324	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/3/02	KAM Consultants	Eng.Co.159	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/3/02	KAM Consultants	Sattelite 5	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/4/02	KAM Consultants	Batt.#46	Asbestos/Fiberglass/Silica	Inside Truck Cabin	<0.0049
3/4/02	KAM Consultants	Eng.Co. 305	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/5/02	KAM Consultants	Eng.Co.59	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/5/02	KAM Consultants	Eng.Co.84	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/5/02	KAM Consultants	Batt.#49	Asbestos/Fiberglass/Silica	Inside Truck Cabin	<0.0049
3/8/02	KAM Consultants	Ladder 58	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/8/02	KAM Consultants	Batt.#26	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/8/02	KAM Consultants	Squadron #61	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/10/02	KAM Consultants	Rescue Co.#4	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/10/02	KAM Consultants	Eng.Co.#251	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049
3/10/02	KAM Consultants	Eng.Co.#93	Asbestos/Fiberglass/Silica	Inside Crew Cabin	<0.0049