

Some
Duplicate
Copies

595-4544

Sunday September 16: 6 AM Report from HazMat Mobile Lab

- **Results of Air Testing:**
 1. Murray/Church = .022 fibers/cc NW corner
 2. Fulton/Church = .034 SW corner
 3. Liberty/Church - replaced w/ B'way / Liberty .0082
 4. Trinity/Cedar - replaced with B'way/Cedar = .033
 5. Church/Dey - danger zone
 6. Park Place/Greenwich - .076
 7. Greenwich/Murray - .031
 8. Murray bet. Church and B'way = .0124
 9. Fulton bet. Church and B'way = .035
 10. B'way and Murray .045
 11. Vesey bet Church and West B'way = .035

(10 & 11 represent 2 additional sites)

- **Update on HEPA Vacuuming of Financial District:**

Clean-up continued through the night at financial district and Wall Street area. There is a problem vacuuming to the west of B'way, the noise created by the machine interfered with the rescuers activities. A Deputy Inspector from the Police Department halted activity west of Broadway.

EPA contractors will begin clean-up of City Hall Park and Park Row sidewalks at 7AM this morning.

- **Derelict Vehicle Update:**

Thus far, all derelict and towed vehicles have been moved to 2 locations:

1. Pier 76 (between 34 & 35 Streets)
2. Market Slip (under FDR). (Total of 50 Vehicles at both sites)

EPA will HEPA vac dirt and debris at these two sites.

Another site to be established on the south side of the Hot Zone for vehicles that are to be taken out of the hot spot (Washington & Carlyle this not yet confirmed).

Legal Issues have arisen regarding the contractors liability regarding the cleaning of debris ridden vehicles. Mark Hoffer and Charles Sturcken have been consulted and are attempting to work out the details.

- **Freon Update:** EPA took airbag sample from shaft and used HazMat's equipment in the mobile lab to test the sample. They were testing specifically for Freon R22 and the results were zero.

596-4544

Sunday September 16: 6 AM Report from HazMat Mobile Lab

- **Results of Air Testing:**
 1. Murray/Church = .022 fibers/cc NW corner
 2. Fulton/Church = .034 SW corner
 3. Liberty/Church - replaced w/ B'way / Liberty .0082
 4. Trinity/Cedar - replaced with B'way/Cedar = .033
 5. Church/Dey - danger zone
 6. Park Place/Greenwich - .076
 7. Greenwich/Murray - .031
 8. Murray bet. Church and B'way = .0124
 9. Fulton bet. Church and B'way = .035
 10. B'way and Murray .045
 11. Vesey bet Church and West B'way = .035

(10 & 11 represent 2 additional sites)

- **Update on HEPA Vacuuming of Financial District:**

Clean-up continued through the night at financial district and Wall Street area. There is a problem vacuuming to the west of B'way, the noise created by the machine interfered with the rescuers activities. A Deputy Inspector from the Police Department halted activity west of Broadway.

EPA contractors will begin clean-up of City Hall Park and Park Row sidewalks at 7AM this morning.

- **Derelict Vehicle Update:**

Thus far, all derelict and towed vehicles have been moved to 2 locations:

1. Pier 76 (between 34 & 35 Streets)
2. Market Slip (under FDR). (Total of 50 Vehicles at both sites)

EPA will HEPA vac dirt and debris at these two sites.

Another site to be established on the south side of the Hot Zone for vehicles that are to be taken out of the hot spot (**Washington & Carlyle this not yet confirmed**).

Legal Issues have arisen regarding the contractors liability regarding the cleaning of debris ridden vehicles. Mark Hoffer and Charles Sturcken have been consulted and are attempting to work out the details.

- **Freon Update:** EPA took airbag sample from shaft and used HazMat's equipment in the mobile lab to test the sample. They were testing specifically for Freon R22 and the results were zero.