

Tenant Copy
Do Not Remove from Office

er 17, 2001

**Annual Assessment, Bulk Sampling &
Air Monitoring Report:**

Gateway Plaza Project: 365 South End Avenue
Building #300

Prepared For:

Gateway Plaza Management Corporation
375 South End Avenue
New York, New York 10280

Prepared By:

ALC Environmental Incorporated
115 West 30th Street, 11th Floor
New York, New York 10001

**ENVIRONMENTAL
INCORPORATED**

The First Choice for Environmental Testing & Consulting
02949

CITY_21MC100_008873481

1.0 Introduction

October 17, 2001

Gateway Plaza Management Corporation
375 South End Avenue
New York, New York 10280

Subject: Gateway Plaza Building #300

Gentlemen:

ALC Environmental Incorporated (ALC) has been contracted by to perform visual assessments, bulk sampling, and air sampling to identify any asbestos contaminant at the above referenced building. ALC performed sampling according to the EPA Guidelines for asbestos bulk sampling and air sampling. The inspections were conducted in this building on September 23, October 5 & 12, 2001.

ALC worked under the guidance provided by the EPA guidelines for asbestos-"Asbestos in Buildings: Simplify Sampling Scheme for Friable Surfacing Materials." and the direction of the Department of Environmental Protection (DEP) to perform the bulk sample collection and analysis. Additionally, ALC provided on site Third Party Air Monitoring and Project Management, which included performing area air sampling on each floor of the building, supervising the clean-up activities in specific apartments where minimal asbestos was found-even though further analysis at a second laboratory showed the results to be below the permissible limits-, performing quality assurance inspections and monitoring the work practices of the Asbestos Abatement Contractor. Air Sampling was conducted in accordance with Federal State and Local regulations including New York City Department of Environmental Protection (NYC-DEP) Title 15, Chapter 1, Asbestos Control Program Subchapter D, "Air and Bulk Sampling, Monitoring and Analysis: and New York State Department of Labor Industrial Code Rule 56 (NYS-DOL ICR56) Section 56-17 "Air Sampling, Monitoring and Analysis."

ALC is licensed to perform asbestos activities by the State of New York Department of Labor (License # 00-0353). ALC employs only certified asbestos personnel to perform required tasks. The following personnel were used to perform asbestos air monitoring and/or asbestos inspections.

Project Manager Inspector/Project Monitor/Sampling Technician:

Americo Rodriguez Jr. (License #AH 89-07160)


Inspector:

Alvin R. Blake (License #AH 00-08397)

ATC Associates 104 East 25th Street New York, New York analyzed all samples. Further analysis was performed by SciLab 117 East 30th Street New York, New York.

If you have any questions or comments please do not hesitate to contact us directly at 212-279-1001.

Sincerely,


Joshua Sarett

ALC Environmental Incorporated

2.0 Executive Summary

ALC Environmental Incorporated (ALC) has been retained to perform bulk sampling, visual assessments & air monitoring according to the *EPA Protocol* to determine the presence of asbestos at the above referenced project. Every apartment in the building was assessed by our inspectors for dust and debris. Any area where visible dust and debris was found, ALC's inspectors took a sample, which was then sent to a third party independent laboratory for analysis. In most cases there was insufficient debris to sample and a visual assessment only was performed. **All samples analyzed were found to be below the permissible limits for asbestos.**

ALC then collected TEM samples on every floor in the building. The air sampling and analysis was done utilizing applicable Federal, State and City Regulations pertaining to asbestos to include Federal OSHA (29 CFR 1926.58) EPA NESHAPS (40 CFR PART 61), AND TSCA TITLE II AHERA/ASHARA (40 CFR PART 763) Asbestos Regulations; the New York State Department of Labor Industrial Code Rule 56 and the New York City Department of Environmental Protection Title 15 Asbestos Regulations.

The air samples were collected by Americo Rodriguez Jr., a licensed project monitor (AH# 89-07160). The visual assessment and bulk samples were collected by, A.R. Blake a NY State Asbestos Inspector (AH#00-08397) and Americo Rodriguez, a NY State Asbestos Inspector (AH#89-07160).

ATC Associates (ELAP #10879) analyzed the samples using the Transmission Electron Microscopy (TEM) Methodology. **The results indicated that the living areas achieved the acceptance criteria below <70 structures per mm² set by the above regulations.**

3.0 Definitions

Air Sampling: Process of measuring the fiber content of a known volume of air collected during a specific period. The procedure utilized for asbestos follows the NIOSH Standard Analytical Method 7400, or the provisional transmission electron microscopy methods developed by the US EPA which are utilized for lower detection levels and specific fiber identification.

Asbestos: Any hydrated mineral silicate separable into commercially usable fibers, including but not limited to chrysotile (serpentine), amosite (cummingtonite-grunerite), crocidolite (riebeckite), tremolite, anthophyllite and actinolite.

Asbestos-Containing Material (ACM): Asbestos or any material containing more than one-percent asbestos.

Clearance Air Monitoring: Employment of aggressive sampling techniques with a volume of air collected to determine the airborne concentration of residual fibers and shall be performed as the final abatement activity.

ELAP: Environmental Laboratory Approval Program administered by the New York State Department of Health.

EPA or USEPA: United States Environmental Protection Agency.

Homogeneous Work Area: Portion of the Work Area that contains one type of ACM and/or where one type of abatement is used.

Phase Contrast Microscopy: "PCM" shall mean the measurement protocol for the assessment for the fiber content of air. For PCM analysis, the clearance air monitoring shall be considered satisfactory when every sample is less than or equal to 0.01 f/cc or the background concentrations, whichever is greater.

Polarized Light Microscopy: "PLM" shall mean the measurement protocol for the assessment for the asbestos content of bulk materials. For PLM analysis, the New York City and EPA Regulatory limit is 1.0%.

Transmission Electron Microscopy: "TEM" shall mean the measurement protocol for the assessment for the asbestos fiber content of air. For TEM analysis, the clearance air monitoring shall be considered satisfactory when the requirements stated in 40 CFR Part 763, Subpart E, Appendix A, Section IV are met. For the purposes of our testing the regulatory limit is 70 asbestos structures per mm².

4.0 Scope of Work

4.1 Bulk Sampling Procedures

ALC's licensed technicians worked under the guidance provided by the EPA guidelines for asbestos-"Asbestos in Buildings: Simplify Sampling Scheme for Friable Surfacing Materials." This sampling procedure uses random sampling to ensure that the samples are representative of the sampling area. ALC's inspectors:

1. Identified all friable surfacing materials and grouped them into homogenous sampling areas by floor
2. Prepared diagrams of each sampling area
3. Determine the number of samples to collect (9 samples per homogenous areas are recommended) Determine sampling locations
4. Collect samples
5. Fill out chain of custody
6. Send samples to a qualified laboratory

Due to the insufficient amount of dust and debris in the apartment units and public areas of the building, we were unable to collect the optimum number of samples suggested in the above referenced guidelines.

With the guidance of the above referenced document and NYCDEP we went to each floor and assessed each apartment on each floor for visible dust and debris. Upon completion of the initial assessment and bulk sample collection, ALC determined that there were no elevated asbestos levels present above the guidelines in any of the apartments where samples were taken.

If any dust and/or debris was found in the apartment we collected a bulk sample and sent it to the laboratory for analysis.

If no sample could be taken due to insufficient material present at the time we were in the apartment, the inspector documented this on the log.

4.2 Air Sampling Procedures

ALC's licensed technicians collected air samples using TEM Methodology. The technician collected five (5) air samples on each floor. The samples were taken in three (3) apartments and at two separate areas in the hallways on each floor. The technician identified the locations that appeared to contain the most visible dust and debris to perform sampling.

The air samples were collected using high volume air sampling pumps. Once the pumps were in place the air sampling technician recorded the location, time, date, sample numbers, pump number, flow rate, start and stop times and his initials.

The air cassette was independent of the pump motor. This is to prevent the vibrations of the motor from affecting the fibers in the cassette. A separate stand or tripod was used to hold the cassette in place. The cassette was angled 45 degrees downward from the horizontal stand. This is to insure that no asbestos will drop into the cassette while sampling.

Using a rotameter, we calibrated each pump to the required flow rate, noting this rate on the sample record. After calibrating the pumps, the end cap from the cassette was removed; the pump was turned on and run for the required amount of time.

The sampling pumps were checked periodically to ensure they were still operating, the cassettes were still in place, and no one has disturbed the equipment. If at any time the area being sampled was suspected of having high fiber counts, the filter inside the cassettes were examined for "overloading", or an excessive amount of fibers and/or debris on the filter.

When the pre-determined volume of air has been collected, the technician then calibrated the sampling pump again to determine the current flow rate. This rate will often be different from the flow rate measured at the beginning of the sampling period. That difference is usually due to the clogging of the filter, thereby adding increased resistance to the flow of air.

Once the pre-determined volume of air has been reached, the time was recorded as well as on the cassette. Before the pump was turned off, the cassette was angled upward and the cap replaced and the end plug. The cassettes were placed in sealed containers, labeled with an identifying code and a sample log was kept. The samples were then submitted to the laboratory to be analyzed for asbestos content. A chain of custody record was prepared and accompanied the samples to the laboratory.

4.3. Asbestos Analysis and Methodology

Each air sample is cross-referenced by field designation and lab internal code to ensure proper, consistent handling through a chain of custody. Sample preparation takes place within a HEPA Filter clean bench to avoid any possible contamination. Air sampling was conducted at a level approximating the breathing zone of persons anticipated to be present in the area during normal operations. Samples collected represent the typical airborne fiber concentration of the area.

5. Findings and Conclusions

Twelve (12) initial background air samples were collected and analyzed via phase contrast microscopy (PCM) at building 300. Seven (7) samples were analyzed via Transmission Electron Microscopy (TEM). After analysis via TEM, all were below the permissible limits.

Based on EPA Guidelines, we collected six (6) bulk samples and analyzed them via Polarized Light Microscopy (PLM) Methodology. Zero (0) were found to be above the regulatory limits.

Thirty (30) air samples were collected and analyzed via TEM Methodology. The results indicated that the living areas achieved the acceptance criteria below <70 structures per mm² set by the above regulations.

6. Limitations and Exclusions

All the professional opinions presented in this report are based solely on the scope of work conducted and sources referred to in our report. The data presented by ALC in this report was collected and analyzed using generally accepted industry methods and practices at the time the report was generated. This report represents the conditions, locations, and materials that were observed at the time the fieldwork was conducted. No inferences regarding other conditions, locations, or materials, at a later or earlier time may be made based on the contents of the report. No other warranty, express or limited is made. ALC's liability and that of its contractors and subcontractors, arising from any services rendered hereunder, shall not exceed the total fee paid by the client to ALC for this project. This report was prepared for the sole use of our client. The use of this report by anyone other than our client or ALC is strictly prohibited without the expressed written consent of ALC. Portions of this report may not be used independent of the entire report.

ASSOCIATES INC

September 26, 2001

Environmental
104 W. 30th Street
New York, NY 10001
Attn: Mr.

Re: Report of TEM Analysis

Dear Mr.:

Following are the results of transmission electron microscopy (TEM) analysis of thirteen PCM air samples from our Group No. 5557:

Client: Mid-State
Project Name: 175 and 185 Southend Avenue
Location: Railways, Buildings 200 and 300
Samples received in TEM Lab: 09/26/01

These results will confirm and document the data transmitted to you today. The analyses were performed in strict conformance with the methodology of the NIOSH method 7402, Issue 2, August 19, 1994.

Forty grid openings from each of the samples were examined at relatively low magnifications (approximately 1,000X and 10,000X) for structures greater than 5um in length and widths between 0.25um and 3um, and having a length-to-width ratio greater than 1:1. These structures would be large enough to be observed by PCM analysis. Asbestos and non-asbestos structures were detected in the samples in the following proportions.

sample number	chrysotile	gypsum	cellulose	F/CC as Asbestos
1	14.3%	85.7%	0.0%	0.002
3	8.8%	55.9%	35.3%	0.001
5	0.0%	100.0%	0.0%	0.0
6	0.0%	61.1%	38.9%	0.0
8	0.0%	100.0%	0.0%	0.0
9	5.8%	94.2%	0.0%	0.001
10	0.0%	30.4%	69.6%	0.0
11	0.0%	83.3%	16.7%	0.0
12	0.0%	27.5%	62.5%	0.0
13	11.8%	60.8%	27.4%	0.002
14	0.0%	100.0%	0.0%	0.0
16	0.0%	100.0%	0.0%	0.0
18	0.0%	75.0%	25.0%	0.0



www.atc-enviro.com
212.353.8280
Fax 212.353.8308

As a consequence, no result exceeds 0.01 F/CM as requested

The analyses were supervised by Dr. Michael A. Gorycki, Director of Electron Microscopy. These analyses were performed by ATC d/b/a ATC Associates Inc. This report may be reproduced only in its entirety and not without prior permission of this laboratory

We are pleased to note that our TEM lab has received full accreditation from NVLAP and also approval under the NY State DOH ELAP program, as is currently required for recognized analysis of TEM air samples for AHERA projects

Please contact me regarding any questions relating to these materials.

Very truly yours,

Michael A. Gorycki, Ph.D
Director of Electron Microscopy

The First Choice for Environmental Testing & Consulting

ENVIRONMENTAL
INDUSTRIES

Sampled By: Mid-State Date: 12/27/01 Project # 4-00

Work Area: 355 Southern Ave. Bldg. 300 - Hallways Rotometer # 4-0

Sample #	Lab #	Sample Location	Code	Time		Total Minutes	Flow Rate		Total Volume	# Pileups / 100 Pileups	Results (U/c)
				Start	Stop		Start	Stop			
1		35th fl. Hallway - North	4	10:00	11:00	60	10.0	10.0	600	14/100	0.011
2		35th fl. Hallway - Middle	4	10:01	11:01	60	10.0	10.0	600	11/100	0.009
3		35th fl. Hallway - South	4	10:02	11:02	60	10.0	10.0	600	14/100	0.013
4		30th fl. Hallway - North	4	11:30	12:30	60	10.0	10.0	600	11/100	0.009
5		30th fl. Hallway - Middle	4	11:31	12:31	60	10.0	10.0	600	20/100	0.016
6		30th fl. Hallway - South	4	11:32	12:32	60	10.0	10.0	600	17/100	0.014
7		Bldg. 300, Hallway - North, 7th fl.	4	13:00	14:00	60	10.0	10.0	600	11/100	0.009
8		Bldg. 300, Hallway - Middle, 7th fl.	4	13:01	14:01	60	10.0	10.0	600	17/100	0.014

Analysis: ☐ TMA ☐ TMA ☐ TMA

Relinquished: Black Date/Time: 12/27/01 01:00

Analyst: E. Black Date/Time: 12/27/01 10:30

115 West 30th Street • 11th Floor • New York, New York 10001 • Tel: 212 279 1000 • Fax: 212 279 6347

Home Office: The Bellevue • Suite 600 • 200 S. Broad Street • Philadelphia, PA 19102 • Tel: 215 732 1419 • Fax: 215 732 9559

The First Choice for Environmental Testing & Consulting



Client: Mid State Date: 9-23-00 Project #: 9-23-00

Sampled By: At-End/Calder Jr. Rotometer #: 300 - Hallways Cassette: 28501

Work Area: 365 S. Second Ave., Bldg. 300 - Hallways

Sample #	Lab #	Sample Location	Code	Time		Total Minutes	Flow Rate		Total Volume	# Filters /100 Plates	Residue (Dec)
				Start	Stop		Start	Stop			
(9)		Bldg. 300, Hallway - South, 7th fl.	4	13:08	14:02	60	0.0	10.0	600	13/100	0.011
(10)		Bldg. 300, Hallway - North, 5th fl.	4	14:30	15:30	60	0.0	10.0	600	14/100	0.011
(11)		Bldg. 300, Hallway - Middle, 5th fl.	4	14:31	15:31	60	0.0	10.0	600	10/100	0.016
(12)		Bldg. 300, Hallway - South, 5th fl.	4	14:31	15:32	60	0.0	10.0	600	14/100	0.011
(13)		Bldg. 300, Hallway - North, 2nd fl.	4	16:00	17:00	60	0.0	10.0	600	21/100	0.017
(14)		Bldg. 300, Hallway - Middle, 2nd fl.	4	16:01	17:01	60	0.0	10.0	600	31/100	0.025
15		Bldg. 300, Hallway - South, 2nd fl.	4	16:02	17:02	60	0.0	10.0	600	11/100	0.009
(16)		Bldg. 300, Hallway - North, 2nd fl.	4	17:20	18:20	60	0.0	10.0	600	18/100	0.015

☐ TIM AIRMETER
☐ TIM AIRMETER
☐ TIM AIRMETER
☐ TIM AIRMETER

1. Pre-Test
 2. Project
 3. Final
 4. Investigative
 5. Personal
 6. Job, etc.

A. Aggressive
 B. Normal
 C. Turnaround
 D. Turnaround
 E. Turnaround
 F. Turnaround
 G. Turnaround
 H. Turnaround
 I. Turnaround
 J. Turnaround
 K. Turnaround
 L. Turnaround
 M. Turnaround
 N. Turnaround
 O. Turnaround
 P. Turnaround
 Q. Turnaround
 R. Turnaround
 S. Turnaround
 T. Turnaround
 U. Turnaround
 V. Turnaround
 W. Turnaround
 X. Turnaround
 Y. Turnaround
 Z. Turnaround

1. Inside Work Area
 2. Outside Work Area
 3. Inside Work Area
 4. Outside Work Area
 5. Inside Work Area
 6. Outside Work Area
 7. Inside Work Area
 8. Outside Work Area
 9. Inside Work Area
 10. Outside Work Area
 11. Inside Work Area
 12. Outside Work Area
 13. Inside Work Area
 14. Outside Work Area
 15. Inside Work Area
 16. Outside Work Area
 17. Inside Work Area
 18. Outside Work Area
 19. Inside Work Area
 20. Outside Work Area
 21. Inside Work Area
 22. Outside Work Area
 23. Inside Work Area
 24. Outside Work Area
 25. Inside Work Area
 26. Outside Work Area
 27. Inside Work Area
 28. Outside Work Area
 29. Inside Work Area
 30. Outside Work Area
 31. Inside Work Area
 32. Outside Work Area
 33. Inside Work Area
 34. Outside Work Area
 35. Inside Work Area
 36. Outside Work Area
 37. Inside Work Area
 38. Outside Work Area
 39. Inside Work Area
 40. Outside Work Area
 41. Inside Work Area
 42. Outside Work Area
 43. Inside Work Area
 44. Outside Work Area
 45. Inside Work Area
 46. Outside Work Area
 47. Inside Work Area
 48. Outside Work Area
 49. Inside Work Area
 50. Outside Work Area
 51. Inside Work Area
 52. Outside Work Area
 53. Inside Work Area
 54. Outside Work Area
 55. Inside Work Area
 56. Outside Work Area
 57. Inside Work Area
 58. Outside Work Area
 59. Inside Work Area
 60. Outside Work Area
 61. Inside Work Area
 62. Outside Work Area
 63. Inside Work Area
 64. Outside Work Area
 65. Inside Work Area
 66. Outside Work Area
 67. Inside Work Area
 68. Outside Work Area
 69. Inside Work Area
 70. Outside Work Area
 71. Inside Work Area
 72. Outside Work Area
 73. Inside Work Area
 74. Outside Work Area
 75. Inside Work Area
 76. Outside Work Area
 77. Inside Work Area
 78. Outside Work Area
 79. Inside Work Area
 80. Outside Work Area
 81. Inside Work Area
 82. Outside Work Area
 83. Inside Work Area
 84. Outside Work Area
 85. Inside Work Area
 86. Outside Work Area
 87. Inside Work Area
 88. Outside Work Area
 89. Inside Work Area
 90. Outside Work Area
 91. Inside Work Area
 92. Outside Work Area
 93. Inside Work Area
 94. Outside Work Area
 95. Inside Work Area
 96. Outside Work Area
 97. Inside Work Area
 98. Outside Work Area
 99. Inside Work Area
 100. Outside Work Area

Received At: 9/26/00 Date: 9/26/00
 Disposed By: TEA Date: 9/26/00
 Disposed At: TEA Date: 9/26/00

115 West 30th Street • 14th Floor • New York, New York 10001 • 212 239 1001 • 212 239 1001 • Fax 212 239 6747
 Home Office: The Bellevue • Suite 600 • 200 S. Broad Street • Philadelphia, PA 19102 • 215 331 9900 • 215 331 9900 • Fax 215 331 9550

Batch #6379

Client: <u>Mid State</u>		Asbestos Air San		mg Data Form		Date: <u>9-27-01</u>		Project #: <u>09880-2010-1712</u>			
Sampled By: <u>AC/RO/AB</u>		Rotameter #: <u>10</u>		Flow Rate		Total		# Fibers /100 Ft/Min		Results (f/cc)	
Work Area: <u>365 Southern Ave Bldg. 300 - Various Areas</u>		Code		Time		Total Minutes		Start		Stop	
Sample #	Sample Location	Code	Start	Stop	Minutes	Start	Stop	Volume	Fibers /100 Ft/Min	Results (f/cc)	
9	Appt #2D - Living Rm	4	1502	1602	60	10.0	10.0	600	6/100	<0.008	
10	Bldg. 300, Apt #1F - Living Rm.	4	1615	1715	60	10.0	10.0	600	4/100	<0.008	
11	Bldg. 300, Apt #1G - Living Rm.	4	1616	1716	60	10.0	10.0	600	7/100	<0.008	
12	Bldg. 300, Apt #1C - Living Rm.	4	1617	1717	60	10.0	10.0	600	10/100	0.008	
13	Field Blank								0/100	-	
14									0/100	-	

Codes	1. Pre-Test	2. Project	3. Final	4. Investigative	5. Personal	6. J/L/C	A. Aggressive	D. Dormant	1. Inside Work Area	2. Outside Work Area	E. Excavation	F. TWA
Analysis	☐ TEM/ASTM	☐ TEM/ASTM/EDS	☐ TEM/ASTM/EDS	☐ TEM/ASTM/EDS	☐ TEM/ASTM/EDS	☐ TEM/ASTM/EDS	☐ ASAP	☐ 2 Day (48hr)	☐ ASAP	☐ 2 Day (48hr)	☐ Same Day (12hr)	☐
Relinquished Analyst	<u>Jeffrey J. Walker</u> Date/Time <u>09/27/01 18:45</u>											
Received	<u>ATC LAB / 09/27/01 18:45</u> Date/Time <u>09/27/01 18:45</u>											

115 West 30th Street • 11th Floor • New York, New York 10001 • 212 279,1001 • 888.466.3630 • Fax: 212 279.6747
 (House Office: The Bellvue • Suite 600 • 200 S. Broad Street • Philadelphia, PA 19102 • 215 732 9499 • 888 789 8378 • Fax: 215 732 9559)

Appendix A: Letter to Tenants for Re-Occupation

02961

CITY_21MC100_008873493



The First Choice for Environmental Testing & Consulting

October 17, 2001

Gateway Plaza Management Corporation
375 South End Avenue
New York, New York 10280

Subject: Gateway Plaza Building #300

Gentlemen:

ALC Environmental Incorporated (ALC) has been retained to perform bulk sampling, visual assessments & air monitoring according to the *EPA Protocol* to determine the presence of asbestos at the above referenced project. Every apartment in the building was assessed by our inspectors for dust and debris. Any area where visible dust and debris was found, ALC's inspectors took a bulk sample, which was then sent to a third party independent laboratory for analysis. In most cases there was insufficient debris to sample and a visual assessment only was performed. Additionally, air sampling was performed using TEM Methodology on every floor in the building.

Twelve (12) initial background air samples were collected and analyzed via phase contrast microscopy (PCM) at building 300. Seven (7) samples were analyzed via Transmission Electron Microscopy (TEM). After analysis via TEM, all were below the permissible limits.

Based on EPA Guidelines, we collected six (6) bulk samples and analyzed them via Polarized Light Microscopy (PLM) Methodology. Zero (0) were found to be above the regulatory limits.

ALC then collected air samples on every floor in the building. The air sampling and analysis was done utilizing applicable Federal, State and City Regulations pertaining to asbestos to include Federal OSHA (29 CFR 1926.58) EPA NESHAPS (40 CFR PART 61), AND TSCA TITLE II AHERA/ASHARA (40 CFR PART 763) Asbestos Regulations; the New York State Department of Labor Industrial Code Rule 56 and the New York City Department of Environmental Protection Title 15 Asbestos Regulations.

Thirty (30) air samples were collected and analyzed via TEM Methodology. The results indicated that the living areas achieved the acceptance criteria below <70 structures per mm² set by the above regulations.

West 30th Street • 11th Floor • New York, New York 10001 • 212.279.1001 • 888.466.3620 • Fax: 212.279.6747

Office: The Bellevue • Suite 600 • 200 S. Broad Street • Philadelphia, PA 19102 • 215.732.9499 • 888.789.8378 • Fax: 215.732.9559

www.ALCEnvironmental.com


CITY_21MC100_008873494

ATC Associates (ELAP #10879) analyzed the samples using the Phase Contrast Microscopy (PCM), Polar Light Microscopy (PLM) Methodology and the Transmission Electron Microscopy (TEM) Methodology.

The air samples were collected by licensed technicians.

Tenants may re-occupy their apartments at the present time.

Sincerely,



Joshua Sarett
ALC Environmental Incorporated