

P.T.&L. Environmental Services

411 Sette Drive, Paramus, New Jersey 07652-2912 • 201-262-4141

Air Sample Record & Chain of Custody

For NIOSH Methodologies

ASBESTOS AREA

Lab. No.	Building	Monitored	Pump	Initial Flow	Mean	Time On	Total	Total	Sample
Sample No.	Work Area	Activity	No.	Final Flow	Flow	Time Off	Time	Volume	Results
				(L/Min.)	(L/Min.)	(24-hr)	(Min)	(L)	(ug/mg3)
0061	CORNER of GREENWICH & MURRAY	N/A		6 5.8	5.9	7:45 13:20	335	2010	
0062	Sign out TRAILER	N/A		6 6	6	7:47 13:22	335	2010	
0063	Middle TRAILER	N/A		6 6	6	7:49 13:24	335	2010	
0064	CORNER of GREENWICH & MURRAY	N/A		6 5.8	5.9	13:20 18:30	310	1829	
0065	Sign out TRAILER	N/A		6 6	6	13:22 18:32	310	1860	
0066	Middle TRAILER	N/A		6 5.7	5.85	13:24 18:34	310	1813	
0067	Field BLANK	N/A		— —	—	— —	—	—	ND
0068	Field BLANK	N/A		— —	—	— —	—	—	ND
129350									
129351									

01-15001

129352 e: Asbestos / Fibers by PCM Total No. of Samples: 8 Job Number: PC-17781

NI 129353 r: NYC Area Samples Turnaround Time: 18 hours Std. = 72 hrs. Job Name: WTC 5, 6, 7

M 129354 a: <1.2um, 25mm, CE Calibration Method: Rotometer 01-HF Job Location: MURRAY and GREENWICH

I 129354 D: 5 (10 - if glovebag or tent) Technician D. Whimich

F 129355 Q: 15 Laboratory Name: EAS

129355 L: 560 (1,800 - if clearance) Laboratory Address: 4 Westchester Plaza Work Area: #2

129356 J: n/s Elmsford, NY 10523-1610 Contractor: SEASON 5

129357 d: n/s (2 to 10 per set) Laboratory Telephone: (914) 592-8380 Date: 9-24-01

M 129357 I: n/s (2 per batch) Laboratory Fax: (914) 592-8956 Page 1 of 1

Bulk Sample required? Yes / No

Relinquished By		Received By		Organization or Affiliation	Date of Transfer	Time of Transfer	Reason for Transfer
Print	Sign	Print	Sign				
			<i>A. F. and 4/28/01</i>				

Fax results promptly to the attention of _____ at (201) 262-6778 or _____

C:\APPS\OFFICE\NIST\FRM\SAS2\COCC.XLS

06.003966

CITY_21MC100_006788251