



Customer Focused Solutions

1430 Broadway, 10th Fl. New York, New York 10018

Phone: (212) 221-7822 - Fax: (212) 221-7840

Airborne Asbestos Fiber Analysis
by Transmission Electron Microscopy

Client Lower Manhattan Development Corporation
Address One Liberty Plaza, 20th Floor
New York, NY 10006
Collected By V. BajomoK. DaRocha
Collected 05/30/2005
Rotometer Standard

Job Number 46600-0000-00001
Date Received 5/30/2005
Date Analyzed 6/1/2005
Job Location 130 Liberty Street

Lab ID Field ID	Sample Location	Start/ Stop	Flow	Volume (liters)	Asbestos Type(s)	Asbestos Structures		Non- Asbestos	Analytical Sensitivity (AS/cc)	Asbestos Concentration (AS/cc)	Asbestos Concentration (AS/mm2)
						≥ .5mm <5mm	≥ 5mm				
030514736-0001 T-053005-2240	WASHINGTON STREET/ ALBANY STREET	00:01 08:01	4	1920	None Detected	0	0	0	0.0042	<0.0042	<21.00
030514736-0002 T-053005-2241	ALBANY STREET/ GREENWICH STREET	00:04 08:04	3.9	1872	None Detected	0	0	0	0.0043	<0.0043	<21.00
030514736-0003 T-053005-2242	GREENWICH STREET	00:07 08:07	4	1920	None Detected	0	0	0	0.0042	<0.0042	<21.00
030514736-0004 T-053005-2243	GREENWICH STREET/ LIBERTY STREET	00:09 08:09	3.95	1896	None Detected	0	0	0	0.0042	<0.0042	<21.00
030514736-0005 T-053005-2244	WASHINGTON STREET/ CEDAR STREET	00:12 08:12	4	1920	None Detected	0	0	0	0.0042	<0.0042	<21.00

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 1 of 3

CITY_21MC100_003243300



1430 Broadway, 10th Fl. New York, New York 10018
Phone: (212) 221-7822 - Fax: (212) 221-7840

Airborne Asbestos Fiber Analysis
by Transmission Electron Microscopy

Client Lower Manhattan Development Corporation
Address One Liberty Plaza, 20th Floor
New York, NY 10006
Collected By V. Bajomo/O. Kuepper
Collected 05/30/2005
Rotometer Standard

Job Number 46600-0000-00001
Date Received 5/30/2005
Date Analyzed 6/1/2005
Date Analyzed 130 Liberty Street

Lab ID Field ID	Sample Location	Start/ Stop	Flow	Volume (liters)	Asbestos Type(s)	Asbestos Structures		Non- Asbestos	Analytical Sensitivity (AS/cc)	Asbestos Concentration (AS/cc)	Asbestos Concentration (AS/mm2)
						≥ .5mm <5mm	≥ 5mm				
030514737-0001 T-053005-2246	WASHINGTON STREET/ ALBANY STREET	08:01 16:00	4	1916	None Detected	0	0	0	0.0042	<0.0042	<21.00
030514737-0002 T-053005-2247	ALBANY STREET/ GREENWICH STREET	08:04 16:04	4.05	1944	None Detected	0	0	0	0.0041	<0.0041	<21.00
030514737-0003 T-053005-2248	GREENWICH STREET	08:07 16:09	4.05	1952	None Detected	0	0	0	0.0041	<0.0041	<21.00
030514737-0004 T-053005-2249	GREENWICH STREET/ LIBERTY STREET	08:09 16:13	3.95	1912	None Detected	0	0	0	0.0042	<0.0042	<21.00
030514737-0005 T-053005-2250	WASHINGTON STREET/ CEDAR STREET	08:12 16:18	4.05	1968	None Detected	0	0	0	0.0041	<0.0041	<21.00

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 2 of 3

CITY_21MC100_003243301



1430 Broadway, 10th Fl. New York, New York 10018
Phone: (212) 221-7822 - Fax: (212) 221-7840

Airborne Asbestos Fiber Analysis
by Transmission Electron Microscopy

Client Lower Manhattan Development Corporation
Address One Liberty Plaza, 20th Floor
New York, NY 10006
Collected By V. Bajomo/A. Dvorkin
Collected 05/30/2005
Rotometer Standard

Job Number 46600-0000-00001
Date Received 05/31/2005
Date Analyzed 06/01/2005
Date Analyzed 130 Liberty Street

Lab ID Field ID	Sample Location	Start/ Stop	Flow	Volume (liters)	Asbestos Type(s)	Asbestos Structures		Non- Asbestos	Analytical Sensitivity (AS/cc)	Asbestos Concentration (AS/cc)	Asbestos Concentration (AS/mm2)
						≥ .5mm <5mm	≥ 5mm				
030514855-0001 T-053005-2252	WASHINGTON STREET/ ALBANY STREET	16:02 00:03	4	1924	None Detected	0	0	0	0.0042	<0.0042	<21.00
030514855-0002 T-053005-2253	ALBANY STREET/ GREENWICH STREET	16:06 00:05	4	1916	None Detected	0	0	0	0.0042	<0.0042	<21.00
030514855-0003 T-053005-2254	GREENWICH STREET	16:11 00:09	4	1912	None Detected	0	0	0	0.0042	<0.0042	<21.00
030514855-0004 T-053005-2255	GREENWICH STREET/ LIBERTY STREET	16:15 00:12	4	1908	None Detected	0	0	0	0.0042	<0.0042	<21.00
030514855-0005 T-053005-2256	WASHINGTON STREET/ CEDAR STREET	16:20 00:15	4	1900	None Detected	0	0	0	0.0042	<0.0042	<21.00

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 3 of 3

CITY_21MC100_003243302