



Customer Focused Solutions

1430 Broadway, 10th Fl. New York, New York 10018

Phone: (212) 221-7822 - Fax: (212) 221-7840

**Airborne Asbestos Fiber Analysis
by Transmission Electron Microscopy**

Client Lower Manhattan Development Corporation
Address One Liberty Plaza, 20th Floor
New York, NY 10006
Collected By K.DaRocha/ N. Agahan
Collected 02/25/2005
Rotometer Standard

Job Number 46600-0000-00001
Date Received 2/25/2005
Date Analyzed 2/25/2005
Job Location 130 Liberty Street

Lab ID Field ID	Sample Location	Start/ Stop	Flow	Volume (liters)	Asbestos Type(s)	Asbestos Structures		Non- Asbestos	Analytical Sensitivity (AS/cc)	Asbestos Concentration (AS/cc)	Asbestos Concentration (AS/mm2)
						≥ .5mm <5mm	≥ 5mm				
030504996-0001 T-022505-548	WASHINGTON STREET/ ALBANY STREET	00:02 08:01	4	1916	None Detected	0	0	1	0.0042	<0.0042	<21.00
030504996-0002 T-022505-549	ALBANY STREET/ GREENWICH STREET	00:05 08:05	4	1920	None Detected	0	0	0	0.0042	<0.0042	<21.00
030504996-0003 T-022505-550	GREENWICH STREET	00:08 08:08	3.95	1896	None Detected	0	0	0	0.0042	<0.0042	<21.00
030504996-0004 T-022505-551	GREENWICH STREET/ LIBERTY STREET	00:11 08:10	4	1916	None Detected	0	0	1	0.0042	<0.0042	<21.00
030504996-0005 T-022505-552	WASHINGTON STREET/ CEDAR STREET	00:15 08:14	3.9	1868	None Detected	0	0	0	0.0043	<0.0043	<21.00

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 1 of 3

CITY_21MC100_003215312



1430 Broadway, 10th Fl. New York, New York 10018
Phone: (212) 221-7822 - Fax: (212) 221-7840

Airborne Asbestos Fiber Analysis
by Transmission Electron Microscopy

Client Lower Manhattan Development Corporation
Address One Liberty Plaza, 20th Floor
New York, NY 10006
Collected By K.DaRocha/ N. Agahan
Collected 02/25/2005
Rotometer Standard

Job Number 46600-0000-00001
Date Received 2/25/2005
Date Analyzed 2/25/2005
Date Analyzed 130 Liberty Street

Lab ID Field ID	Sample Location	Start/ Stop	Flow	Volume (liters)	Asbestos Type(s)	Asbestos Structures		Non- Asbestos	Analytical Sensitivity (AS/cc)	Asbestos Concentration (AS/cc)	Asbestos Concentration (AS/mm2)
						≥ .5mm <5mm	≥ 5mm				
030504997-0001 T-022505-554	WASHINGTON STREET/ ALBANY STREET	08:02 16:01	4	1916	None Detected	0	0	0	0.0042	<0.0042	<21.00
030504997-0002 T-022505-555	ALBANY STREET/ GREENWICH STREET	08:05 16:04	4	1916	None Detected	0	0	0	0.0042	<0.0042	<21.00
030504997-0003 T-022505-556	GREENWICH STREET	08:08 16:07	4	1916	None Detected	0	0	0	0.0042	<0.0042	<21.00
030504997-0004 T-022505-557	GREENWICH STREET/ LIBERTY STREET	08:11 16:10	4	1916	None Detected	0	0	0	0.0042	<0.0042	<21.00
030504997-0005 T-022505-558	WASHINGTON STREET/ CEDAR STREET	08:15 16:13	3.95	1888.1	None Detected	0	0	0	0.0042	<0.0042	<21.00

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 2 of 3

CITY_21MC100_003215313



1430 Broadway, 10th Fl. New York, New York 10018
Phone: (212) 221-7822 - Fax: (212) 221-7840

Airborne Asbestos Fiber Analysis
by Transmission Electron Microscopy

Client Lower Manhattan Development Corporation
Address One Liberty Plaza, 20th Floor
New York, NY 10006
Collected By K.DaRocha
Collected 02/25/2005
Rotometer Standard

Job Number 46600-0000-00001
Date Received 02/26/2005
Date Analyzed 02/26/2005
Date Analyzed 130 Liberty Street

Lab ID Field ID	Sample Location	Start/ Stop	Flow	Volume (liters)	Asbestos Type(s)	Asbestos Structures		Non- Asbestos	Analytical Sensitivity (AS/cc)	Asbestos Concentration (AS/cc)	Asbestos Concentration (AS/mm2)
						≥ .5mm <5mm	≥ 5mm				
030505060-0001 T-022505-560	WASHINGTON STREET/ ALBANY STREET	16:01 00:03	4	1928	None Detected	0	0	0	0.0042	<0.0042	<21.00
030505060-0002 T-022505-561	ALBANY STREET/ GREENWICH STREET	16:04 00:06	3.95	1904	None Detected	0	0	0	0.0042	<0.0042	<21.00
030505060-0003 T-022505-562	GREENWICH STREET	16:07 00:09	3.9	1880	None Detected	0	0	0	0.0043	<0.0043	<21.00
030505060-0004 T-022505-563	GREENWICH STREET/ LIBERTY STREET	16:10 00:12	4	1928	None Detected	0	0	0	0.0042	<0.0042	<21.00
030505060-0005 T-022505-564	WASHINGTON STREET/ CEDAR STREET	16:13 00:15	3.9	1880	None Detected	0	0	0	0.0043	<0.0043	<21.00

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 3 of 3