



1430 Broadway, 10th Fl. New York, New York 10018
Phone: (212) 221-7822 - Fax: (212) 221-7840

Airborne Asbestos Fiber Analysis
by Transmission Electron Microscopy

Client Lower Manhattan Development Corporation
Address One Liberty Plaza, 20th Floor
New York, NY 10006
Collected By A. Dvorkin/K. DaRocha
Collected 08/18/2005
Rotometer Standard

Job Number 46600-0000-00001
Date Received 8/18/2005
Date Analyzed 8/20/2005
Job Location 130 Liberty Street

Lab ID Field ID	Sample Location	Start/ Stop	Flow	Volume (liters)	Asbestos Type(s)	Asbestos Structures		Non- Asbestos	Analytical Sensitivity (AS/cc)	Asbestos Concentration (AS/cc)	Asbestos Concentration (AS/mm2)
						≥ .5mm <5mm	≥ 5mm				
030524468-0001 T-081805-3680	WASHINGTON STREET/ ALBANY STREET	00:02 08:00	4	1912	None Detected	0	0	0	0.0039	<0.0039	<19.00
030524468-0002 T-081805-3681	ALBANY STREET/ GREENWICH STREET	00:05 08:03	4	1912	None Detected	0	0	0	0.0039	<0.0039	<19.00
030524468-0003 T-081805-3682	GREENWICH STREET	00:07 08:06	4	1916	None Detected	0	0	0	0.0039	<0.0039	<19.00
030524468-0004 T-081805-3683	GREENWICH STREET/ LIBERTY STREET	00:10 08:10	4	1920	None Detected	0	0	0	0.0039	<0.0039	<19.00
030524468-0005 T-081805-3684	WASHINGTON STREET/ CEDAR STREET	00:12 08:12	4	1920	None Detected	0	0	0	0.0039	<0.0039	<19.00

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 1 of 3

CITY_21MC100_003215670



1430 Broadway, 10th Fl. New York, New York 10018
Phone: (212) 221-7822 - Fax: (212) 221-7840

Airborne Asbestos Fiber Analysis
by Transmission Electron Microscopy

Client Lower Manhattan Development Corporation
Address One Liberty Plaza, 20th Floor
New York, NY 10006
Collected By D. Katehis
Collected 08/18/2005
Rotometer Standard

Job Number 46600-0000-00001
Date Received 8/18/2005
Date Analyzed 8/20/2005
Date Analyzed 130 Liberty Street

Lab ID Field ID	Sample Location	Start/ Stop	Flow	Volume (liters)	Asbestos Type(s)	Asbestos Structures		Non- Asbestos	Analytical Sensitivity (AS/cc)	Asbestos Concentration (AS/cc)	Asbestos Concentration (AS/mm2)
						≥ .5mm <5mm	≥ 5mm				
030524470-0001 T-081805-3686	WASHINGTON STREET/ ALBANY STREET	08:00 16:00	4	1920	None Detected	0	0	0	0.0039	<0.0039	<19.00
030524470-0002 T-081805-3687	ALBANY STREET/ GREENWICH STREET	08:03 16:03	4	1920	None Detected	0	0	0	0.0039	<0.0039	<19.00
030524470-0003 T-081805-3688	GREENWICH STREET	08:06 16:06	4	1920	None Detected	0	0	0	0.0039	<0.0039	<19.00
030524470-0004 T-081805-3689	GREENWICH STREET/ LIBERTY STREET	08:10 16:10	4	1920	None Detected	0	0	0	0.0039	<0.0039	<19.00
030524470-0005 T-081805-3690	WASHINGTON STREET/ CEDAR STREET	08:12 16:12	4	1920	None Detected	0	0	0	0.0039	<0.0039	<19.00

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 2 of 3

CITY_21MC100_003215671



1430 Broadway, 10th Fl. New York, New York 10018
Phone: (212) 221-7822 - Fax: (212) 221-7840

Airborne Asbestos Fiber Analysis
by Transmission Electron Microscopy

Client Lower Manhattan Development Corporation
Address One Liberty Plaza, 20th Floor
New York, NY 10006
Collected By D. Katehis/A. Dvorkin
Collected 08/18/2005
Rotometer Standard

Job Number 46600-0000-00001
Date Received 08/19/2005
Date Analyzed 08/20/2005
Date Analyzed 130 Liberty Street

Lab ID Field ID	Sample Location	Start/ Stop	Flow	Volume (liters)	Asbestos Type(s)	Asbestos Structures		Non- Asbestos	Analytical Sensitivity (AS/cc)	Asbestos Concentration (AS/cc)	Asbestos Concentration (AS/mm2)
						≥ .5mm <5mm	≥ 5mm				
030524642-0001 T-081805-3692	WASHINGTON STREET/ ALBANY STREET	16:00 00:02	4	1928	None Detected	0	0	0	0.0038	<0.0038	<19.00
030524642-0002 T-081805-3693	ALBANY STREET/ GREENWICH STREET	16:03 00:05	4	1928	None Detected	0	0	0	0.0038	<0.0038	<19.00
030524642-0003 T-081805-3694	GREENWICH STREET	16:06 00:07	4	1924	None Detected	0	0	0	0.0038	<0.0038	<19.00
030524642-0004 T-081805-3695	GREENWICH STREET/ LIBERTY STREET	16:10 00:09	4	1916	None Detected	0	0	0	0.0039	<0.0039	<19.00
030524642-0005 T-081805-3696	WASHINGTON STREET/ CEDAR STREET	16:12 00:12	4	1920	None Detected	0	0	0	0.0039	<0.0039	<19.00

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 3 of 3