



Customer Focused Solutions

1430 Broadway, 10th Fl. New York, New York 10018

Phone: (212) 221-7822 - Fax: (212) 221-7840

Airborne Asbestos Fiber Analysis
by Transmission Electron Microscopy

Client Lower Manhattan Development Corporation
Address One Liberty Plaza, 20th Floor
New York, NY 10006
Collected By V. Bajomo/K. DaRocha
Collected 03/23/2005
Rotometer Standard

Job Number 46600-0000-00001
Date Received 3/23/2005
Date Analyzed 3/25/2005
Job Location 130 Liberty Street

Lab ID Field ID	Sample Location	Start/ Stop	Flow	Volume (liters)	Asbestos Type(s)	Asbestos Structures		Non- Asbestos	Analytical Sensitivity (AS/cc)	Asbestos Concentration (AS/cc)	Asbestos Concentration (AS/mm2)
						≥ .5mm <5mm	≥ 5mm				
030507750-0001 T-032305-1016	WASHINGTON STREET/ ALBANY STREET	00:01 08:02	4	1924	None Detected	0	0	0	0.0042	<0.0042	<21.00
030507750-0002 T-032305-1017	ALBANY STREET/ GREENWICH STREET	00:04 08:05	3.9	1876	None Detected	0	0	0	0.0043	<0.0043	<21.00
030507750-0003 T-032305-1018	GREENWICH STREET	00:07 08:08	4	1924	None Detected	0	0	0	0.0042	<0.0042	<21.00
030507750-0004 T-032305-1019	GREENWICH STREET/ LIBERTY STREET	00:11 08:11	4	1920	None Detected	0	0	0	0.0042	<0.0042	<21.00
030507750-0005 T-032305-1020	WASHINGTON STREET/ CEDAR STREET	00:14 08:15	4	1924	None Detected	0	0	0	0.0042	<0.0042	<21.00

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 1 of 3

CITY_21MC100_003221220



1430 Broadway, 10th Fl. New York, New York 10018
Phone: (212) 221-7822 - Fax: (212) 221-7840

Airborne Asbestos Fiber Analysis
by Transmission Electron Microscopy

Client Lower Manhattan Development Corporation
Address One Liberty Plaza, 20th Floor
New York, NY 10006
Collected By V. Bajamo/K. DaRocha
Collected 03/23/2005
Rotometer Standard

Job Number 46600-0000-00001
Date Received 3/23/2005
Date Analyzed 3/25/2005
Date Analyzed 130 Liberty Street

Lab ID Field ID	Sample Location	Start/ Stop	Flow	Volume (liters)	Asbestos Type(s)	Asbestos Structures		Non- Asbestos	Analytical Sensitivity (AS/cc)	Asbestos Concentration (AS/cc)	Asbestos Concentration (AS/mm2)
						≥ .5mm <5mm	≥ 5mm				
030507751-0001 T-032305-1022	WASHINGTON STREET/ ALBANY STREET	08:02 16:00	4	1912	None Detected	0	0	0	0.0042	<0.0042	<21.00
030507751-0002 T-032305-1023	ALBANY STREET/ GREENWICH STREET	08:05 16:03	4	1912	None Detected	0	0	0	0.0042	<0.0042	<21.00
030507751-0003 T-032305-1024	GREENWICH STREET	08:08 16:06	4	1912	None Detected	0	0	0	0.0042	<0.0042	<21.00
030507751-0004 T-032305-1025	GREENWICH STREET/ LIBERTY STREET	08:11 16:09	3.95	1888	None Detected	0	0	0	0.0042	<0.0042	<21.00
030507751-0005 T-032305-1026	WASHINGTON STREET/ CEDAR STREET	08:15 16:12	3.95	1884	None Detected	0	0	0	0.0043	<0.0043	<21.00

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 2 of 3

CITY_21MC100_003221221



1430 Broadway, 10th Fl. New York, New York 10018
Phone: (212) 221-7822 - Fax: (212) 221-7840

Airborne Asbestos Fiber Analysis
by Transmission Electron Microscopy

Client Lower Manhattan Development Corporation
Address One Liberty Plaza, 20th Floor
New York, NY 10006
Collected By K. DaRocha
Collected 03/23/2005
Rotometer Standard

Job Number 46600-0000-00001
Date Received 03/24/2005
Date Analyzed 03/25/2005
Date Analyzed 130 Liberty Street

Lab ID Field ID	Sample Location	Start/ Stop	Flow	Volume (liters)	Asbestos Type(s)	Asbestos Structures		Non- Asbestos	Analytical Sensitivity (AS/cc)	Asbestos Concentration (AS/cc)	Asbestos Concentration (AS/mm2)
						≥ .5mm <5mm	≥ 5mm				
030507869-0001 T-032305-1028	WASHINGTON STREET/ ALBANY STREET	16:00 00:00	4	1920	None Detected	0	0	0	0.0042	<0.0042	<21.00
030507869-0002 T-032305-1029	ALBANY STREET/ GREENWICH STREET	16:03 00:03	4	1920	None Detected	0	0	0	0.0042	<0.0042	<21.00
030507869-0003 T-032305-1030	GREENWICH STREET	16:06 00:06	3.9	1872	None Detected	0	0	2	0.0043	<0.0043	<21.00
030507869-0004 T-032305-1031	GREENWICH STREET/ LIBERTY STREET	16:09 00:09	4	1920	None Detected	0	0	0	0.0042	<0.0042	<21.00
030507869-0005 T-032305-1032	WASHINGTON STREET/ CEDAR STREET	16:12 00:15	3.95	1908	None Detected	0	0	5	0.0042	<0.0042	<21.00

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 3 of 3