



Customer-Focused Solutions

1430 Broadway, 10th Fl. New York, New York 10018

Phone: (212) 221-7822 - Fax: (212) 221-7840

**Airborne Asbestos Fiber Analysis
by Transmission Electron Microscopy**

Client Lower Manhattan Development Corporation
Address One Liberty Plaza, 20th Floor
New York, NY 10006
Collected By K. DaRocha/A. Dvorkin
Collected 04/26/2005
Rotometer Standard

Job Number 46600-0000-00001
Date Received 4/26/2005
Date Analyzed 4/28/2005
Job Location 130 Liberty Street

Lab ID Field ID	Sample Location	Start/ Stop	Flow	Volume (liters)	Asbestos Type(s)	Asbestos Structures		Non- Asbestos	Analytical Sensitivity (AS/cc)	Asbestos Concentration (AS/cc)	Asbestos Concentration (AS/mm2)
						≥ .5mm <5mm	≥ 5mm				
030511079-0001 T-042605-1628	WASHINGTON STREET/ ALBANY STREET	00:00 08:01	4	1924	None Detected	0	0	0	0.0042	<0.0042	<21.00
030511079-0002 T-042605-1629	ALBANY STREET/ GREENWICH STREET	00:03 08:04	4	1924	None Detected	0	0	0	0.0042	<0.0042	<21.00
030511079-0003 T-042605-1630	GREENWICH STREET	00:06 08:07	3.9	1876	None Detected	0	0	0	0.0043	<0.0043	<21.00
030511079-0004 T-042605-1631	GREENWICH STREET/ LIBERTY STREET	00:08 08:10	4	1928	None Detected	0	0	0	0.0042	<0.0042	<21.00
030511079-0005 T-042605-1632	WASHINGTON STREET/ CEDAR STREET	00:11 08:13	4	1928	None Detected	0	0	0	0.0042	<0.0042	<21.00

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 1 of 3

CITY_21MC100_003220289



1430 Broadway, 10th Fl. New York, New York 10018
Phone: (212) 221-7822 - Fax: (212) 221-7840

Airborne Asbestos Fiber Analysis
by Transmission Electron Microscopy

Client Lower Manhattan Development Corporation
Address One Liberty Plaza, 20th Floor
New York, NY 10006
Collected By A. Dvorkin/K. DaRocha
Collected 04/26/2005
Rotometer Standard

Job Number 46600-0000-00001
Date Received 4/26/2005
Date Analyzed 4/28/2005
Date Analyzed 130 Liberty Street

Lab ID Field ID	Sample Location	Start/ Stop	Flow	Volume (liters)	Asbestos Type(s)	Asbestos Structures		Non- Asbestos	Analytical Sensitivity (AS/cc)	Asbestos Concentration (AS/cc)	Asbestos Concentration (AS/mm2)
						≥ .5mm <5mm	≥ 5mm				
030511081-0001 T-042605-1634	WASHINGTON STREET/ ALBANY STREET	08:01 16:00	4	1916	None Detected	0	0	0	0.0042	<0.0042	<21.00
030511081-0002 T-042605-1635	ALBANY STREET/ GREENWICH STREET	08:04 16:03	4	1916	None Detected	0	0	0	0.0042	<0.0042	<21.00
030511081-0003 T-042605-1636	GREENWICH STREET	08:07 16:06	4	1916	None Detected	0	0	0	0.0042	<0.0042	<21.00
030511081-0004 T-042605-1637	GREENWICH STREET/ LIBERTY STREET	08:10 16:09	4	1916	None Detected	0	0	0	0.0042	<0.0042	<21.00
030511081-0005 T-042605-1638	WASHINGTON STREET/ CEDAR STREET	08:13 16:12	3.95	1892	None Detected	0	0	0	0.0042	<0.0042	<21.00

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 2 of 3

CITY_21MC100_003220290



1430 Broadway, 10th Fl. New York, New York 10018
Phone: (212) 221-7822 - Fax: (212) 221-7840

**Airborne Asbestos Fiber Analysis
by Transmission Electron Microscopy**

Client Lower Manhattan Development Corporation
Address One Liberty Plaza, 20th Floor
New York, NY 10006
Collected By K. DaRocha
Collected 04/26/2005
Rotometer Standard

Job Number 46600-0000-00001
Date Received 04/27/2005
Date Analyzed 04/28/2005
Date Analyzed 130 Liberty Street

Lab ID Field ID	Sample Location	Start/ Stop	Flow	Volume (liters)	Asbestos Type(s)	Asbestos Structures		Non- Asbestos	Analytical Sensitivity (AS/cc)	Asbestos Concentration (AS/cc)	Asbestos Concentration (AS/mm2)
						≥ .5mm <5mm	≥ 5mm				
030511233-0001 T-042605-1640	WASHINGTON STREET/ ALBANY STREET	16:00 00:01	4	1924	None Detected	0	0	0	0.0042	<0.0042	<21.00
030511233-0002 T-042605-1641	ALBANY STREET/ GREENWICH STREET	16:03 00:04	4	1924	None Detected	0	0	0	0.0042	<0.0042	<21.00
030511233-0003 T-042605-1642	GREENWICH STREET	16:06 00:07	4	1924	None Detected	0	0	0	0.0042	<0.0042	<21.00
030511233-0004 T-042605-1643	GREENWICH STREET/ LIBERTY STREET	16:09 00:11	4	1928	None Detected	0	0	0	0.0042	<0.0042	<21.00
030511233-0005 T-042605-1644	WASHINGTON STREET/ CEDAR STREET	16:12 00:15	4	1932	None Detected	0	0	0	0.0042	<0.0042	<21.00

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 3 of 3

CITY_21MC100_003220291