



Customer Focused Solutions

1430 Broadway, 10th Fl. New York, New York 10018

Phone: (212) 221-7822 - Fax: (212) 221-7840

Airborne Asbestos Fiber Analysis
by Transmission Electron Microscopy

Client Lower Manhattan Development Corporation
Address One Liberty Plaza, 20th Floor
New York, NY 10006
Collected By A. Dvorkin/V. Bajomo
Collected 05/21/2005
Rotometer Standard

Job Number 46600-0000-00001
Date Received 5/21/2005
Date Analyzed 5/23/2005
Job Location 130 Liberty Street

Lab ID Field ID	Sample Location	Start/ Stop	Flow	Volume (liters)	Asbestos Type(s)	Asbestos Structures		Non- Asbestos	Analytical Sensitivity (AS/cc)	Asbestos Concentration (AS/cc)	Asbestos Concentration (AS/mm2)
						≥ .5mm <5mm	≥ 5mm				
030513923-0001 T-052105-2078	WASHINGTON STREET/ ALBANY STREET	00:01 08:00	4	1916	None Detected	0	0	0	0.0042	<0.0042	<21.00
030513923-0002 T-052105-2079	ALBANY STREET/ GREENWICH STREET	00:04 08:03	3.9	1868	None Detected	0	0	0	0.0043	<0.0043	<21.00
030513923-0003 T-052105-2080	GREENWICH STREET	00:08 08:07	4	1916	None Detected	0	0	0	0.0042	<0.0042	<21.00
030513923-0004 T-052105-2081	GREENWICH STREET/ LIBERTY STREET	00:11 08:10	4	1916	None Detected	0	0	0	0.0042	<0.0042	<21.00
030513923-0005 T-052105-2082	WASHINGTON STREET/ CEDAR STREET	00:15 08:14	3.95	1892	None Detected	0	0	0	0.0042	<0.0042	<21.00

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 1 of 3

CITY_21MC100_003219976



1430 Broadway, 10th Fl. New York, New York 10018
Phone: (212) 221-7822 - Fax: (212) 221-7840

Airborne Asbestos Fiber Analysis
by Transmission Electron Microscopy

Client Lower Manhattan Development Corporation
Address One Liberty Plaza, 20th Floor
New York, NY 10006
Collected By V. Bajomo
Collected 05/21/2005
Rotometer Standard

Job Number 46600-0000-00001
Date Received 5/21/2005
Date Analyzed 5/23/2005
Date Analyzed 130 Liberty Street

Lab ID Field ID	Sample Location	Start/ Stop	Flow	Volume (liters)	Asbestos Type(s)	Asbestos Structures		Non- Asbestos	Analytical Sensitivity (AS/cc)	Asbestos Concentration (AS/cc)	Asbestos Concentration (AS/mm2)
						≥ .5mm <5mm	≥ 5mm				
030513924-0001 T-052105-2084	WASHINGTON STREET/ ALBANY STREET	08:00 16:00	4	1920	None Detected	0	0	0	0.0042	<0.0042	<21.00
030513924-0002 T-052105-2085	ALBANY STREET/ GREENWICH STREET	08:03 16:03	4	1920	None Detected	0	0	0	0.0042	<0.0042	<21.00
030513924-0003 T-052105-2086	GREENWICH STREET	08:07 16:06	3.9	1868	None Detected	0	0	0	0.0043	<0.0043	<21.00
030513924-0004 T-052105-2087	GREENWICH STREET/ LIBERTY STREET	08:10 16:09	4	1916	None Detected	0	0	0	0.0042	<0.0042	<21.00
030513924-0005 T-052105-2088	WASHINGTON STREET/ CEDAR STREET	08:14 16:13	4	1916	None Detected	0	0	0	0.0042	<0.0042	<21.00

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 2 of 3

CITY_21MC100_003219977



1430 Broadway, 10th Fl. New York, New York 10018
Phone: (212) 221-7822 - Fax: (212) 221-7840

**Airborne Asbestos Fiber Analysis
by Transmission Electron Microscopy**

Client Lower Manhattan Development Corporation
Address One Liberty Plaza, 20th Floor
New York, NY 10006
Collected By A. Dvorkin/V. Bajomo
Collected 05/21/2005
Rotometer Standard

Job Number 46600-0000-00001
Date Received 05/22/2005
Date Analyzed 05/23/2005
Date Analyzed 130 Liberty Street

Lab ID Field ID	Sample Location	Start/ Stop	Flow	Volume (liters)	Asbestos Type(s)	Asbestos Structures		Non- Asbestos	Analytical Sensitivity (AS/cc)	Asbestos Concentration (AS/cc)	Asbestos Concentration (AS/mm2)
						≥ .5mm <5mm	≥ 5mm				
030514018-0001	WASHINGTON STREET/ ALBANY STREET	16:00 00:01	4	1924	None Detected	0	0	0	0.0042	<0.0042	<21.00
T-052105-2090											
030514018-0002	ALBANY STREET/ GREENWICH STREET	16:03 00:04	3.9	1876	None Detected	0	0	0	0.0043	<0.0043	<21.00
T-052105-2091											
030514018-0003	GREENWICH STREET	16:06 00:07	4	1924	None Detected	0	0	0	0.0042	<0.0042	<21.00
T-052105-2092											
030514018-0004	GREENWICH STREET/ LIBERTY STREET	16:09 00:09	4	1920	None Detected	0	0	0	0.0042	<0.0042	<21.00
T-052105-2093											
030514018-0005	WASHINGTON STREET/ CEDAR STREET	16:13 00:12	4	1916	None Detected	0	0	0	0.0042	<0.0042	<21.00
T-052105-2094											

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 3 of 3

CITY_21MC100_003219978