



1430 Broadway, 10th Fl. New York, New York 10018
Phone: (212) 221-7822 - Fax: (212) 221-7840

Airborne Asbestos Fiber Analysis
by Transmission Electron Microscopy

Client Lower Manhattan Development Corporation
Address One Liberty Plaza, 20th Floor
New York, NY 10006
Collected By A. Dvorkin/K. DaRocha
Collected 08/03/2005
Rotometer Standard

Job Number 46600-0000-00001
Date Received 8/3/2005
Date Analyzed 8/5/2005
Job Location 130 Liberty Street

Lab ID Field ID	Sample Location	Start/ Stop	Flow	Volume (liters)	Asbestos Type(s)	Asbestos Structures		Non- Asbestos	Analytical Sensitivity (AS/cc)	Asbestos Concentration (AS/cc)	Asbestos Concentration (AS/mm2)
						≥ .5mm <5mm	≥ 5mm				
030522539-0001 T-080305-3410	WASHINGTON STREET/ ALBANY STREET	00:03 08:02	4	1916	None Detected	0	0	0	0.0039	<0.0039	<19.00
030522539-0002 T-080305-3411	ALBANY STREET/ GREENWICH STREET	00:05 08:04	4	1916	None Detected	0	0	0	0.0038	<0.0038	<19.00
030522539-0003 T-080305-3412	GREENWICH STREET	00:07 08:06	3.9	1868	None Detected	0	0	0	0.0039	<0.0039	<19.00
030522539-0004 T-080305-3413	GREENWICH STREET/ LIBERTY STREET	00:10 08:09	3.95	1892	None Detected	0	0	0	0.0039	<0.0039	<19.00
030522539-0005 T-080305-3414	WASHINGTON STREET/ CEDAR STREET	00:12 08:12	3.95	1896	None Detected	0	0	0	0.0039	<0.0039	<19.00

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 1 of 3

CITY_21MC100_003220959



1430 Broadway, 10th Fl. New York, New York 10018
Phone: (212) 221-7822 - Fax: (212) 221-7840

Airborne Asbestos Fiber Analysis
by Transmission Electron Microscopy

Client Lower Manhattan Development Corporation
Address One Liberty Plaza, 20th Floor
New York, NY 10006
Collected By K. DaRocha
Collected 08/03/2005
Rotometer Standard

Job Number 46600-0000-00001
Date Received 8/3/2005
Date Analyzed 8/5/2005
Date Analyzed 130 Liberty Street

Lab ID Field ID	Sample Location	Start/ Stop	Flow	Volume (liters)	Asbestos Type(s)	Asbestos Structures		Non- Asbestos	Analytical Sensitivity (AS/cc)	Asbestos Concentration (AS/cc)	Asbestos Concentration (AS/mm2)
						≥ .5mm <5mm	≥ 5mm				
030522540-0001 T-080305-3416	WASHINGTON STREET/ ALBANY STREET	08:02 16:00	4	1912	None Detected	0	0	0	0.0039	<0.0039	<19.00
030522540-0002 T-080305-3417	ALBANY STREET/ GREENWICH STREET	08:04 16:03	4	1916	None Detected	0	0	0	0.0039	<0.0039	<19.00
030522540-0003 T-080305-3418	GREENWICH STREET	08:06 16:06	4	1920	None Detected	0	0	0	0.0039	<0.0039	<19.00
030522540-0004 T-080305-3419	GREENWICH STREET/ LIBERTY STREET	08:09 16:10	4	1924	None Detected	0	0	0	0.0038	<0.0038	<19.00
030522540-0005 T-080305-3420	WASHINGTON STREET/ CEDAR STREET	08:12 16:13	3.9	1876	None Detected	0	0	0	0.0039	<0.0039	<19.00

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 2 of 3

CITY_21MC100_003220960



1430 Broadway, 10th Fl. New York, New York 10018
Phone: (212) 221-7822 - Fax: (212) 221-7840

Airborne Asbestos Fiber Analysis
by Transmission Electron Microscopy

Client Lower Manhattan Development Corporation
Address One Liberty Plaza, 20th Floor
New York, NY 10006
Collected By D. Katehis/A. Dvorkin
Collected 08/03/2005
Rotometer Standard

Job Number 46600-0000-00001
Date Received 08/04/2005
Date Analyzed 08/05/2005
Date Analyzed 130 Liberty Street

Lab ID Field ID	Sample Location	Start/ Stop	Flow	Volume (liters)	Asbestos Type(s)	Asbestos Structures		Non- Asbestos	Analytical Sensitivity (AS/cc)	Asbestos Concentration (AS/cc)	Asbestos Concentration (AS/mm2)
						≥ .5mm <5mm	≥ 5mm				
030522781-0001 T-080305-3422	WASHINGTON STREET/ ALBANY STREET	16:00 00:05	4	1940	None Detected	0	0	0	0.0038	<0.0038	<19.00
030522781-0002 T-080305-3423	ALBANY STREET/ GREENWICH STREET	16:03 00:11	4	1952	None Detected	0	0	0	0.0038	<0.0038	<19.00
030522781-0003 T-080305-3424	GREENWICH STREET	16:06 00:18	4	1968	None Detected	0	0	0	0.0038	<0.0038	<19.00
030522781-0004 T-080305-3425	GREENWICH STREET/ LIBERTY STREET	16:10 00:24	4	1976	None Detected	0	0	0	0.0037	<0.0037	<19.00
030522781-0005 T-080305-3426	WASHINGTON STREET/ CEDAR STREET	16:13 00:29	4	1984	None Detected	0	0	0	0.0037	<0.0037	<19.00

Samples analyzed by EMSL Analytical, Inc.; NY ELAP ID# 10872 and 11506

Page 3 of 3