New York Lab
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email:

EMSL

Attn: Howard Bader
H.A. Bader Consultants
88 Bleecker St
Suite 4E
New York, NY 10012
Fax: (212) 477-8941 Phone: 212-475-4122
Project: DC 37 / 125 Barclay Street, NY, NY

Customer ID: HAB50
Customer PO:
Received: 09/25/01 5:00 PM

EMSL Order: 030104913
EMSL Project ID:
Analysis Date: 9/26/01

Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Final Rule (AHERA)

Sample	Volume	Area Analyzed	Non Asb	Asbestos Type(s)	# Structure 0.5µ - 5	# Structure 5µ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm²)	Asbestos Concentration (S/cc)	Notes
010 030104913-0001	1340.00	0.0625	5	Chrysotile	0	1	0.0046	16	0.0046	
09 030104913-0002	1330.00	0.0625	3	None Detected			0.0046	<16.00	<0.0046	
08 030104913-0003	1350.00	0.0625	2	None Detected			0.0046	<16.00	<0.0046	
07 030104913-0004	1370.00	0.0625	7	Chrysotile	1	0	0.0045	16	0.0045	
06 030104913-0005	1350.00	0.0625	2	None Detected			0.0046	<16.00	<0.0046	
05 030104913-0006	1350.00	0.0625	1	None Detected			0.0046	<16.00	<0.0046	
04 030104913-0007	1440.00	0.0625	5	None Detected			0.0043	<16.00	<0.0043	
03 030104913-0008	1430.00	0.0625	5	None Detected			0.0043	<16.00	<0.0043	
02 030104913-0009	1250.00	0.0625	2	None Detected			0.0049	<16.00	<0.0049	
01 030104913-0010	1250.00	0.0625	1	None Detected			0.0049	<16.00	<0.0049	

Jim Hall
Analyst

Laboratory Manager
or other approved signatory

Disclaimers: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by EMSL. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysts' accuracy and precision) is available upon request.
Accredited for NVLAP PLM/TEM #101048-0, NY State ELAP #11505

TEMAHERA-1

New York Lab
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email:

EMSL

Attn: Howard Bader
H.A. Bader Consultants
88 Bleecker St
Suite 4E
New York, NY 10012
Fax: (212) 477-8941 Phone: 212-475-4122
Project: DC 37/ 125 Barclay Street, New York, N.Y.

Customer ID: HAB50
Customer PO:
Received: 09/25/01 5:40 PM

EMSL Order: 030104915
EMSL Project ID:

Lead in Wipes by Flame AAS (SW 846, 7420)

Client Sample Description		Lab ID	Analyzed	Area	Lead Concentration	Notes
D301	10th FL N. Floor Tile 12x12	0001		n/a	<10.0 µg/wipe	
D302	10th Fl. S. Floor Tile 12x12	0002		n/a	<10.0 µg/wipe	
D303	Field Blank	0003		n/a	<10.0 µg/wipe	
D304	9th Fl. N. F.T. 12x12	0004		n/a	<10.0 µg/wipe	
D305	9th Fl. S. Window Sill Interior 12x12	0005		n/a	<10.0 µg/wipe	
D306	8th fl. S. FT 12x12	0006		n/a	<10.0 µg/wipe	
D307	8th fl. S. Desk 12x12	0007		n/a	<10.0 µg/wipe	
D308	7th Fl. N. 12x12 FT	0008		n/a	<10.0 µg/wipe	
D309	7th Fl S. 12x12 FT	0009		n/a	<10.0 µg/wipe	
D310	6th Fl N. 12x12 FT	0010		n/a	<10.0 µg/wipe	
D311	6th Fl S. 12x12 FT	0011		n/a	<10.0 µg/wipe	
D312	1st Fl. S. Entrance 12x12 Stone Floor	0012		n/a	<10.0 µg/wipe	
D313	1st Fl. N. Entrance 12x12 Stone Floor	0013		n/a	<10.0 µg/wipe	
D314	2nd Fl N. 12x12 FT	0014		n/a	<10.0 µg/wipe	
D315	2nd Fl S. 12x12 FT	0015		144 in^2	69.0 $\mu g/ft^2$	
D316	5th Fl. Exec. Office 527 12x12 Table Top	0016		144 in^2	41.0 $\mu g/ft^2$	
D317	5th Fl N. 12x12 Desk	0017		n/a	<10.0 µg/wipe	
D318	5th Fl S. 12x12 File Cabinet	0018		n/a	<10.0 µg/wipe	
D319	4th Fl. N. 12x12 FT	0019		n/a	<10.0 µg/wipe	
D320	4th Fl. S. 12x12 FT	0020		n/a	<10.0 µg/wipe	
D321	3rd Fl. N. 12x12 FT	0021		n/a	<10.0 µg/wipe	
D322	3rd Fl. S. 12x12 FT	0022		n/a	<10.0 µg/wipe	
D323	Field Blank	0023		n/a	<10.0 µg/wipe	