NYC 9/11 Public Portal Document

ASBESTOS ANALYTICAL REPORT

DEP

ASBESTOS CONTROL PROGRAM LABORATORY
96-05 HORACE HARDING EXPRESSWAY
CORONA, NEW YORK 11368
(718) 595-6309 FAX# (718) 595-6307

ELAP # 11045

TEST METHODS : 1) 40 CFR Part 763, Subpart F, App. A
2) Polarized Light Microscopy plus Stratified Point-Counting Method
3) EPA/600/R-93/116

Incident #: TRU0273MN03
Inspector : P. THEODORELLYS
Premise : 114 LIBERTY STREET
Boro : Manhattan
Analyst : G. ANAKHU

Date Collected: 03/17/03
Received: 03/17/03
Analyzed: 03/18/03

Client #:			
DEP Sample #:	30317/A019012	30317/A019013	30317/A019014
Laboratory #:	30317/344	30317/345	30317/346
Location Sampled:	9TH FL BEAM	9TH FL COLUMN	9TH FL BEAM
Color:	GREY	GREY	GREY
Homogenous:	Yes	Yes	Yes
Asbestos Present:	No	No	No
Results (%)			
	Cellulose 1	Cellulose 2	Cellulose 2
	Fibrous glass 48	Fibrous glass 40	Gypsum 43
	Matrix 51	Silicates 1	Silicates 1
		Matrix 57	Matrix 54

Comments:

Reviewed by: _____
Laboratory Director

This test report may not be reproduced except with the written approval of this laboratory. The test report relates only to the item(s) listed and does not represent a product endorsement by NVLAP or any other U.S. Government agency.