TAYLOR ENVIRONMENTAL GROUP

# DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD

PAGE 1 OF 1

| | | | |
|---|---|---|---|
| TECHNICIAN: G. Petranek. | CLIENT: NYC-SCA. | SITE ADDRESS: Stuyvesant H.S. | DATE SUBMITTED: 8-20-02 |
| DATE SAMPLED: 8-20-02 | CONTACT: Hamid Savoy | WORK AREA: 3rd Floor | DATE LOGGED: |
| ROTOMETER NO.: TEG-147 | PROJECT NO.: M477-15217-29881 | PROJECT MANAGER: C. McElgun | DATE APPROVED / SIGNATURE: |

| SAMPLE & PUMP # | LABORATORY NO. | SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE | FLOW ON/OFF | TIME ON | TIME OFF | DURATION MINUTES | FLOW (AVERAGE) | LITERS | FIELDS | FIBERS | F/MM² | F/CC |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 3-T1 | | IWA ☑ OWA ☐ Room 336 - Center | 8/8 | 1131 | 1434 | 183 | 8 | 1464 | | | | |
| 3-T2 | | IWA ☑ OWA ☐ 3rd Fl. Corridor @ Stairwell "R" | 8/8 | 1133 | 1435 | 182 | 8 | 1456 | | | | |
| 3-T3 | | IWA ☑ OWA ☐ Room 350 - West Side | 8/8 | 1135 | 1436 | 181 | 8 | 1448 | | | | |
| 3-T4 | | IWA ☑ OWA ☐ 3rd Fl Corridor @ Stair "W" | 8/8 | 1137 | 1437 | 180 | 8 | 1440 | | | | |
| 3-T5 | | IWA ☑ OWA ☐ 3rd Fl Corridor o/s Rm 315 | 8/9 | 1139 | 1438 | 179 | 8.5 | 1521.5 | | 0302 | 115 | 05 |
| 3-T6 | | IWA ☑ OWA ☐ 3rd Fl Corridor o/s Gym | 8/8 | 1141 | 1439 | 178 | 8 | 1424 | | | | |
| 3-T7 | | IWA ☑ OWA ☐ Gymnasium - South | 8/8 | 1143 | 1440 | 177 | 8 | 1416 | | | | |
| 3-T8 | | IWA ☑ OWA ☐ Gymnasium - North | 8/8 | 1145 | 1441 | 176 | 8 | 1408 | | | | |
| 3-T9 | | IWA ☑ OWA ☐ Room 307 - East Side | 8/8 | 1146 | 1442 | 176 | 8 | 1408 | | | | |
| 3-T10 | | IWA ☑ OWA ☐ 3rd Fl Corridor o/s Rm 302 | 8/9 | 1148 | 1443 | 175 | 8.5 | 1487.5 | | | | |
| FB-1 | | IWA ☐ OWA ☐ F/Blank-1 | | | | | | | | | | |
| FB-2 | | IWA ☐ OWA ☐ F/Blank-2 | | | | | | | | | | |
| SB-1 | | IWA ☐ OWA ☐ S/Blank | | | | | | | | | | |

02 AUG 20 PM 4:46

EMSL MANHATTAN RECEIVED

| | | | | | |
|---|---|---|---|---|---|
| RELINQUISHED TO TEG DROP BOX (SIGNATURE): [signature] | DATE: 8/20 | TIME: 1650 | RECEIVED FROM TEG DROP BOX (SIGNATURE): | DATE: | TIME: |
| RELINQUISHED BY: (SIGNATURE) | DATE: | TIME: | RECEIVED BY: (SIGNATURE): [signature] | DATE: 8/20/02 | TIME: 446 pm |
| ANALYST: (SIGNATURE): [signature] | DATE: 8/20/02 | TIME: 845 pm | COMMENTS: 6 HR T/A. ANALYZE T-1 THROUGH T-10 | | |

CIRCLE: PCM TEM BGRD PRE DURING POST OSHA OTHER

LOT #

FILTER MANUFACTURER

Call G. Taylor w/ Results

WHITE: Office Copy YELLOW: Lab Copy PINK: Samples ORANGE: Site Copy

10 @ 6 hr

CITY_21MC100_011273990

NYC 9/11 Public Portal Document

**EMSL Analytical, Inc.**
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email: manhattanlab@emsl.com

Attn: Taylor Environmental Group, Inc.
Floral Park Corporate Center
130 Jericho Tpke.
Floral Park, NY 11001
Fax: (516) 358-1780 Phone: 516-358-2955
Project: **M477-15217-29881 / NYC SCA / Stuyvesant H.S. 3rd Floor**

Customer ID: TAYL50
Customer PO:
Received: 08/20/02 4:45 PM
EMSL Order: 030211505
EMSL Project ID:
Analysis Date: 8/20/2002

## Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Final Rule (AHERA)

| Sample | Volume | Area Analyzed | Non Asb | Asbestos Type(s) | # Structures ≥ 0.5µ < 5 | # Structures ≥ 5µ | Analytical Sensitivity (S/cc) | Asbestos Concentration (S/mm²) | Asbestos Concentration (S/cc) | Notes |
|---|---|---|---|---|---|---|---|---|---|---|
| 3-T1 030211505-0001 | 1464.00 | 0.0625 | 0 | None Detected | | | 0.0042 | <16.00 | <0.0042 | |
| 3-T2 030211505-0002 | 1456.00 | 0.0625 | 0 | None Detected | | | 0.0042 | <16.00 | <0.0042 | |
| 3-T3 030211505-0003 | 1448.00 | 0.0625 | 0 | None Detected | | | 0.0043 | <16.00 | <0.0043 | |
| 3-T4 030211505-0004 | 1440.00 | 0.0625 | 0 | None Detected | | | 0.0043 | <16.00 | <0.0043 | |
| 3-T5 030211505-0005 | 1521.50 | 0.0625 | 0 | None Detected | | | 0.0040 | <16.00 | <0.0040 | |
| 3-T6 030211505-0006 | 1424.00 | 0.0625 | 0 | None Detected | | | 0.0043 | <16.00 | <0.0043 | |
| 3-T7 030211505-0007 | 1416.00 | 0.0625 | 0 | None Detected | | | 0.0044 | <16.00 | <0.0044 | |
| 3-T8 030211505-0008 | 1408.00 | 0.0625 | 0 | None Detected | | | 0.0044 | <16.00 | <0.0044 | |
| 3-T9 030211505-0009 | 1408.00 | 0.0625 | 0 | None Detected | | | 0.0044 | <16.00 | <0.0044 | |
| 3-T10 030211505-0010 | 1487.50 | 0.0625 | 0 | None Detected | | | 0.0041 | <16.00 | <0.0041 | |

Analyst(s)
*Roman Peysakhov (10)*

Laboratory Manager
or other approved signatory

Disclaimers: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by EMSL. This report must not be used to claim product endorsement by NVLAP or any agency of the U.S. Government. This report relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysts' accuracy and precision) is available upon request.
Accredited for NVLAP PLM/TEM #101048-9, NY State ELAP #11506





CITY_21MC100_011273991

NYC-WTC_000323638