NYC 9/11 Public Portal Document

New York Lab
307 West 38th Street, New York, NY 10018
Phone: 212-290-0051 Fax: 2122900058 Email:

Attn: CTSI-Consulting & Testing Services, Inc.
622 Georges Rd,
North Brunswick, NJ 08902
Fax: (732) 729-1803 Phone: 732-729-1600
Project: 100 Trinity / NYU

Customer ID: CTSI50
Customer PO:
Received: 09/24/01 2:45 PM
EMSL Order: 030104857
EMSL Project ID:

Analysis Date: 9/24/2001

Asbestos Analysis of Bulk Materials by PLM via the NY State ELAP 198.1 Method

				Non-Asbestos				Asbestos
Sample	Location	Appearance	Treatment	%	Fibrous	%	Non-Fibrous	% Type
00 T -001-FS 30104857-0001	Lobby, Inside Recration Room Dust Sample	Gray Fibrous Homogeneous	Teased Dissolved	10.00% 20.00%	Glass Cellulose	40.00% 30.00%	Non-fibrous (other) CA Carbonite	None Detected
00 T -002 -FS 30104857-0002	Roof-MER Adj to BMt, Dust Sample	Gray Fibrous Heterogeneous	Teased Dissolved	20.00% 25.00%	Glass Cellulose	25.00% 30.00%	Non-fibrous (other) CA Carbonite	<1% Chrysotile
00 T -003 -FS 30104857-0003	10th Floor Window Ledge (Ent)	Gray Fibrous Heterogeneous	Teased Dissolved	25.00% 20.00%	Glass Cellulose	25.00% 30.00%	Non-fibrous (other) CA Carbonite	<1% Chrysotile
00 T -004 -FS 30104857-0004	9th Floor, Room 907	Gray Fibrous Heterogeneous	Teased Dissolved	25.00% 20.00%	Glass Cellulose	28.50% 25.00%	Non-fibrous (other) CA Carbonite	1.50% Chrysotile
-005 -FS 30104857-0005	8th Floor, Dinning Room	Gray Fibrous Heterogeneous	Teased Dissolved	25.00% 25.00%	Glass Cellulose	23.30% 25.00%	Non-fibrous (other) CA Carbonite	1.70% Chrysotile
00 T -006 -FS 30104857-0006	4th Floor, Staircase very Dusty	Gray Fibrous Heterogeneous	Teased Dissolved	25.00% 20.00%	Glass Cellulose	23.80% 30.00%	Non-fibrous (other) CA Carbonite	1.20% Chrysotile
00 T -007 -FS 30104857-0007	Staircase to Basement Debris on Stairs	Gray Fibrous Heterogeneous	Teased Dissolved	25.00% 20.00%	Glass Cellulose	25.00% 30.00%	Non-fibrous (other) CA Carbonite	<1% Chrysotile

Williams John
Analyst

Laboratory Manager
or other approved signatory

...has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none ...ld should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL ...ronment, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government.
...lysis performed by EMSL Manhattan (NVLAP #101048-0), NY ELAP #11504

PLM PointCount=1

1

NYC-WTC_000340207