NYC 9/11 Public Portal Document

PHS

Parker House Services, Inc.

14 Leewood Circle
Eastchester, NY 10709
(914) 337-0229
Fax (914) 337-4955

October 27, 2001

Milford Management
155 West 68th Street
New York, NY 10023

Attn: Robert Gross

Re: Results of Air Testing @ 200 Rector Place, NYC

In accordance with protocols recently established and in full compliance with the NYC Asbestos Rules and Regulations, Title#15, Chapter#1, ambient air monitoring was conducted at the subject locations. The **final** results of said testing for **Friday October 26, 2001** were as follows:

LOCATION	SAMPLE#	TotalAsbestos StructuresDetected	Type of Asbestos
200 Rector Place Inside Lobby	1026-012	0.0	NSD
200 Rector Place	1026-013	0.0	NSD

(N.B. NSD = No Structures Detected)

All samples were analyzed by Transmission Electron Microscopy, Scilab ELAP#11480, NVLAP#200546-0.

All samples **pass final clearance levels. No further action is necessary.**

Very truly yours,

Michael LaCommare

Michael LaCommare-President

CITY_21MC100_002850446

NYC-WTC_000367014