NYC 9/11 Public Portal Document

ENVIROSCIENCE CONSULTANTS, INC.

2150 SMITHTOWN AVENUE
RONKONKOMA, NY 11779
PHONE: (631) 580-3191 • FACSIMILE: (631) 580-3195
WWW.ENVIROHEALTH.ORG

ASBESTOS BULK SAMPLE RESULTS

CLIENT:	AMERICAN STOCK EXCHANGE	CHAIN OF CUSTODY:	B-23-27
PROJECT:	ROOF MATERIAL 22 THAMES 86 TRINITY TOP OF TRADE FLOOR	SAMPLER:	L. SAVARESE
		DATE:	JANUARY 31, 2002
PAGE:	1 OF 1	DATE ANALYZED:	FEBRUARY 4, 2002

SAMPLE #	DESCRIPTION / LOCATION	RESULT
3-1	Top of Trading Floor, North	Trace Chrysotile
3-2	Top of Trading Floor, South	**1.0 % Chrysotile**
3-3	Top of Trading Floor, East	None Detected
3-4	Top of Trading Floor, West	None Detected
3-5	Top of Trading Floor, Northwest	None Detected
3-6	Top of Trading Floor, Southeast	None Detected
3-7	Top of Trading Floor, Southwest	None Detected

Reviewed by: _____ Analyzed by: _____

Asbestos Containing Materials contain more than 1% asbestos (shown in **bold** type).

Trace - Asbestos found is 1% or less; not considered ACM.

None Detected - No asbestos found in samples using polarized light microscopy (PLM).

None Detected by TEM - No asbestos found in samples using transmission electron microscopy (TEM).

Inconclusive - No asbestos found in non friable organically bound samples using polarized light microscopy (PLM).

ELAP # 11681

NYC-WTC_000367448