NYC 9/11 Public Portal Document




# ENVIROSCIENCE CONSULTANTS, INC.

2150 SMITHTOWN AVENUE
RONKONKOMA, NY 11779
PHONE: (631) 580-3191 • FACSIMILE: (631) 580-3195
WWW.ENVIROHEALTH.ORG


## MICRO VACUUM SAMPLE RESULTS

| | | | |
|---|---|---|---|
| CLIENT: | TECH CLEAN | CHAIN OF CUSTODY: | B-05-18 |
| PROJECT: | AMERICAN STOCK EXCHANGE<br>22 THAMES | SAMPLER: | B. GALLAGHER |
| | | DATE: | SEPTEMBER 24, 2001 |
| PAGE: | 1 OF 1 | DATE ANALYZED: | SEPTEMBER 25, 2001 |

| SAMPLE # | DESCRIPTION / LOCATION | RESULT |
|---|---|---|
| MV1 | First floor cafeteria lower level seating area, carpet | None Detected |
| MV2 | First floor cafeteria upper seating area, tile floor | None Detected |
| MV3 | First floor cafeteria serving area, tile floor | None Detected |
| MV4 | 8th floor room 801, carpet | None Detected |
| MV5 | 8th floor room 802, computer screen rack 2 | None Detected |
| MV6 | 8th floor room 806, northwest office desk | None Detected |
| MV7 | 6th floor by elevators | None Detected |
| MV8 | 6th floor room 610 | None Detected |
| MV9 | 6th floor main room | None Detected |
| MV10 | 5th floor near elevator | None Detected |
| MV11 | 5th floor room 514 | None Detected |
| MV12 | 5th floor fire escape near room 526 | None Detected |

Reviewed by: Edward M. Stolarski Analyzed by: ERO

**Asbestos Containing Materials contain more than 1% asbestos (shown in bold type).**

**Trace - Asbestos found is 1% or less; not considered ACM.**

**None Detected - No asbestos found in samples using polarized light microscopy (PLM).**

**None Detected by TEM - No asbestos found in samples using transmission electron microscopy (TEM).**

**Inconclusive - No asbestos found in non friable organically bound samples using polarized light microscopy (PLM).**

**ELAP # 11691**



NYC-WTC_000367455