NYC 9/11 Public Portal Document

EMSL Analytical, Inc.
107 Haddon Ave., Westmont, NJ 08108
Phone: (856) 858-4800 Fax: (856) 858-4960 Email: asiegel@EMSL.com

EMSL

Attn: Jeffrey J. Tasca
AMEC
285 Davidson Avenue Suite 100
Somerset, NJ 08873
Fax: (212) 227-5230 Phone: 732-302-9500
Project: 1-7418 0000

Customer ID: OGDE54
Customer PO: 1-7418-0000-0200
Received: 11/13/01 11:16 AM

EMSL Order: 040117373
EMSL Project ID:
Analysis Date: 11/14/2001

Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Location	Appearance	Treatment	Non-Asbestos % Fibrous	Non-Asbestos % Non-Fibrous	Asbestos % Type
110901-0305 *040117373-0001*	26 FLR	White Fibrous Homogeneous	Teased	5% Cellulose 5% Glass	90% Non-fibrous (other)	None Detected
110901-0310 *040117373-0002*	S WALL-26 FLR	White Fibrous Homogeneous	Teased	5% Cellulose 5% Glass	90% Non-fibrous (other)	None Detected
110901-0315 *040117373-0003*	S WALL ADJ TO 0310	Brown Fibrous Homogeneous	Teased	40% Cellulose 10% Glass	50% Non-fibrous (other)	None Detected
110901-2110 *040117373-0004*	PLATFORM @ COLUMN	Brown Fibrous Homogeneous	Teased	40% Cellulose 15% Glass	45% Non-fibrous (other)	None Detected
110901-2120 *040117373-0005*	20TH FLR	Brown Fibrous Homogeneous	Teased	35% Cellulose 10% Glass	55% Non-fibrous (other)	None Detected
110901-2140 *040117373-0006*	FLOOR 17 AMEX BLDG	Brown Fibrous Homogeneous	Teased	35% Cellulose 10% Glass	55% Non-fibrous (other)	None Detected
110901-2145 *040117373-0007*	WINDOWSILL	White Fibrous Homogeneous	Teased	5% Cellulose <1% Glass	95% Non-fibrous (other)	None Detected
110901-2150 *040117373-0008*	EAST WALL	Brown Fibrous Homogeneous	Teased	95% Cellulose 5% Glass		None Detected
110901-2130 *040117373-0009*	SOUTH WALL 20TH FLR	White Fibrous Homogeneous	Teased	3% Cellulose 10% Glass	87% Non-fibrous (other)	None Detected

Stephen Siegel

Analyst(s)
Delores Beard (9)

Stephen Siegel, CIH
or other approved signatory

PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. The above test report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. The above test must not be used by the client to claim product endorsement by NVLAP nor any agency of the United States Government.
Analysis performed by EMSL Westmont (NVLAP #101048-0), NY ELAP 10872

PLM-1

12/10/2001 16:45 FAX 610 828 6700 AMEC PHILADELPHIA 024/045

CITY_21MC100_000396425

NYC-WTC_000389366