NYC 9/11 Public Portal Document

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Antimony Concentration (ng/m3)	Barium Concentration (ng/m3)	Beryllium Concentration (ng/m3)
				3 * Target Air Quality Levels					15,000	15,000	60
				EPA Site Specific Trigger Levels					14,000	5,000	200
METALS-ST1-9/14/05	G5I150193001	Southwest Area (street-level)	9/14/2005	1627.9	Metals	6020	STL-SAC	9/16/2005	2.1	< 73.7	< 0.74
METALS-ST2-9/14/05	G5I150193002	Southeast Area (street-level)	9/14/2005	1658.2	Metals	6020	STL-SAC	9/16/2005	2.1	< 72.4	< 0.72
METALS-ST3-9/14/05	G5I150193003	Northeast Area (street-level)	9/14/2005	1688	Metals	6020	STL-SAC	9/16/2005	3.2	< 71.1	< 0.71
METALS-ST4-9/14/05	G5I150193004	Northwest Area (street-level)	9/14/2005	1645.8	Metals	6020	STL-SAC	9/16/2005	2.7	< 72.9	< 0.73
METALS-ST5-9/14/05	G5I150193005	Firehouse #10 (roof level)	9/14/2005	1720.8	Metals	6020	STL-SAC	9/16/2005	2.6	< 69.7	< 0.7
METALS-ST6-9/14/05	G5I150193006	Southwest Area (roof level)	9/14/2005	1854	Metals	6020	STL-SAC	9/16/2005	< 1.3	< 64.7	< 0.65
METALS-ST7-9/14/05	G5I150193007	Southeast Area (roof level)	9/14/2005	1783.4	Metals	6020	STL-SAC	9/16/2005	1.4	< 67.3	< 0.67
METALS-ST8-9/14/05	G5I150193008	Northeast Area (roof level)	9/14/2005	1721.8	Metals	6020	STL-SAC	9/16/2005	1.5	< 69.7	< 0.7
METALS-ST9-9/14/05	G5I150193009	Northwest Area (roof level)	9/14/2005	1666.9	Metals	6020	STL-SAC	9/16/2005	1.5	< 72	< 0.72
METALS-ST1-9/15/05	G5I170208001	Southwest Area (street-level)	9/15/2005	1735.1	Metals	6020	STL-SAC	9/17/2005	3.2	< 69.2	< 0.69
METALS-ST2-9/15/05	G5I170208002	Southeast Area (street level)	9/15/2005	1760.8	Metals	6020	STL-SAC	9/17/2005	4	79.7	< 0.68
METALS-ST3-9/15/05	G5I170208003	Northeast Area (street-level)	9/15/2005	1684.6	Metals	6020	STL-SAC	9/17/2005	3.4	< 71.2	< 0.71
METALS-ST4-9/15/05	G5I170208004	Northwest Area (street-level)	9/15/2005	1768.4	Metals	6020	STL-SAC	9/17/2005	3.1	< 67.9	< 0.68
METALS-ST5-9/15/05	G5I170208005	Firehouse #10 (roof level)	9/15/2005	1766.2	Metals	6020	STL-SAC	9/17/2005	3.1	< 67.9	< 0.68
METALS-ST6-9/15/05	G5I170208006	Southwest Area (roof level)	9/15/2005	1765.4	Metals	6020	STL-SAC	9/17/2005	1.8	< 68	< 0.68
METALS-ST7-9/15/05	G5I170208007	Southeast Area (roof level)	9/15/2005	1716.9	Metals	6020	STL-SAC	9/17/2005	2.2	< 69.9	< 0.7
METALS-ST8-9/15/05	G5I170208008	Northeast Area (roof level)	9/15/2005	1752.7	Metals	6020	STL-SAC	9/17/2005	2.1	< 68.5	< 0.68
METALS-ST9-9/15/05	G5I170208009	Northwest Area (roof level)	9/15/2005	1626	Metals	6020	STL-SAC	9/17/2005	2.3	< 73.8	< 0.74
METALS-ST1-9/16/05	G5I200153001	Southwest Area (street-level)	9/16/2005	1748.7	Metals	6020	STL-SAC	9/20/2005	3.9	< 68.6	< 0.69
METALS-ST2-9/16/05	G5I200153002	Southeast Area (street-level)	9/16/2005	1792.4	Metals	6020	STL-SAC	9/20/2005	5.2	< 66.9	< 0.67
METALS-ST3-9/16/05	G5I200153003	Northeast Area (street-level)	9/16/2005	1803.5	Metals	6020	STL-SAC	9/20/2005	3.5	< 66.5	< 0.67
METALS-ST4-9/16/05	G5I200153004	Northwest Area (street-level)	9/16/2005	1703.5	Metals	6020	STL-SAC	9/20/2005	2.9	< 70.4	< 0.70
METALS-ST5-9/16/05	G5I200153005	Firehouse #10 (roof level)	9/16/2005	1801.4	Metals	6020	STL-SAC	9/20/2005	2.7	< 66.6	< 0.67
METALS-ST6-9/16/05	G5I200153006	Southwest Area (roof level)	9/16/2005	1948.7	Metals	6020	STL-SAC	9/20/2005	2.5	< 61.6	< 0.62
METALS-ST7-9/16/05	G5I200153007	Southeast Area (roof level)	9/16/2005	1955.9	Metals	6020	STL-SAC	9/20/2005	2.6	< 61.4	< 0.61
METALS-ST8-9/16/05	G5I200153008	Northeast Area (roof level)	9/16/2005	1970.8	Metals	6020	STL-SAC	9/20/2005	2.4	< 60.9	< 0.61
METALS-ST9-9/16/05	G5I200153009	Northwest Area (roof level)	9/16/2005	669.6	Metals	6020	STL-SAC	9/20/2005	< 3.6	< 179	< 1.8
METALS-ST1-9/17/05	G5I200194001	Southwest Area (street-level)	9/17/2005	1721.3	Metals	6020	STL-SAC	9/20/2005	3.6	< 69.7	< 0.70
METALS-ST2-9/17/05	G5I200194002	Southeast Area (street-level)	9/17/2005	1686.3	Metals	6020	STL-SAC	9/20/2005	4.0	< 71.2	< 0.71
METALS-ST4-9/17/05	G5I200194003	Northwest Area (street-level)	9/17/2005	1747.2	Metals	6020	STL-SAC	9/20/2005	3.9	< 68.7	< 0.69
METALS-ST5-9/17/05	G5I200194004	Firehouse #10 (roof level)	9/17/2005	1757.1	Metals	6020	STL-SAC	9/20/2005	3.7	< 68.3	< 0.68
METALS-ST6-9/17/05	G5I200194005	Southwest Area (roof level)	9/17/2005	1783.9	Metals	6020	STL-SAC	9/20/2005	2.7	< 67.3	< 0.67
METALS-ST7-9/17/05	G5I200194006	Southeast Area (roof level)	9/17/2005	1719.4	Metals	6020	STL-SAC	9/20/2005	2.4	< 69.8	< 0.70
METALS-ST8-9/17/05	G5I200194007	Northeast Area (roof level)	9/17/2005	1752.7	Metals	6020	STL-SAC	9/20/2005	2.8	< 68.5	< 0.68
METALS-ST9-9/17/05	G5I200194008	Northwest Area (roof level)	9/17/2005	1620.8	Metals	6020	STL-SAC	9/20/2005	2.5	< 74.0	< 0.74
METALS-ST10-9/17/05	G5I200194009	North Side Sidewalk Bridge	9/17/2005	1715.7	Metals	6020	STL-SAC	9/20/2005	3.5	< 69.9	< 0.70
METALS-ST1-9/18/05	G5I200209001	Southwest Area (street-level)	9/18/2005	1750.5	Metals	6020	STL-SAC	9/20/2005	2.5	< 66.6	< 0.69
METALS-ST2-9/18/05	G5I200209002	Southeast Area (street-level)	9/18/2005	1811.7	Metals	6020	STL-SAC	9/20/2005	3.3	< 66.2	< 0.66
METALS-ST4-9/18/05	G5I200209003	Northwest Area (street-level)	9/18/2005	1740.8	Metals	6020	STL-SAC	9/20/2005	1.9	< 68.9	< 0.69
METALS-ST5-9/18/05	G5I200209004	Firehouse #10 (roof level)	9/18/2005	1799.7	Metals	6020	STL-SAC	9/20/2005	1.9	< 66.7	< 0.67
METALS-ST6-9/18/05	G5I200209005	Southwest Area (roof level)	9/18/2005	1905.3	Metals	6020	STL-SAC	9/20/2005	1.4	< 63.0	< 0.63
METALS-ST7-9/18/05	G5I200209006	Southeast Area (roof level)	9/18/2005	1846.6	Metals	6020	STL-SAC	9/20/2005	1.4	< 65.0	< 0.65
METALS-ST8-9/18/05	G5I200209007	Northeast Area (roof level)	9/18/2005	1907.2	Metals	6020	STL-SAC	9/20/2005	1.5	< 62.9	< 0.63
METALS-ST9-9/18/05	G5I200209008	Northwest Area (roof level)	9/18/2005	1756.5	Metals	6020	STL-SAC	9/20/2005	1.4	< 68.3	< 0.68
METALS-ST10-9/18/05	G5I200209009	North Side Sidewalk Bridge	9/18/2005	1751.2	Metals	6020	STL-SAC	9/20/2005	1.7	< 68.5	< 0.69

CITY_DEP_WORBY_CANNATA_SUBP_000054226

NYC-WTC_000422366

NYC 9/11 Public Portal Document

Cadmium Concentration (ng/m3)	Chromium (Total) Concentration (ng/m3)	Copper Concentration (ng/m3)	Lead Concentration (ng/m3)	Manganese Concentration (ng/m3)	Nickel Concentration (ng/m3)	Zinc Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
120	1,800	30,000	4,500	1,500	600	48,000			
2,000	600	100,000	5,000	500	20,000	100,000			
< 0.74	< 7.4	103	22.4	24.9	6.2	82	No	No	
< 0.72	< 7.2	316	22.8	23.4	6.1	113	No	No	
< 0.71	< 7.1	89.2	24.4	29.3	5.7	100	No	No	
< 0.73	< 7.3	112	25.1	23.3	5.8	128	No	No	
< 0.7	< 7	223	80	24.3	5.9	86	No	No	
< 0.65	< 6.5	66.8	10	12.3	4.9	37.2	No	No	
< 0.67	< 6.7	43.7	11.5	13.8	5.1	43.6	No	No	
< 0.7	< 7	27.6	12.3	13.1	4.8	51.5	No	No	
< 0.72	< 7.2	32.2	12.8	13.6	5.2	43.9	No	No	
< 0.69	< 6.9	87.8	17.6	19.9	6.7	89.1	No	No	
< 0.68	< 6.8	326	30.7	30.4	8.2	298	No	No	
< 0.71	< 7.1	140	23.4	23	6.3	149	No	No	
< 0.68	< 6.8	169	39.4	19.6	5.8	75	No	No	
< 0.68	< 6.8	86.8	16.6	22.7	6.2	94.8	No	No	
< 0.68	< 6.8	72.2	8.5	9	4.3	55.3	No	No	
< 0.7	< 7	50.3	8.7	10	4.8	63.8	No	No	
< 0.68	< 6.8	39.6	8.8	10	4.4	64	No	No	
< 0.74	< 7.4	34.1	10	11.4	5.2	70.7	No	No	
< 0.69	< 6.9	104	41.3	26.9	15.3	148	No	No	
< 0.67	7.1	162	43.4	28.1	16.5	307	No	No	
< 0.67	< 6.7	96.2	24.7	21.6	14.1	137	No	No	
< 0.70	< 7.0	112	19.9	18.9	13.3	61.6	No	No	
< 0.67	< 6.7	99.9	12.9	16.0	12.8	54.8	No	No	
< 0.62	< 6.2	72.3	11.2	11.0	12.6	58.1	No	No	
< 0.61	< 6.1	43.2	11.3	11.1	12.6	62.2	No	No	
< 0.61	< 6.1	47.2	11.4	11.3	12.5	58.9	No	No	
< 1.8	< 17.9	36.0	20.6	15.1	< 9.0	95.2	No	No	Reduced sample volume due to pump failure.
< 0.70	< 7.0	47.4	15.4	11.9	5.2	47.8	No	No	
< 0.71	< 7.1	66.7	13.9	12.9	5.1	63.1	No	No	
< 0.69	< 6.9	135	45.2	14.3	6.0	56.4	No	No	
< 0.68	< 6.8	82.6	11.4	13.1	5.5	40.8	No	No	
< 0.67	< 6.7	81.3	7.4	6.9	4.3	37.4	No	No	
< 0.70	< 7.0	26.6	6.4	6.6	3.9	22.6	No	No	
< 0.68	< 6.8	25.7	6.3	6.4	4.1	20.8	No	No	
< 0.74	< 7.4	16.5	6.7	7.0	4.2	21.8	No	No	
< 0.70	< 7.0	30.2	13.4	13.9	5.3	44.7	No	No	
< 0.69	< 6.9	47.9	36.4	13.0	4.3	55.0	No	No	
< 0.66	< 6.6	59.9	16.7	12.6	4.6	67.9	No	No	
< 0.69	< 6.9	88.0	18.3	8.9	4.0	28.9	No	No	
< 0.67	< 6.7	56.7	6.4	9.9	4.3	28.1	No	No	
< 0.63	< 6.3	47.4	6.0	6.6	4.4	28.1	No	No	
< 0.65	< 6.5	28.5	5.2	6.8	4.5	22.5	No	No	
< 0.63	< 6.3	30.2	5.2	7.4	4.7	22.4	No	No	
< 0.68	< 6.8	23.2	4.7	6.3	4.7	19.5	No	No	
< 0.69	< 6.9	24.4	5.7	8.4	3.8	25.8	No	No	

CITY_DEP_WORBY_CANNATA_SUBP_000054227

NYC-WTC_000422367

NYC 9/11 Public Portal Document

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Mercury (Total) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									900			
									3,000			
TotalHg-ST1-9/14/05	05BR1371-1	Southwest Area (street-level)	9/14/2005	0.53	Mercury	EPA 324/1631	BRL	9/16/2005	< 28.3	No	No	
TotalHg-ST2-9/14/05	05BR1371-2	Southeast Area (street-level)	9/14/2005	0.53	Mercury	EPA 324/1631	BRL	9/16/2005	< 28.3	No	No	
TotalHg-ST3-9/14/05	05BR1371-3	Northeast Area (street-level)	9/14/2005	0.54	Mercury	EPA 324/1631	BRL	9/16/2005	< 27.8	No	No	
TotalHg-ST4-9/14/05	05BR1371-4	Northwest Area (street-level)	9/14/2005	0.54	Mercury	EPA 324/1631	BRL	9/16/2005	< 27.8	No	No	
TotalHg-ST5-9/14/05	05BR1371-5	Firehouse #10 (roof level)	9/14/2005	0.55	Mercury	EPA 324/1631	BRL	9/16/2005	< 27.3	No	No	
TotalHg-ST6-9/14/05	05BR1371-6	Southwest Area (roof level)	9/14/2005	0.56	Mercury	EPA 324/1631	BRL	9/16/2005	< 26.8	No	No	
TotalHg-ST7-9/14/05	05BR1371-7	Southeast Area (roof level)	9/14/2005	0.56	Mercury	EPA 324/1631	BRL	9/16/2005	< 26.8	No	No	
TotalHg-ST8-9/14/05	05BR1371-8	Northeast Area (roof level)	9/14/2005	0.54	Mercury	EPA 324/1631	BRL	9/16/2005	< 27.8	No	No	
TotalHg-ST9-9/14/05	05BR1371-9	Northwest Area (roof level)	9/14/2005	0.21	Mercury	EPA 324/1631	BRL	9/16/2005	< 71.4	No	No	
TotalHg-ST1-9/15/05	05BR1389-1	Southwest Area (street-level)	9/15/2005	0.57	Mercury	EPA 324/1631	BRL	9/17/2005	< 26.3	No	No	
TotalHg-ST2-9/15/05	05BR1389-2	Southeast Area (street-level)	9/15/2005	0.57	Mercury	EPA 324/1631	BRL	9/17/2005	< 26.3	No	No	
TotalHg-ST3-9/15/05	05BR1389-3	Northeast Area (street-level)	9/15/2005	0.54	Mercury	EPA 324/1631	BRL	9/17/2005	< 27.8	No	No	
TotalHg-ST4-9/15/05	05BR1389-4	Northwest Area (street-level)	9/15/2005	0.58	Mercury	EPA 324/1631	BRL	9/17/2005	< 25.9	No	No	
TotalHg-ST5-9/15/05	05BR1389-5	Firehouse #10 (roof level)	9/15/2005	0.57	Mercury	EPA 324/1631	BRL	9/17/2005	< 26.3	No	No	
TotalHg-ST6-9/15/05	05BR1389-6	Southwest Area (roof level)	9/15/2005	0.54	Mercury	EPA 324/1631	BRL	9/17/2005	< 27.8	No	No	
TotalHg-ST7-9/15/05	05BR1389-7	Southeast Area (roof level)	9/15/2005	0.54	Mercury	EPA 324/1631	BRL	9/17/2005	< 27.8	No	No	
TotalHg-ST8-9/15/05	05BR1389-8	Northeast Area (roof level)	9/15/2005	0.54	Mercury	EPA 324/1631	BRL	9/17/2005	< 27.8	No	No	
TotalHg-ST9-9/15/05	05BR1389-9	Northwest Area (roof level)	9/15/2005	0.54	Mercury	EPA 324/1631	BRL	9/17/2005	< 27.8	No	No	
TotalHg-ST1-9/16/05	05BR1393-1	Southwest Area (street-level)	9/16/2005	0.57	Mercury	EPA 324/1631	BRL	9/20/2005	< 26.3	No	No	
TotalHg-ST2-9/16/05	05BR1393-2	Southeast Area (street-level)	9/16/2005	0.58	Mercury	EPA 324/1631	BRL	9/20/2005	< 25.9	No	No	
TotalHg-ST3-9/16/05	05BR1393-3	Northeast Area (street-level)	9/16/2005	0.56	Mercury	EPA 324/1631	BRL	9/20/2005	< 26.8	No	No	
TotalHg-ST4-9/16/05	05BR1393-4	Northwest Area (street-level)	9/16/2005	0.56	Mercury	EPA 324/1631	BRL	9/20/2005	< 26.8	No	No	
TotalHg-ST5-9/16/05	05BR1393-5	Firehouse #10 (roof level)	9/16/2005	0.58	Mercury	EPA 324/1631	BRL	9/20/2005	< 25.9	No	No	
TotalHg-ST6-9/16/05	05BR1393-6	Southwest Area (roof level)	9/16/2005	0.60	Mercury	EPA 324/1631	BRL	9/20/2005	< 25	No	No	
TotalHg-ST7-9/16/05	05BR1393-7	Southeast Area (roof level)	9/16/2005	0.58	Mercury	EPA 324/1631	BRL	9/20/2005	< 25.9	No	No	
TotalHg-ST8-9/16/05	05BR1393-8	Northeast Area (roof level)	9/16/2005	0.58	Mercury	EPA 324/1631	BRL	9/20/2005	< 25.9	No	No	
TotalHg-ST9-9/16/05	05BR1393-9	Northwest Area (roof level)	9/16/2005	0.58	Mercury	EPA 324/1631	BRL	9/20/2005	< 25.9	No	No	
TotalHg-ST1-9/17/05	05BR1394-1	Southwest Area (street-level)	9/17/2005	0.56	Mercury	EPA 324/1631	BRL	9/20/2005	< 26.8	No	No	
TotalHg-ST2-9/17/05	05BR1394-2	Southeast Area (street-level)	9/17/2005	0.54	Mercury	EPA 324/1631	BRL	9/20/2005	< 27.8	No	No	
TotalHg-ST4-9/17/05	05BR1394-3	Northwest Area (street-level)	9/17/2005	0.57	Mercury	EPA 324/1631	BRL	9/20/2005	< 26.3	No	No	
TotalHg-ST5-9/17/05	05BR1394-4	Firehouse #10 (roof level)	9/17/2005	0.56	Mercury	EPA 324/1631	BRL	9/20/2005	< 26.8	No	No	
TotalHg-ST6-9/17/05	05BR1394-5	Southwest Area (roof level)	9/17/2005	0.53	Mercury	EPA 324/1631	BRL	9/20/2005	< 28.3	No	No	
TotalHg-ST7-9/17/05	05BR1394-6	Southeast Area (roof level)	9/17/2005	0.54	Mercury	EPA 324/1631	BRL	9/20/2005	< 27.8	No	No	
TotalHg-ST8-9/17/05	05BR1394-7	Northeast Area (roof level)	9/17/2005	0.55	Mercury	EPA 324/1631	BRL	9/20/2005	< 27.3	No	No	
TotalHg-ST9-9/17/05	05BR1394-8	Northwest Area (roof level)	9/17/2005	0.54	Mercury	EPA 324/1631	BRL	9/20/2005	< 27.8	No	No	
TotalHg-ST10-9/17/05	05BR1394-9	North Side Sidewalk Bridge	9/17/2005	0.55	Mercury	EPA 324/1631	BRL	9/20/2005	< 27.3	No	No	

CITY_DEP_WORBY_CANNATA_SUBP_000054228

NYC-WTC_000422368

NYC 9/11 Public Portal Document

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m³)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Respirable Silica Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
		3 * Target Air Quality Levels							30			
		EPA Site Specific Trigger Levels							10			
SILICA-ST1-9/15/05	040517900-0001	Southwest Area (street-level)	9/ 5/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/19/2005	< 5	No	No	
SILICA-ST2-9/15/05	040517900-0002	Southeast Area (street-evel)	9/ 5/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/19/2005	< 5	No	No	
SILICA-ST3-9/15/05	040517900-0003	Northeast Area (street-level)	9/ 5/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/19/2005	5	No	No	
SILICA-ST4-9/15/05	040517900-0004	Northwest Area (street-level)	9/ 5/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/19/2005	< 5	No	No	
SILICA-ST5-9/15/05	040517900-0005	Firehouse #10 (roof level)	9/ 5/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/19/2005	< 5	No	No	
SILICA-ST6-9/15/05	040517900-0006	Southwest Area (roof leve)	9/ 5/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/19/2005	< 5	No	No	
SILICA-ST7-9/15/05	040517900-0007	Southeast Area (roof level)	9/ 5/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/19/2005	< 5	No	No	
SILICA ST8 9/15/05	040517900 0008	Northeast Area (roof level)	9/ 5/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/19/2005	< 5	No	No	
SILICA ST9 9/15/05	040517900 0009	Northwest Area (roof level)	9/ 5/2005		Silica	NIOSH 7500 XRD	EMSL	9/19/2005	< 5	No	No	Actual volume collected is unknown due to pump failure; reportec results in units of ug
SILICA ST1 9/16/05	040517988-0001	Southwest Area (street level)	9/ 6/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA ST2 9/16/05	040517988 0002	Southeast Area (street -evel)	9/ 6/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA ST3 9/16/05	040517988 0003	Northeast Area (street level)	9/ 6/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA-ST4-9/16/05	040517988-0004	Northwest Area (street-level)	9/ 6/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 21	No	No	Detection limit exceeds EPA Trigger Level due to primary peak spectral interference
SILICA-ST5-9/16/05	040517988-0005	Firehouse #10 (roof level)	9/ 6/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA-ST6-9/16/05	040517988-0006	Southwest Area (roof leve)	9/ 6/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA-ST7-9/16/05	040517988-0007	Southeast Area (roof level)	9/ 6/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA-ST8-9/16/05	040517988-0008	Northeast Area (roof level)	9/ 6/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	5	No	No	
SILICA-ST9-9/16/05	040517988-0009	Northwest Area (roof level)	9/ 6/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA-ST1-9/17/05	040517993-0001	Southwest Area (street-level)	9/ 7/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA-ST2-9/17/05	040517993-0002	Southeast Area (street-evel)	9/ 7/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA-ST4-9/17/05	040517993-0004	Northwest Area (street-level)	9/ 7/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	7	No	No	
SILICA-ST5-9/17/05	040517993-0005	Firehouse #10 (roof level)	9/ 7/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA-ST6-9/17/05	040517993-0006	Southwest Area (roof leve)	9/ 7/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA-ST7-9/17/05	040517993-0007	Southeast Area (roof level)	9/ 7/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA-ST8-9/17/05	040517993-0008	Northeast Area (roof level)	9/ 7/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA-ST9-9/17/05	040517993-0009	Northwest Area (roof level)	9/ 7/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA-ST10-9/ 7/05	040517993-0003	North Side Sidewalk Bridge	9/ 7/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA-ST1-9/18/05	040517996-0001	Southwest Area (street-level)	9/ 8/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA-ST2-9/18/05	040517996-0002	Southeast Area (street-evel)	9/ 8/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA-ST4-9/18/05	040517996-0004	Northwest Area (street-level)	9/ 8/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	Nu	Nu	
SILICA-ST5-9/18/05	040517996-0005	Firehouse #10 (roof level)	9/ 8/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA-ST6-9/18/05	040517996-0006	Southwest Area (roof leve)	9/ 8/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA-ST7-9/18/05	040517996-0007	Southeast Area (roof level)	9/ 8/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA-ST8-9/18/05	040517996-0008	Northeast Area (roof level)	9/ 8/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA-ST9-9/18/05	040517996-0009	Northwest Area (roof level)	9/ 8/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	No	No	
SILICA-ST10-9/ 8/05	040517996-0003	North Side Sidewalk Bridge	9/ 8/2005	0.96	Silica	NIOSH 7500 XRD	EMSL	9/20/2005	< 5	Nu	Nu	
SILICA-ST1-9/19/05	040518068-0001	Southwest Area (street-level)	9/ 9/2005	1.92	Silica	NIOSH 7500 XRD	EMSL	9/21/2105	< 3	Nu	Nu	
SILICA-ST2-9/19/05	040518068-0002	Southeast Area (street-evel)	9/ 9/2005	1.92	Silica	NIOSH 7500 XRD	EMSL	9/21/2105	< 3	Nu	Nu	
SILICA-ST4-9/19/05	040518068-0003	Northwest Area (street-level)	9/ 9/2005	1.92	Silica	NIOSH 7500 XRD	EMSL	9/21/2105	< 3	Nu	Nu	
SILICA-ST5-9/19/05	040518068-0004	Firehouse #10 (roof level)	9/ 9/2005	1.92	Silica	NIOSH 7500 XRD	EMSL	9/21/2105	< 3	Nu	Nu	
SILICA-ST6-9/19/05	040518068-0005	Southwest Area (roof leve)	9/ 9/2005	1.92	Silica	NIOSH 7500 XRD	EMSL	9/21/2105	< 3	No	No	
SILICA-ST7-9/19/05	040518068-0006	Southeast Area (roof level)	9/ 9/2005	1.92	Silica	NIOSH 7500 XRD	EMSL	9/21/2105	< 3	No	No	
SILICA-ST8-9/19/05	040518068-0007	Northeast Area (roof level)	9/ 9/2005	1.92	Silica	NIOSH 7500 XRD	EMSL	9/21/2105	< 3	No	No	
SILICA-ST9-9/19/05	040518068-0008	Northwest Area (roof level)	9/ 9/2005	1.92	Silica	NIOSH 7500 XRD	EMSL	9/21/2105	< 3	No	No	
SILICA-ST10-9/ 9/05	040518068-0009	North Side Sidewalk Bridge	9/ 9/2005	1.92	Silica	NIOSH 7500 XRD	EMSL	9/21/2105	< 3	No	No	
SILICA-ST1-9/20/05	040518158-0001	Southwest Area (street-level)	9/20/2005	1.92	Silica	NIOSH 7500 XRD	EMSL	9/22/2005	< 3	No	No	
SILICA-ST2-9/20/05	040518158-0002	Southeast Area (street-evel)	9/20/2005	1.92	Silica	NIOSH 7500 XRD	EMSL	9/22/2005	< 3	No	No	
SILICA-ST4-9/20/05	040518158-0003	Northwest Area (street-level)	9/20/2005	1.92	Silica	NIOSH 7500 XRD	EMSL	9/22/2005	< 3	No	No	
SILICA-ST5-9/20/05	040518158-0004	Firehouse #10 (roof level)	9/20/2005	1.92	Silica	NIOSH 7500 XRD	EMSL	9/22/2005	< 3	No	No	
SILICA-ST6-9/20/05	040518158-0005	Southwest Area (roof leve)	9/20/2005	1.92	Silica	NIOSH 7500 XRD	EMSL	9/22/2005	< 3	No	No	
SILICA-ST7-9/20/05	040518158-0006	Southeast Area (roof level)	9/20/2005	1.92	Silica	NIOSH 7500 XRD	EMSL	9/22/2005	< 3	No	No	
SILICA-ST8-9/20/05	040518158-0007	Northeast Area (roof level)	9/20/2005	1.92	Silica	NIOSH 7500 XRD	EMSL	9/22/2005	< 3	No	No	
SILICA-ST9-9/20/05	040518158-0008	Northwest Area (roof level)	9/20/2005	1.92	Silica	NIOSH 7500 XRD	EMSL	9/22/2005	< 3	No	No	
SILICA-ST10-9/20/05	040518158-0009	North Side Sidewalk Bridge	9/20/2005	1.92	Silica	NIOSH 7500 XRD	EMSL	9/22/2005	< 3	No	No	

CITY_DEP_WORBY_CANNATA_SUBP_000054229

NYC-WTC_000422369

NYC 9/11 Public Portal Document

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
					3 * Target Air Quality Levels					NA			
					EPA Site Specific Trigger Levels					70			
ASBESTOS-ST1-9/16/2005	030527800-0001	Southwest Area (street-level)	9/16/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST2-9/16/2005	030527800-0002	Southeast Area (street-level)	9/16/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST3-9/16/2005	030527800-0003	Northeast Area (street-level)	9/16/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST4-9/16/2005	030527800-0004	Northwest Area (street-level)	9/16/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST5-9/16/2005	030527800-0005	Firehouse #10 (roof level)	9/16/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST6-9/16/2005	030527800-0006	Southwest Area (roof level)	9/16/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST7-9/16/2005	030527800-0007	Southeast Area (roof level)	9/16/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST8-9/16/2005	030527800-0008	Northeast Area (roof level)	9/16/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST9-9/16/2005	030527800-0009	Northwest Area (roof level)	9/16/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST10-9/17/05	030527795-0003	North Side Sidewalk Bridge	9/17/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST1-9/17/05	030527795-0001	Southwest Area (street-level)	9/17/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST2-9/17/05	030527795-0002	Southeast Area (street-level)	9/17/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST4-9/17/05	030527795-0004	Northwest Area (street-level)	9/17/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST5-9/17/05	030527795-0005	Firehouse #10 (roof level)	9/17/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST6-9/17/05	030527795-0006	Southwest Area (roof level)	9/17/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST7-9/17/05	030527795-0007	Southeast Area (roof level)	9/17/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST8-9/17/05	030527795-0008	Northeast Area (roof level)	9/17/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST9-9/17/05	030527795-0009	Northwest Area (roof level)	9/17/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS ST1 9/18/05	030527797 0001	Southwest Area (street level)	9/18/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST2-9/18/05	030527797-0002	Southeast Area (street-level)	9/18/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST4-9/18/05	030527797-0003	Northwest Area (street-level)	9/18/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST5-9/18/05	030527797-0004	Firehouse #10 (roof level)	9/18/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST6-9/18/05	030527797-0005	Southwest Area (roof level)	9/18/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST7-9/18/05	030527797-0006	Southeast Area (roof level)	9/18/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST8-9/18/05	030527797-0007	Northeast Area (roof level)	9/18/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST9-9/18/05	030527797-0008	Northwest Area (roof level)	9/18/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST10-9/18/05	030527797-0009	North Side Sidewalk Bridge	9/18/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/19/2005	< 13.00	No	No	
ASBESTOS-ST1-9/19/05 A	030527931-1	Southwest Area (street-level)	9/19/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/20/2005	< 13.00	No	No	
ASBESTOS-ST2-9/19/05 A	030527931-2	Southeast Area (street-level)	9/19/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/20/2005	< 13.00	No	No	
ASBESTOS-ST4-9/19/05 A	030527931-3	Northwest Area (street-level)	9/19/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/20/2005	< 13.00	No	No	
ASBESTOS-ST5-9/19/05 A	030527931-4	Firehouse #10 (roof level)	9/19/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/20/2005	< 13.00	No	No	
ASBESTOS-ST6-9/19/05 A	030527931-5	Southwest Area (roof level)	9/19/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/20/2005	< 13.00	No	No	
ASBESTOS-ST7-9/19/05 A	030527931-6	Southeast Area (roof level)	9/19/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/20/2005	< 13.00	No	No	
ASBESTOS-ST8-9/19/05 A	030527931-7	Northeast Area (roof level)	9/19/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/20/2005	< 13.00	No	No	
ASBESTOS-ST9-9/19/05 A	030527931-8	Northwest Area (roof level)	9/19/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/20/2005	< 13.00	No	No	
ASBESTOS-ST10-9/19/05 A	030527931-9	North Side Sidewalk Bridge	9/19/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/20/2005	< 13.00	No	No	
ASBESTOS-ST1-9/19/05 B	030527931-10	Southwest Area (street-level)	9/19/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/20/2005	< 13.00	No	No	
ASBESTOS-ST2-9/19/05 B	030527931-11	Southeast Area (street-level)	9/19/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/20/2005	< 13.00	No	No	
ASBESTOS-ST4-9/19/05 B	030527931-12	Northwest Area (street-level)	9/19/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/20/2005	< 13.00	No	No	
ASBESTOS-ST5-9/19/05 B	030527931-13	Firehouse #10 (roof level)	9/19/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/20/2005	< 13.00	No	No	
ASBESTOS-ST6-9/19/05 B	030527931-14	Southwest Area (roof level)	9/19/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/20/2005	< 13.00	No	No	
ASBESTOS-ST7-9/19/05 B	030527931-15	Southeast Area (roof level)	9/19/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/20/2005	< 13.00	No	No	
ASBESTOS-ST8-9/19/05 B	030527931-16	Northeast Area (roof level)	9/19/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/20/2005	< 13.00	No	No	
ASBESTOS-ST9-9/19/05 B	030527931-17	Northwest Area (roof level)	9/19/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/20/2005	< 13.00	No	No	
ASBESTOS-ST10-9/19/05 B	030527931-18	North Side Sidewalk Bridge	9/19/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/20/2005	< 13.00	No	No	
ASBESTOS-ST1-9/20/05A	030528110-0001	Southwest Area (street-level)	9/20/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/2005	< 13.00	No	No	
ASBESTOS-ST2-9/20/05A	030528110-0002	Southeast Area (street-level)	9/20/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/2005	< 13.00	No	No	
ASBESTOS-ST4-9/20/05A	030528110-0003	Northwest Area (street-level)	9/20/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/2005	< 13.00	No	No	
ASBESTOS-ST5-9/20/05A	030528110-0004	Firehouse #10 (roof level)	9/20/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/2005	< 13.00	No	No	
ASBESTOS-ST6-9/20/05A	030528110-0005	Southwest Area (roof level)	9/20/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/2005	< 13.00	No	No	
ASBESTOS-ST7-9/20/05A	030528110-0006	Southeast Area (roof level)	9/20/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/2005	< 13.00	No	No	
ASBESTOS-ST8-9/20/05A	030528110-0007	Northeast Area (roof level)	9/20/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/2005	< 13.00	No	No	
ASBESTOS-ST9-9/20/05A	030528110-0008	Northwest Area (roof level)	9/20/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/2005	< 13.00	No	No	
ASBESTOS-ST10-9/20/05A	030528110-0009	North Side Sidewalk Bridge	9/20/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/2005	< 13.00	No	No	
ASBESTOS-ST1-9/20/05B	030528110-0010	Southwest Area (street-level)	9/20/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/2005	< 13.00	No	No	
ASBESTOS-ST2-9/20/05B	030528110-0011	Southeast Area (street-level)	9/20/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/2005	< 13.00	No	No	
ASBESTOS-ST4-9/20/05B	030528110-0012	Northwest Area (street-level)	9/20/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/2005	< 13.00	No	No	
ASBESTOS-ST5-9/20/05B	030528110-0013	Firehouse #10 (roof level)	9/20/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/2005	< 13.00	No	No	
ASBESTOS-ST6-9/20/05B	030528110-0014	Southwest Area (roof level)	9/20/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/2005	< 13.00	No	No	
ASBESTOS-ST7-9/20/05B	030528110-0015	Southeast Area (roof level)	9/20/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/2005	< 13.00	No	No	
ASBESTOS-ST8-9/20/05B	030528110-0016	Northeast Area (roof level)	9/20/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/2005	< 13.00	No	No	
ASBESTOS-ST9-9/20/05B	030528110-0017	Northwest Area (roof level)	9/20/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/2005	< 13.00	No	No	
ASBESTOS-ST10-9/20/05B	030528110-0018	North Side Sidewalk Bridge	9/20/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/21/2005	< 13.00	No	No	
ASBESTOS-ST1-9/21/05A	030528252-0001	Southwest Area (street-level)	9/21/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST1-9/21/05B	030528252-0010	Southwest Area (street-level)	9/21/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST2-9/21/05A	030528252-0002	Southeast Area (street-level)	9/21/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST2-9/21/05B	030528252-0011	Southeast Area (street-level)	9/21/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	

CITY_DEP_WORBY_CANNATA_SUBP_000054230

NYC-WTC_000422370

NYC 9/11 Public Portal Document

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
				3 * Target Air Quality Levels						NA			
				EPA Site Specific Trigger Levels						70			
ASBESTOS-ST4-9/21/05A	030528252-0003	Northwest Area (street-level)	9/21/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST4-9/21/05B	030528252-0012	Northwest Area (street-level)	9/21/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST5-9/21/05A	030528252-0004	Firehouse #10 (roof level)	9/21/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST5-9/21/05B	030528252-0013	Firehouse #10 (roof level)	9/21/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST6-9/21/05A	030528252-0005	Southwest Area (roof level)	9/21/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST6-9/21/05B	030528252-0014	Southwest Area (roof level)	9/21/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST7-9/21/05A	030528252-0006	Southeast Area (roof level)	9/21/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST7-9/21/05B	030528252-0015	Southeast Area (roof level)	9/21/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST8-9/21/05A	030528252-0007	Northeast Area (roof level)	9/21/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST8-9/21/05B	030528252-0016	Northeast Area (roof level)	9/21/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST9-9/21/05A	030528252-0008	Northwest Area (roof level)	9/21/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST9-9/21/05B	030528252-0017	Northwest Area (roof level)	9/21/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST10-9/21/05A	030528252-0009	North Side Sidewalk Bridge	9/21/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST10-9/21/05B	030528252-0018	North Side Sidewalk Bridge	9/21/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/22/2005	< 13.00	No	No	
ASBESTOS-ST1-9/22/05A	030528386-0001	Southwest Area (street-level)	9/22/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST1-9/22/05B	030528386-0010	Southwest Area (street-level)	9/22/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST2-9/22/05A	030528386-0002	Southeast Area (street-level)	9/22/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST2-9/22/05B	030528386-0011	Southeast Area (street-level)	9/22/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST4-9/22/05A	030528386-0003	Northwest Area (street-level)	9/22/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST4-9/22/05B	030528386-0012	Northwest Area (street-level)	9/22/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST5-9/22/05A	030528386-0004	Firehouse #10 (roof level)	9/22/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST5-9/22/05B	030528386-0013	Firehouse #10 (roof level)	9/22/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST6-9/22/05A	030528386-0005	Southwest Area (roof level)	9/22/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST6-9/22/05B	030528386-0014	Southwest Area (roof level)	9/22/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST7-9/22/05A	030528386-0006	Southeast Area (roof level)	9/22/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST7-9/22/05B	030528386-0015	Southeast Area (roof level)	9/22/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST8-9/22/05A	030528386-0007	Northeast Area (roof level)	9/22/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST8-9/22/05B	030528386-0016	Northeast Area (roof level)	9/22/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST9-9/22/05A	030528386-0008	Northwest Area (roof level)	9/22/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST9-9/22/05B	030528386-0017	Northwest Area (roof level)	9/22/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST10-9/22/05A	030528386-0009	North Side Sidewalk Bridge	9/22/2005	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	
ASBESTOS-ST10-9/22/05B	030528386-0018	North Side Sidewalk Bridge	9/22/2005	2	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	9/23/2005	< 13.00	No	No	

CITY_DEP_WORBY_CANNATA_SUBP_000054231

NYC-WTC_000422371

NYC 9/11 Public Portal Document

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
				Target Air Quality Levels						0.0009			
				EPA Site Specific Trigger Levels						NA			
ASBESTOS-ST1-9/16/2005	030527800-0001	Southwest Area (street-level)	9/16/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST2-9/16/2005	030527800-0002	Southeast Area (street-level)	9/16/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST3-9/16/2005	030527800-0003	Notheast Area (street-level)	9/16/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST4-9/16/2005	030527800-0004	Nothwest Area (street-level)	9/16/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST5-9/16/2005	030527800-0005	Firehouse #10 (roof level)	9/16/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST6-9/16/2005	030527800-0006	Southwest Area (roof level)	9/16/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST7-9/16/2005	030527800-0007	Southeast Area (roof level)	9/16/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST8-9/16/2005	030527800-0008	Notheast Area (roof level)	9/16/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST9-9/16/2005	030527800-0009	Nothwest Area (roof level)	9/16/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST1-9/17/05	030527795-0001	Southwest Area (street-level)	9/17/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST2-9/17/05	030527795-0002	Southeast Area (street-level)	9/17/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST4-9/17/05	030527795-0004	Nothwest Area (street-level)	9/17/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST5-9/17/05	030527795-0005	Firehouse #10 (roof level)	9/17/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST6-9/17/05	030527795-0006	Southwest Area (roof level)	9/17/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST7-9/17/05	030527795-0007	Southeast Area (roof level)	9/17/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST8-9/17/05	030527795-0008	Notheast Area (roof level)	9/17/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST9-9/17/05	030527795-0009	Nothwest Area (roof level)	9/17/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST10-9/17/05	030527795-0003	Noth Side Sidewalk Bridge	9/17/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS ST1 9/18/05	030527797 0001	Southwest Area (street level)	9/18/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST2-9/18/05	030527797-0002	Southeast Area (street-level)	9/18/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST4-9/18/05	030527797-0003	Nothwest Area (street-level)	9/18/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST5-9/18/05	030527797-0004	Firehouse #10 (roof level)	9/18/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST6-9/18/05	030527797-0005	Southwest Area (roof level)	9/18/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST7-9/18/05	030527797-0006	Southeast Area (roof level)	9/18/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST8-9/18/05	030527797-0007	Notheast Area (roof level)	9/18/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST9-9/18/05	030527797-0008	Nothwest Area (roof level)	9/18/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST10-9/18/05	030527797-0009	Noth Side Sidewalk Bridge	9/18/2005	1	2.880	Asbestos	PCME	EMSL	9/19/2005	< 0.00079	No	No	
ASBESTOS-ST1-9/19/05 A	030527931-1	Southwest Area (street-level)	9/19/2005	1	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST2-9/19/05 A	030527931-2	Southeast Area (street-level)	9/19/2005	1	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST4-9/19/05 A	030527931-3	Nothwest Area (street-level)	9/19/2005	1	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST5-9/19/05 A	030527931-4	Firehouse #10 (roof level)	9/19/2005	1	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST6-9/19/05 A	030527931-5	Southwest Area (roof level)	9/19/2005	1	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST7-9/19/05 A	030527931-6	Southeast Area (roof level)	9/19/2005	1	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST8-9/19/05 A	030527931-7	Notheast Area (roof level)	9/19/2005	1	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST9-9/19/05 A	030527931-8	Nothwest Area (roof level)	9/19/2005	1	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST10-9/19/05 A	030527931-9	Noth Side Sidewalk Bridge	9/19/2005	1	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST1-9/19/05 B	030527931-10	Southwest Area (street-level)	9/19/2005	2	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST2-9/19/05 B	030527931-11	Southeast Area (street-level)	9/19/2005	2	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST4-9/19/05 B	030527931-12	Nothwest Area (street-level)	9/19/2005	2	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST5-9/19/05 B	030527931-13	Firehouse #10 (roof level)	9/19/2005	2	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00079	No	No	
ASBESTOS-ST6-9/19/05 B	030527931-14	Southwest Area (roof level)	9/19/2005	2	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00086	No	No	
ASBESTOS-ST7-9/19/05 B	030527931-15	Southeast Area (roof level)	9/19/2005	2	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00086	No	No	
ASBESTOS-ST8-9/19/05 B	030527931-16	Notheast Area (roof level)	9/19/2005	2	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00086	No	No	
ASBESTOS-ST9-9/19/05 B	030527931-17	Nothwest Area (roof level)	9/19/2005	2	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00086	No	No	
ASBESTOS-ST10-9/19/05 B	030527931-18	Noth Side Sidewalk Bridge	9/19/2005	2	2.880	Asbestos	PCME	EMSL	9/20/2005	< 0.00086	No	No	
ASBESTOS-ST1-9/20/05A	030528110-0001	Southwest Area (street-level)	9/20/2005	1	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST2-9/20/05A	030528110-0002	Southeast Area (street-level)	9/20/2005	1	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST4-9/20/05A	030528110-0003	Nothwest Area (street-level)	9/20/2005	1	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST5-9/20/05A	030528110-0004	Firehouse #10 (roof level)	9/20/2005	1	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST6-9/20/05A	030528110-0005	Southwest Area (roof level)	9/20/2005	1	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST7-9/20/05A	030528110-0006	Southeast Area (roof level)	9/20/2005	1	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST8-9/20/05A	030528110-0007	Notheast Area (roof level)	9/20/2005	1	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST9-9/20/05A	030528110-0008	Nothwest Area (roof level)	9/20/2005	1	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST10-9/20/05A	030528110-0009	Noth Side Sidewalk Bridge	9/20/2005	1	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST1-9/20/05B	030528110-0010	Southwest Area (street-level)	9/20/2005	2	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST2-9/20/05B	030528110-0011	Southeast Area (street-level)	9/20/2005	2	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST4-9/20/05B	030528110-0012	Nothwest Area (street-level)	9/20/2005	2	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST5-9/20/05B	030528110-0013	Firehouse #10 (roof level)	9/20/2005	2	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST6-9/20/05B	030528110-0014	Southwest Area (roof level)	9/20/2005	2	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST7-9/20/05B	030528110-0015	Southeast Area (roof level)	9/20/2005	2	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST8-9/20/05B	030528110-0016	Notheast Area (roof level)	9/20/2005	2	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST9-9/20/05B	030528110-0017	Nothwest Area (roof level)	9/20/2005	2	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST10-9/20/05B	030528110-0018	Noth Side Sidewalk Bridge	9/20/2005	2	2.880	Asbestos	PCME	EMSL	9/21/2005	< 0.00079	No	No	
ASBESTOS-ST1-9/21/05A	030528252-0001	Southwest Area (street-level)	9/21/2005	1	2.880	Asbestos	PCME	EMSL	9/22/2005	< 0.00086	No	No	
ASBESTOS-ST1-9/21/05B	030528252-0010	Southwest Area (street-level)	9/21/2005	2	2.880	Asbestos	PCME	EMSL	9/22/2005	< 0.00079	No	No	
ASBESTOS-ST2-9/21/05A	030528252-0002	Southeast Area (street-level)	9/21/2005	1	2.880	Asbestos	PCME	EMSL	9/22/2005	< 0.00086	No	No	
ASBESTOS-ST2-9/21/05B	030528252-0011	Southeast Area (street-level)	9/21/2005	2	2.880	Asbestos	PCME	EMSL	9/22/2005	< 0.00079	No	No	

CITY_DEP_WORBY_CANNATA_SUBP_000054232

NYC-WTC_000422372

NYC 9/11 Public Portal Document

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										0.0009			
EPA Site Specific Trigger Levels										NA			
ASBESTOS-ST4-9/21/05A	030528252-0003	Nothwest Area (street-level)	9/21/2005	1	2.880	Asbestos	PCME	EMSL	9/22/2005	< 0.00086	No	No	
ASBESTOS-ST4-9/21/05B	030528252-0012	Nothwest Area (street-level)	9/21/2005	2	2.880	Asbestos	PCME	EMSL	9/22/2005	< 0.00079	No	No	
ASBESTOS-ST5-9/21/05A	030528252-0004	Firehouse #10 (roof level)	9/21/2005	1	2.880	Asbestos	PCME	EMSL	9/22/2005	< 0.00086	No	No	
ASBESTOS-ST5-9/21/05B	030528252-0013	Firehouse #10 (roof level)	9/21/2005	2	2.880	Asbestos	PCME	EMSL	9/22/2005	< 0.00086	No	No	
ASBESTOS-ST6-9/21/05A	030528252-0005	Southwest Area (roof level)	9/21/2005	1	2.880	Asbestos	PCME	EMSL	9/22/2005	< 0.00086	No	No	
ASBESTOS-ST6-9/21/05B	030528252-0014	Southwest Area (roof level)	9/21/2005	2	2.880	Asbestos	PCME	EMSL	9/22/2005	< 0.00086	No	No	
ASBESTOS-ST7-9/21/05A	030528252-0006	Southeast Area (roof level)	9/21/2005	1	2.880	Asbestos	PCME	EMSL	9/22/2005	< 0.00079	No	No	
ASBESTOS-ST7-9/21/05B	030528252-0015	Southeast Area (roof level)	9/21/2005	2	2.880	Asbestos	PCME	EMSL	9/22/2005	< 0.00086	No	No	
ASBESTOS-ST8-9/21/05A	030528252-0007	Notheast Area (roof level)	9/21/2005	1	2.880	Asbestos	PCME	EMSL	9/22/2005	< 0.00079	No	No	
ASBESTOS-ST8-9/21/05B	030528252-0016	Notheast Area (roof level)	9/21/2005	2	2.880	Asbestos	PCME	EMSL	9/22/2005	< 0.00086	No	No	
ASBESTOS-ST9-9/21/05A	030528252-0008	Nothwest Area (roof level)	9/21/2005	1	2.880	Asbestos	PCME	EMSL	9/22/2005	< 0.00079	No	No	
ASBESTOS-ST9-9/21/05B	030528252-0017	Nothwest Area (roof level)	9/21/2005	2	2.880	Asbestos	PCME	EMSL	9/22/2005	< 0.00086	No	No	
ASBESTOS-ST10-9/21/05A	030528252-0009	Noth Side Sidewalk Bridge	9/21/2005	1	2.880	Asbestos	PCME	EMSL	9/22/2005	< 0.00079	No	No	
ASBESTOS-ST10-9/21/05B	030528252-0018	Noth Side Sidewalk Bridge	9/21/2005	2	2.880	Asbestos	PCME	EMSL	9/22/2005	< 0.00086	No	No	
ASBESTOS-ST1-9/22/05A	030528386-0001	Southwest Area (street-level)	9/22/2005	1	2.880	Asbestos	PCME	EMSL	9/23/2005	< 0.00079	No	No	
ASBESTOS-ST1-9/22/05B	030528386-0010	Southwest Area (street-level)	9/22/2005	2	2.880	Asbestos	PCME	EMSL	9/23/2005	< 0.00086	No	No	
ASBESTOS-ST2-9/22/05A	030528386-0002	Southeast Area (street-level)	9/22/2005	1	2.880	Asbestos	PCME	EMSL	9/23/2005	< 0.00086	No	No	
ASBESTOS-ST2-9/22/05B	030528386-0011	Southeast Area (street-level)	9/22/2005	2	2.880	Asbestos	PCME	EMSL	9/23/2005	< 0.00086	No	No	
ASBESTOS-ST4-9/22/05A	030528386-0003	Nothwest Area (street-level)	9/22/2005	1	2.880	Asbestos	PCME	EMSL	9/23/2005	< 0.00086	No	No	
ASBESTOS-ST4-9/22/05B	030528386-0012	Nothwest Area (street-level)	9/22/2005	2	2.880	Asbestos	PCME	EMSL	9/23/2005	< 0.00086	No	No	
ASBESTOS-ST5-9/22/05A	030528386-0004	Firehouse #10 (roof level)	9/22/2005	1	2.880	Asbestos	PCME	EMSL	9/23/2005	< 0.00086	No	No	
ASBESTOS-ST5-9/22/05B	030528386-0013	Firehouse #10 (roof level)	9/22/2005	2	2.880	Asbestos	PCME	EMSL	9/23/2005	< 0.00086	No	No	
ASBESTOS-ST6-9/22/05A	030528386-0005	Southwest Area (roof level)	9/22/2005	1	2.880	Asbestos	PCME	EMSL	9/23/2005	< 0.00086	No	No	
ASBESTOS-ST6-9/22/05B	030528386-0014	Southwest Area (roof level)	9/22/2005	2	2.880	Asbestos	PCME	EMSL	9/23/2005	< 0.00086	No	No	
ASBESTOS-ST7-9/22/05A	030528386-0006	Southeast Area (roof level)	9/22/2005	1	2.880	Asbestos	PCME	EMSL	9/23/2005	< 0.00086	No	No	
ASBESTOS-ST7-9/22/05B	030528386-0015	Southeast Area (roof level)	9/22/2005	2	2.880	Asbestos	PCME	EMSL	9/23/2005	< 0.00086	No	No	
ASBESTOS-ST8-9/22/05A	030528386-0007	Notheast Area (roof level)	9/22/2005	1	2.880	Asbestos	PCME	EMSL	9/23/2005	< 0.00086	No	No	
ASBESTOS-ST8-9/22/05B	030528386-0016	Notheast Area (roof level)	9/22/2005	2	2.880	Asbestos	PCME	EMSL	9/23/2005	< 0.00086	No	No	
ASBESTOS-ST9-9/22/05A	030528386-0008	Nothwest Area (roof level)	9/22/2005	1	2.880	Asbestos	PCME	EMSL	9/23/2005	< 0.00086	No	No	
ASBESTOS-ST9-9/22/05B	030528386-0017	Nothwest Area (roof level)	9/22/2005	2	2.880	Asbestos	PCME	EMSL	9/23/2005	< 0.00086	No	No	
ASBESTOS-ST10-9/22/05A	030528386-0009	Noth Side Sidewalk Bridge	9/22/2005	1	2.880	Asbestos	PCME	EMSL	9/23/2005	< 0.00086	No	No	
ASBESTOS-ST10-9/22/05B	030528386-0018	Noth Side Sidewalk Bridge	9/22/2005	2	2.880	Asbestos	PCME	EMSL	9/23/2005	< 0.00086	No	No	

CITY_DEP_WORBY_CANNATA_SUBP_000054233

NYC-WTC_000422373

NYC 9/11 Public Portal Document

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Dioxin TEQ Concentration (pg/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
				3 * Target Air Quality Levels					0.75			
				EPA Site Specific Trigger Levels					25			
Dioxins/Furans-ST1-9/14/05	P5846_3476_002	Southwest Area (street-level)	9/14/2005	304	Dioxin	TO-9A	AP	9/16/2005	0.035	No	No	
Dioxins/Furans-ST2-9/14/05	P5846_3476_003	Southeast Area (street-level)	9/14/2005	322	Dioxin	TO-9A	AP	9/16/2005	0.0271	No	No	
Dioxins/Furans-ST3-9/14/05	P5846_3476_004	Northeast Area (street-level)	9/14/2005	311	Dioxin	TO-9A	AP	9/16/2005	0.0323	No	No	
Dioxins/Furans-ST4-9/14/05	P5846_3476_005	Northwest Area (street-level)	9/14/2005	335	Dioxin	TO-9A	AP	9/16/2005	0.0559	No	No	
Dioxins/Furans-ST5-9/14/05	P5846_3476_006	Firehouse #10 (roof level)	9/14/2005	336	Dioxin	TO-9A	AP	9/16/2005	0.0519	No	No	
Dioxins/Furans-ST6-9/14/05	P5846_3476_007	Southwest Area (roof level)	9/14/2005	362	Dioxin	TO-9A	AP	9/16/2005	0.0324	No	No	
Dioxins/Furans-ST8-9/14/05	P5846_3476_009	Northeast Area (roof level)	9/14/2005	299	Dioxin	TO-9A	AP	9/16/2005	0.0316	No	No	
Dioxins/Furans-ST9-9/14/05	P5846_3476_010	Northwest Area (roof level)	9/14/2005	329	Dioxin	TO-9A	AP	9/16/2005	0.0259	No	No	
Dioxins/Furans-ST1-9/15/05	P5848_3482_002	Southwest Area (street-level)	9/15/2005	311	Dioxin	TO-9A	AP	9/17/2005	0.0883	No	No	
Dioxins/Furans-ST2-9/15/05	P5848_3482_003	Southeast Area (street-level)	9/15/2005	344	Dioxin	TO-9A	AP	9/17/2005	0.0429	No	No	
Dioxins/Furans-ST3-9/15/05	P5848_3482_004	Northeast Area (street-level)	9/15/2005	303	Dioxin	TO-9A	AP	9/17/2005	0.0498	No	No	
Dioxins/Furans-ST4-9/15/05	P5848_3482_005	Northwest Area (street-level)	9/15/2005	358	Dioxin	TO-9A	AP	9/17/2005	0.0576	No	No	
Dioxins/Furans-ST5-9/15/05	P5848_3482_006	Firehouse #10 (roof level)	9/15/2005	340	Dioxin	TO-9A	AP	9/17/2005	0.0464	No	No	
Dioxins/Furans-ST6-9/15/05	P5848_3482_007	Southwest Area (roof level)	9/15/2005	349	Dioxin	TO-9A	AP	9/17/2005	0.0477	No	No	
Dioxins/Furans-ST7-9/15/05	P5848_3482_008	Southeast Area (roof level)	9/15/2005	340	Dioxin	TO-9A	AP	9/17/2005	0.0481	No	No	
Dioxins/Furans-ST8-9/15/05	P5848_3482_009	Northeast Area (roof level)	9/15/2005	310	Dioxin	TO-9A	AP	9/17/2005	0.0418	No	No	
Dioxins/Furans-ST9-9/15/05	P5848_3482_010	Northwest Area (roof level)	9/15/2005	315	Dioxin	TO-9A	AP	9/17/2005	0.0529	No	No	

CITY_DEP_WORBY_CANNATA_SUBP_000054234

NYC-WTC_000422374

NYC 9/11 Public Portal Document

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Total PCBs Concentration (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
3 * Target Air Quality Levels									0.36			
EPA Site Specific Trigger Levels									12			
PCB'S-ST1-9/14/05	AI10708	Southwest Area (street-level)	9/14/2005	6.63	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/16/2005	< 0.106	No	No	
PCB'S-ST2-9/14/05	AI10709	Southeast Area (street-level)	9/14/2005	6.648	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/16/2005	< 0.105	No	No	
PCB'S-ST3-9/14/05	AI10710	Northeast Area (street-level)	9/14/2005	6.763	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/16/2005	< 0.104	No	No	
PCB'S-ST4-9/14/05	AI10711	Northwest Area (street-level)	9/14/2005	6.707	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/16/2005	< 0.104	No	No	
PCB'S-ST5-9/14/05	AI10712	Firehouse #10 (roof level)	9/14/2005	6.89	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/16/2005	< 0.102	No	No	
PCB'S-ST6-9/14/05	AI10713	Southwest Area (roof level)	9/14/2005	0	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/16/2005	< 0.700	No	No	reported results in units of ug and not reflective of an exceedance.
PCB'S-ST7-9/14/05	AI10714	Southeast Area (roof level)	9/14/2005	0	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/16/2005	< 0.700	No	No	
PCB'S-ST8-9/14/05	AI10715	Northeast Area (roof level)	9/14/2005	6.764	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/16/2005	< 0.103	No	No	
PCB'S-ST9-9/14/05	AI10716	Northwest Area (roof level)	9/14/2005	6.914	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/16/2005	< 0.101	No	No	
PCB'S-ST1-9/15/05	AI10742RR1	Southwest Area (street-level)	9/15/2005	7.118	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/19/2005	< 0.0983	No	No	
PCB'S-ST2-9/15/05	AI10743RR1	Southeast Area (street-level)	9/15/2005	7.099	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/19/2005	< 0.0986	No	No	
PCB'S-ST3-9/15/05	AI10744RR1	Northeast Area (street-level)	9/15/2005	6.744	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/19/2005	< 0.104	No	No	
PCB'S-ST4-9/15/05	AI10745RR1	Northwest Area (street-level)	9/15/2005	7.205	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/19/2005	< 0.0972	No	No	
PCB'S-ST5-9/15/05	AI10746RR1	Firehouse #10 (roof level)	9/15/2005	7.098	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/19/2005	< 0.0986	No	No	
PCB'S-ST6-9/15/05	AI10747RR1	Southwest Area (roof level)	9/15/2005	6.795	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/19/2005	< 0.103	No	No	
PCB'S-ST7-9/15/05	AI10748	Southeast Area (roof level)	9/15/2005	6.739	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/19/2005	< 0.104	No	No	
PCB'S-ST8-9/15/05	AI10749	Northeast Area (roof level)	9/15/2005	6.771	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/19/2005	< 0.103	No	No	
PCB'S ST9 9/15/05	AI10750	Northwest Area (roof level)	9/15/2005	6.785	PCBs	EPA Method TO 10A/EPA 8082	Northeast	9/19/2005	< 0.103	No	No	
PCB'S-ST1-9/16/05	AI10832	Southwest Area (street-level)	9/16/2005	7.297	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/20/2005	< 0.0959	No	No	
PCB'S-ST2-9/16/05	AI10833	Southeast Area (street-level)	9/16/2005	7.2	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/20/2005	< 0.0972	No	No	
PCB'S-ST3-9/16/05	AI10834	Northeast Area (street-level)	9/16/2005	7.2	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/20/2005	< 0.0972	No	No	
PCB'S-ST4-9/16/05	AI10835	Northwest Area (street-level)	9/16/2005	6.959	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/20/2005	< 0.101	No	No	
PCB'S-ST5-9/16/05	AI10836	Firehouse #10 (roof level)	9/16/2005	7.2	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/20/2005	< 0.0972	No	No	
PCB'S-ST6-9/16/05	AI10837	Southwest Area (roof level)	9/16/2005	7.2	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/20/2005	< 0.0972	No	No	
PCB'S-ST7-9/16/05	AI10838	Southeast Area (roof level)	9/16/2005	7.2	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/20/2005	0.0152	No	No	
PCB'S-ST8-9/16/05	AI10839	Northeast Area (roof level)	9/16/2005	7.2	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/20/2005	< 0.0972	No	No	
PCB'S-ST9-9/16/05	AI10840	Northwest Area (roof level)	9/16/2005	7.2	PCBs	EPA Method TO-10A/EPA 8082	Northeast	9/20/2005	< 0.0972	No	No	

CITY_DEP_WORBY_CANNATA_SUBP_000054235

NYC-WTC_000422375

NYC 9/11 Public Portal Document

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	PAHs (BAP-equivalent) Concentration (ng/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
									102			
									3,400			
PAHs-ST1-09/14/05	G5I160185001	Southwest Area (street-level)	9/14/2005	323.6	PAHs	8270C SIM	STL-SAC	9/16/2005	< 7.8	No	No	
PAHs-ST2-09/14/05	G5I160185002	Southeast Area (street-level)	9/14/2005	325.3	PAHs	8270C SIM	STL-SAC	9/16/2005	< 7.8	No	No	
PAHs-ST3-09/14/05	G5I160185003	Northeast Area (street-level)	9/14/2005	352.6	PAHs	8270C SIM	STL-SAC	9/16/2005	< 7.0	No	No	
PAHs-ST4-09/14/05	G5I160185004	Northwest Area (street-level)	9/14/2005	326.3	PAHs	8270C SIM	STL-SAC	9/16/2005	< 7.8	No	No	
PAHs-ST5-09/14/05	G5I160185005	Firehouse #10 (roof level)	9/14/2005	327	PAHs	8270C SIM	STL-SAC	9/16/2005	< 7.8	No	No	
PAHs-ST6-09/14/05	G5I160185006	Southwest Area (roof level)	9/14/2005	314.4	PAHs	8270C SIM	STL-SAC	9/16/2005	< 8.0	No	No	
PAHs-ST7-09/14/05	G5I160185007	Southeast Area (roof level)	9/14/2005	329.2	PAHs	8270C SIM	STL-SAC	9/16/2005	< 7.5	No	No	
PAHs-ST8-09/14/05	G5I160185008	Northeast Area (roof level)	9/14/2005	325.9	PAHs	8270C SIM	STL-SAC	9/16/2005	< 7.8	No	No	
PAHs-ST9-09/14/05	G5I160185009	Northwest Area (roof level)	9/14/2005	315.8	PAHs	8270C SIM	STL-SAC	9/16/2005	< 8.0	No	No	

CITY_DEP_WORBY_CANNATA_SUBP_000054236

NYC-WTC_000422376

NYC 9/11 Public Portal Document

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
		Target Air Quality Levels					150			
		EPA Site Specific Trigger Levels					130			
PM10-ST1-9/14/2005	Southwest Area (street-level)	9/14/2005	1440	Particulate	Direct Read	Met One E-BAM	55.9	No	No	
PM10-ST2-9/14/2005	Southeast Area (street-level)	9/14/2005	1440	Particulate	Direct Read	Met One E-BAM	55.9	No	No	
PM10-ST3-9/14/2005	Northeast Area (street-level)	9/14/2005	1440	Particulate	Direct Read	Met One E-BAM	52	No	No	
PM10-ST4-9/14/2005	Northwest Area (street-level)	9/14/2005	1440	Particulate	Direct Read	Met One E-BAM	53.3	No	No	
PM10-ST5-9/14/2005	Firehouse #10 (roof level)	9/14/2005	1440	Particulate	Direct Read	Met One E-BAM	45.5	No	No	
PM10-ST6-9/14/2005	Southwest Area (roof level)	9/14/2005	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST7-9/14/2005	Southeast Area (roof level)	9/14/2005	1440	Particulate	Direct Read	Met One E-BAM	35.1	No	No	
PM10-ST8-9/14/2005	Northeast Area (roof level)	9/14/2005	1440	Particulate	Direct Read	Met One E-BAM	36.4	No	No	
PM10-ST9-9/14/2005	Northwest Area (roof level)	9/14/2005	1440	Particulate	Direct Read	Met One E-BAM	37.7	No	No	
PM10-ST1-9/15/2005	Southwest Area (street-level)	9/15/2005	1440	Particulate	Direct Read	Met One E-BAM	37.7	No	No	
PM10-ST2-9/15/2005	Southeast Area (street-level)	9/15/2005	1440	Particulate	Direct Read	Met One E-BAM	52	No	No	
PM10-ST3-9/15/2005	Northeast Area (street-level)	9/15/2005	1440	Particulate	Direct Read	Met One E-BAM	36.4	No	No	
PM10-ST4-9/15/2005	Northwest Area (street-level)	9/15/2005	1440	Particulate	Direct Read	Met One E-BAM	36.4	No	No	
PM10-ST5-9/15/2005	Firehouse #10 (roof level)	9/15/2005	1440	Particulate	Direct Read	Met One E-BAM	33.8	No	No	
PM10-ST6-9/15/2005	Southwest Area (roof level)	9/15/2005	1440	Particulate	Direct Read	Met One E-BAM	32.5	No	No	
PM10-ST7-9/15/2005	Southeast Area (roof level)	9/15/2005	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST8-9/15/2005	Northeast Area (roof level)	9/15/2005	1440	Particulate	Direct Read	Met One E-BAM	32.5	No	No	
PM10-ST9-9/15/2005	Northwest Area (roof level)	9/15/2005	1440	Particulate	Direct Read	Met One E-BAM	35.1	No	No	
PM10-ST1-9/16/2005	Southwest Area (street-level)	9/16/2005	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST2-9/16/2005	Southeast Area (street-level)	9/16/2005	1440	Particulate	Direct Read	Met One E-BAM	28.6	No	No	
PM10-ST4-9/16/2005	Northwest Area (street-level)	9/16/2005	1440	Particulate	Direct Read	Met One E-BAM	31.2	No	No	
PM10-ST5-9/16/2005	Firehouse #10 (roof level)	9/16/2005	1440	Particulate	Direct Read	Met One E-BAM	32.5	No	No	
PM10-ST6-9/16/2005	Southwest Area (roof level)	9/16/2005	1440	Particulate	Direct Read	Met One E-BAM	37.7	No	No	
PM10-ST7-9/16/2005	Southeast Area (roof level)	9/16/2005	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST8-9/16/2005	Northeast Area (roof level)	9/16/2005	1440	Particulate	Direct Read	Met One E-BAM	33.8	No	No	
PM10-ST9-9/16/2005	Northwest Area (roof level)	9/16/2005	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST1-9/17/2005	Southwest Area (street-level)	9/17/2005	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST2-9/17/2005	Southeast Area (street-level)	9/17/2005	1440	Particulate	Direct Read	Met One E-BAM	33.8	No	No	
PM10-ST4-9/17/2005	Northwest Area (street-level)	9/17/2005	1440	Particulate	Direct Read	Met One E-BAM	44.2	No	No	
PM10-ST5-9/17/2005	Firehouse #10 (roof level)	9/17/2005	1440	Particulate	Direct Read	Met One E-BAM	44.2	No	No	
PM10-ST6-9/17/2005	Southwest Area (roof level)	9/17/2005	1440	Particulate	Direct Read	Met One E-BAM	35.1	No	No	
PM10-ST7-9/17/2005	Southeast Area (roof level)	9/17/2005	1440	Particulate	Direct Read	Met One E-BAM	33.8	No	No	
PM10-ST8-9/17/2005	Northeast Area (roof level)	9/17/2005	1440	Particulate	Direct Read	Met One E-BAM	33.8	No	No	
PM10-ST9-9/17/2005	Northwest Area (roof level)	9/17/2005	1440	Particulate	Direct Read	Met One E-BAM	33.8	No	No	
PM10-ST1-9/18/2005	Southwest Area (street-level)	9/18/2005	1440	Particulate	Direct Read	Met One E-BAM	15.6	No	No	
PM10-ST2-9/18/2005	Southeast Area (street-level)	9/18/2005	1440	Particulate	Direct Read	Met One E-BAM	14.3	No	No	
PM10-ST4-9/18/2005	Northwest Area (street-level)	9/18/2005	1440	Particulate	Direct Read	Met One E-BAM	16.9	No	No	
PM10-ST5-9/18/2005	Firehouse #10 (roof level)	9/18/2005	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST6-9/18/2005	Southwest Area (roof level)	9/18/2005	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST7-9/18/2005	Southeast Area (roof level)	9/18/2005	1440	Particulate	Direct Read	Met One E-BAM	11.7	No	No	
PM10-ST8-9/18/2005	Northeast Area (roof level)	9/18/2005	1440	Particulate	Direct Read	Met One E-BAM	11.7	No	No	
PM10-ST9-9/18/2005	Northwest Area (roof level)	9/18/2005	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM10-ST10-9/18/2005	North Side Sidewalk Bridge	9/18/2005	1440	Particulate	Direct Read	Met One E-BAM	11.7	No	No	
PM10-ST1-9/19/2005	Southwest Area (street-level)	9/19/2005	1440	Particulate	Direct Read	Met One E-BAM	31.2	No	No	
PM10-ST2-9/19/2005	Southeast Area (street-level)	9/19/2005	1440	Particulate	Direct Read	Met One E-BAM	37.7	No	No	
PM10-ST4-9/19/2005	Northwest Area (street-level)	9/19/2005	1440	Particulate	Direct Read	Met One E-BAM	31.2	No	No	
PM10-ST5-9/19/2005	Firehouse #10 (roof level)	9/19/2005	1440	Particulate	Direct Read	Met One E-BAM	42.9	No	No	
PM10-ST6-9/19/2005	Southwest Area (roof level)	9/19/2005	1440	Particulate	Direct Read	Met One E-BAM	27.3	No	No	
PM10-ST7-9/19/2005	Southeast Area (roof level)	9/19/2005	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST8-9/19/2005	Northeast Area (roof level)	9/19/2005	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST9-9/19/2005	Northwest Area (roof level)	9/19/2005	1440	Particulate	Direct Read	Met One E-BAM	27.3	No	No	
PM10-ST10-9/19/2005	North Side Sidewalk Bridge	9/19/2005	1440	Particulate	Direct Read	Met One E-BAM	32.5	No	No	
PM10-ST1-9/20/2005	Southwest Area (street-level)	9/20/2005	1440	Particulate	Direct Read	Met One E-BAM	53.3	No	No	
PM10-ST2-9/20/2005	Southeast Area (street-level)	9/20/2005	1440	Particulate	Direct Read	Met One E-BAM	62.4	No	No	
PM10-ST4-9/20/2005	Northwest Area (street-level)	9/20/2005	1440	Particulate	Direct Read	Met One E-BAM	57.2	No	No	
PM10-ST5-9/20/2005	Firehouse #10 (roof level)	9/20/2005	1440	Particulate	Direct Read	Met One E-BAM	57.2	No	No	
PM10-ST6-9/20/2005	Southwest Area (roof level)	9/20/2005	1440	Particulate	Direct Read	Met One E-BAM	48.1	No	No	
PM10-ST7-9/20/2005	Southeast Area (roof level)	9/20/2005	1440	Particulate	Direct Read	Met One E-BAM	46.8	No	No	
PM10-ST8-9/20/2005	Northeast Area (roof level)	9/20/2005	1440	Particulate	Direct Read	Met One E-BAM	57.2	No	No	
PM10-ST9-9/20/2005	Northwest Area (roof level)	9/20/2005	1440	Particulate	Direct Read	Met One E-BAM	53.3	No	No	

CITY_DEP_WORBY_CANNATA_SUBP_000054237

NYC-WTC_000422377

NYC 9/11 Public Portal Document

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
		Target Air Quality Levels					150			
		EPA Site Specific Trigger Levels					130			
PM10-ST10-9/20/2005	North Side Sidewalk Bridge	9/20/2005	1440	Particulate	Direct Read	Met One E-BAM	54.6	No	No	
PM10-ST1-9/21/2005	Southwest Area (street-level)	9/21/2005	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM10-ST2-9/21/2005	Southeast Area (street-level)	9/21/2005	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST4-9/21/2005	Northwest Area (street-level)	9/21/2005	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM10-ST5-9/21/2005	Firehouse #10 (roof level)	9/21/2005	1440	Particulate	Direct Read	Met One E-BAM	31.2	No	No	
PM10-ST6-9/21/2005	Southwest Area (roof level)	9/21/2005	1440	Particulate	Direct Read	Met One E-BAM	16.9	No	No	
PM10-ST7-9/21/2005	Southeast Area (roof level)	9/21/2005	1440	Particulate	Direct Read	Met One E-BAM	15.6	No	No	
PM10-ST8-9/21/2005	Northeast Area (roof level)	9/21/2005	1440	Particulate	Direct Read	Met One E-BAM	20.8	No	No	
PM10-ST9-9/21/2005	Northwest Area (roof level)	9/21/2005	1440	Particulate	Direct Read	Met One E-BAM	16.9	No	No	
PM10-ST10-9/21/2005	North Side Sidewalk Bridge	9/21/2005	1440	Particulate	Direct Read	Met One E-BAM	24.7	No	No	
PM10-ST1-9/22/2005	Southwest Area (street-level)	9/22/2005	1440	Particulate	Direct Read	Met One E-BAM	32.5	No	No	
PM10-ST2-9/22/2005	Southeast Area (street-level)	9/22/2005	1440	Particulate	Direct Read	Met One E-BAM	52	No	No	
PM10-ST4-9/22/2005	Northwest Area (street-level)	9/22/2005	1440	Particulate	Direct Read	Met One E-BAM	36.4	No	No	
PM10-ST5-9/22/2005	Firehouse #10 (roof level)	9/22/2005	1440	Particulate	Direct Read	Met One E-BAM	79.3	No	No	
PM10-ST6-9/22/2005	Southwest Area (roof level)	9/22/2005	1440	Particulate	Direct Read	Met One E-BAM	27.3	No	No	
PM10-ST7-9/22/2005	Southeast Area (roof level)	9/22/2005	1440	Particulate	Direct Read	Met One E-BAM	24.7	No	No	
PM10-ST8-9/22/2005	Northeast Area (roof level)	9/22/2005	1440	Particulate	Direct Read	Met One E-BAM	28.6	No	No	
PM10-ST9-9/22/2005	Northwest Area (roof level)	9/22/2005	1440	Particulate	Direct Read	Met One E-BAM	31.2	No	No	
PM10-ST10-9/22/2005	North Side Sidewalk Bridge	9/22/2005	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST1-9/23/2005	Southwest Area (street-level)	9/23/2005	1440	Particulate	Direct Read	Met One E-BAM	40.3	No	No	
PM10-ST2-9/23/2005	Southeast Area (street-level)	9/23/2005	1440	Particulate	Direct Read	Met One E-BAM	50.7	No	No	
PM10-ST4-9/23/2005	Northwest Area (street-level)	9/23/2005	1440	Particulate	Direct Read	Met One E-BAM	45.5	No	No	
PM10-ST5-9/23/2005	Firehouse #10 (roof level)	9/23/2005	1440	Particulate	Direct Read	Met One E-BAM	58.5	No	No	
PM10-ST6-9/23/2005	Southwest Area (roof level)	9/23/2005	1440	Particulate	Direct Read	Met One E-BAM	31.2	No	No	
PM10-ST7-9/23/2005	Southeast Area (roof level)	9/23/2005	1440	Particulate	Direct Read	Met One E-BAM	31.2	No	No	
PM10-ST8-9/23/2005	Northeast Area (roof level)	9/23/2005	1440	Particulate	Direct Read	Met One E-BAM	35.1	No	No	
PM10-ST9-9/23/2005	Northwest Area (roof level)	9/23/2005	1440	Particulate	Direct Read	Met One E-BAM	55.9	No	No	
PM10-ST10-9/23/2005	North Side Sidewalk Bridge	9/23/2005	1440	Particulate	Direct Read	Met One E-BAM	35.1	No	No	
PM10-ST1-9/24/2005	Southwest Area (street-level)	9/24/2005	1440	Particulate	Direct Read	Met One E-BAM	14.3	No	No	
PM10-ST2-9/24/2005	Southeast Area (street-level)	9/24/2005	1440	Particulate	Direct Read	Met One E-BAM	29.9	No	No	
PM10-ST4-9/24/2005	Northwest Area (street-level)	9/24/2005	1440	Particulate	Direct Read	Met One E-BAM	20.8	No	No	
PM10-ST5-9/24/2005	Firehouse #10 (roof level)	9/24/2005	1440	Particulate	Direct Read	Met One E-BAM	18.2	No	No	
PM10-ST6-9/24/2005	Southwest Area (roof level)	9/24/2005	1440	Particulate	Direct Read	Met One E-BAM	16.9	No	No	
PM10-ST7-9/24/2005	Southeast Area (roof level)	9/24/2005	1440	Particulate	Direct Read	Met One E-BAM	14.3	No	No	
PM10-ST8-9/24/2005	Northeast Area (roof level)	9/24/2005	1440	Particulate	Direct Read	Met One E-BAM	22.1	No	No	
PM10-ST9-9/24/2005	Northwest Area (roof level)	9/24/2005	1440	Particulate	Direct Read	Met One E-BAM	71.5	No	No	
PM10-ST10-9/24/2005	North Side Sidewalk Bridge	9/24/2005	1440	Particulate	Direct Read	Met One E-BAM	16.9	No	No	

CITY_DEP_WORBY_CANNATA_SUBP_000054238

NYC-WTC_000422378

NYC 9/11 Public Portal Document

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
			Target Air Quality Levels				40			
			EPA Site Specific Trigger Levels				65			
PM2.5-ST1-9/14/2005	Southwest Area (street-level)	9/14/2005	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM2.5-ST2-9/14/2005	Southeast Area (street-level)	9/14/2005	1440	Particulate	Direct Read	Met One E-BAM	24.7	No	No	
PM2.5-ST3-9/14/2005	Northeast Area (street-level)	9/14/2005	1440	Particulate	Direct Read	Met One E-BAM	24.7	No	No	
PM2.5-ST4-9/14/2005	Northwest Area (street-level)	9/14/2005	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM2.5-ST5-9/14/2005	Firehouse #10 (roof level)	9/14/2005	1440	Particulate	Direct Read	Met One E-BAM	27.3	No	No	
PM2.5-ST6-9/14/2005	Southwest Area (roof level)	9/14/2005	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM2.5-ST7-9/14/2005	Southeast Area (roof level)	9/14/2005	1440	Particulate	Direct Read	Met One E-BAM	28.6	No	No	
PM2.5-ST8-9/14/2005	Northeast Area (roof level)	9/14/2005	1440	Particulate	Direct Read	Met One E-BAM	27.3	No	No	
PM2.5-ST9-9/14/2005	Northwest Area (roof level)	9/14/2005	1440	Particulate	Direct Read	Met One E-BAM	24.7	No	No	
PM2.5-ST1-9/15/2005	Southwest Area (street-level)	9/15/2005	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST2-9/15/2005	Southeast Area (street-level)	9/15/2005	1440	Particulate	Direct Read	Met One E-BAM	15.6	No	No	
PM2.5-ST3-9/15/2005	Northeast Area (street-level)	9/15/2005	1440	Particulate	Direct Read	Met One E-BAM	15.6	No	No	
PM2.5-ST4-9/15/2005	Northwest Area (street-level)	9/15/2005	1440	Particulate	Direct Read	Met One E-BAM	14.3	No	No	
PM2.5-ST5-9/15/2005	Firehouse #10 (roof level)	9/15/2005	1440	Particulate	Direct Read	Met One E-BAM	18.2	No	No	
PM2.5-ST6-9/15/2005	Southwest Area (roof level)	9/15/2005	1440	Particulate	Direct Read	Met One E-BAM	15.6	No	No	
PM2.5-ST7-9/15/2005	Southeast Area (roof level)	9/15/2005	1440	Particulate	Direct Read	Met One E-BAM	18.2	No	No	
PM2.5-ST8-9/15/2005	Northeast Area (roof level)	9/15/2005	1440	Particulate	Direct Read	Met One E-BAM	19.5	No	No	
PM2.5-ST9-9/15/2005	Northwest Area (roof level)	9/15/2005	1440	Particulate	Direct Read	Met One E-BAM	16.9	No	No	
PM2.5-ST1-9/16/2005	Southwest Area (street-level)	9/16/2005	1440	Particulate	Direct Read	Met One E-BAM	14.3	No	No	
PM2.5-ST2-9/16/2005	Southeast Area (street-level)	9/16/2005	1440	Particulate	Direct Read	Met One E-BAM	16.9	No	No	
PM2.5-ST4-9/16/2005	Northwest Area (street-level)	9/16/2005	1440	Particulate	Direct Read	Met One E-BAM	18.2	No	No	
PM2.5-ST5-9/16/2005	Firehouse #10 (roof level)	9/16/2005	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM2.5-ST6-9/16/2005	Southwest Area (roof level)	9/16/2005	1440	Particulate	Direct Read	Met One E-BAM	22.1	No	No	
PM2.5-ST7-9/16/2005	Southeast Area (roof level)	9/16/2005	1440	Particulate	Direct Read	Met One E-BAM	18.2	No	No	
PM2.5-ST8-9/16/2005	Northeast Area (roof level)	9/16/2005	1440	Particulate	Direct Read	Met One E-BAM	28.6	No	No	
PM2.5-ST9-9/16/2005	Northwest Area (roof level)	9/16/2005	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM2.5-ST1-9/17/2005	Southwest Area (street-level)	9/17/2005	1440	Particulate	Direct Read	Met One E-BAM	22.1	No	No	
PM2.5-ST2-9/17/2005	Southeast Area (street-level)	9/17/2005	1440	Particulate	Direct Read	Met One E-BAM	22.1	No	No	
PM2.5-ST4-9/17/2005	Northwest Area (street-level)	9/17/2005	1440	Particulate	Direct Read	Met One E-BAM	20.8	No	No	
PM2.5-ST5-9/17/2005	Firehouse #10 (roof level)	9/17/2005	1440	Particulate	Direct Read	Met One E-BAM	31.2	No	No	
PM2.5-ST6-9/17/2005	Southwest Area (roof level)	9/17/2005	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM2.5-ST7-9/17/2005	Southeast Area (roof level)	9/17/2005	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM2.5-ST8-9/17/2005	Northeast Area (roof level)	9/17/2005	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM2.5-ST9-9/17/2005	Northwest Area (roof level)	9/17/2005	1440	Particulate	Direct Read	Met One E-BAM	24.7	No	No	
PM2.5-ST1-9/18/2005	Southwest Area (street-level)	9/18/2005	1440	Particulate	Direct Read	Met One E-BAM	7.8	No	No	
PM2.5-ST2-9/18/2005	Southeast Area (street-level)	9/18/2005	1440	Particulate	Direct Read	Met One E-BAM	7.8	No	No	
PM2.5-ST4-9/18/2005	Northwest Area (street-level)	9/18/2005	1440	Particulate	Direct Read	Met One E-BAM	6.5	No	No	
PM2.5-ST5-9/18/2005	Firehouse #10 (roof level)	9/18/2005	1440	Particulate	Direct Read	Met One E-BAM	14.3	No	No	
PM2.5-ST6-9/18/2005	Southwest Area (roof level)	9/18/2005	1440	Particulate	Direct Read	Met One E-BAM	7.8	No	No	
PM2.5-ST7-9/18/2005	Southeast Area (roof level)	9/18/2005	1440	Particulate	Direct Read	Met One E-BAM	6.5	No	No	
PM2.5-ST8-9/18/2005	Northeast Area (roof level)	9/18/2005	1440	Particulate	Direct Read	Met One E-BAM	7.8	No	No	
PM2.5-ST9-9/18/2005	Northwest Area (roof level)	9/18/2005	1440	Particulate	Direct Read	Met One E-BAM	9.1	No	No	
PM2.5-ST10-9/18/2005	North Side Sidewalk Bridge	9/18/2005	1440	Particulate	Direct Read	Met One E-BAM	27.3	No	No	
PM2.5-ST1-9/19/2005	Southwest Area (street-level)	9/19/2005	1440	Particulate	Direct Read	Met One E-BAM	19.5	No	No	
PM2.5-ST2-9/19/2005	Southeast Area (street-level)	9/19/2005	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM2.5-ST4-9/19/2005	Northwest Area (street-level)	9/19/2005	1440	Particulate	Direct Read	Met One E-BAM	19.5	No	No	
PM2.5-ST5-9/19/2005	Firehouse #10 (roof level)	9/19/2005	1440	Particulate	Direct Read	Met One E-BAM	29.9	No	No	
PM2.5-ST6-9/19/2005	Southwest Area (roof level)	9/19/2005	1440	Particulate	Direct Read	Met One E-BAM	19.5	No	No	
PM2.5-ST7-9/19/2005	Southeast Area (roof level)	9/19/2005	1440	Particulate	Direct Read	Met One E-BAM	18.2	No	No	
PM2.5-ST8-9/19/2005	Northeast Area (roof level)	9/19/2005	1440	Particulate	Direct Read	Met One E-BAM	19.5	No	No	
PM2.5-ST9-9/19/2005	Northwest Area (roof level)	9/19/2005	1440	Particulate	Direct Read	Met One E-BAM	19.5	No	No	
PM2.5-ST10-9/19/2005	North Side Sidewalk Bridge	9/19/2005	1440	Particulate	Direct Read	Met One E-BAM	22.1	No	No	
PM2.5-ST1-9/20/2005	Southwest Area (street-level)	9/20/2005	1440	Particulate	Direct Read	Met One E-BAM	48.1	Yes	No	
PM2.5-ST2-9/20/2005	Southeast Area (street-level)	9/20/2005	1440	Particulate	Direct Read	Met One E-BAM	48.1	Yes	No	Regional Air Quality Influences; No action per 9/21/05 Telecon with EPA.
PM2.5-ST4-9/20/2005	Northwest Area (street-level)	9/20/2005	1440	Particulate	Direct Read	Met One E-BAM	41.6	Yes	No	
PM2.5-ST5-9/20/2005	Firehouse #10 (roof level)	9/20/2005	1440	Particulate	Direct Read	Met One E-BAM	45.5	Yes	No	
PM2.5-ST6-9/20/2005	Southwest Area (roof level)	9/20/2005	1440	Particulate	Direct Read	Met One E-BAM	42.9	Yes	No	
PM2.5-ST7-9/20/2005	Southeast Area (roof level)	9/20/2005	1440	Particulate	Direct Read	Met One E-BAM	42.9	Yes	No	
PM2.5-ST8-9/20/2005	Northeast Area (roof level)	9/20/2005	1440	Particulate	Direct Read	Met One E-BAM	49.4	Yes	No	
PM2.5-ST9-9/20/2005	Northwest Area (roof level)	9/20/2005	1440	Particulate	Direct Read	Met One E-BAM	42.9	Yes	No	

CITY_DEP_WORBY_CANNATA_SUBP_000054239

NYC-WTC_000422379

NYC 9/11 Public Portal Document

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM2.5 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
		Target Air Quality Levels					40			
		EPA Site Specific Trigger Levels					65			
PM2.5-ST10-9/20/2005	North Side Sidewalk Bridge	9/20/2005	1440	Particulate	Direct Read	Met One E-BAM	48.1	Yes	No	
PM2.5-ST1-9/21/2005	Southwest Area (street-level)	9/21/2005	1440	Particulate	Direct Read	Met One E-BAM	19.5	No	No	
PM2.5-ST2-9/21/2005	Southeast Area (street-level)	9/21/2005	1440	Particulate	Direct Read	Met One E-BAM	20.8	No	No	
PM2.5-ST4-9/21/2005	Northwest Area (street-level)	9/21/2005	1440	Particulate	Direct Read	Met One E-BAM	11.7	No	No	
PM2.5-ST5-9/21/2005	Firehouse #10 (roof level)	9/21/2005	1440	Particulate	Direct Read	Met One E-BAM	14.3	No	No	
PM2.5-ST6-9/21/2005	Southwest Area (roof level)	9/21/2005	1440	Particulate	Direct Read	Met One E-BAM	10.4	No	No	
PM2.5-ST7-9/21/2005	Southeast Area (roof level)	9/21/2005	1440	Particulate	Direct Read	Met One E-BAM	11.7	No	No	
PM2.5-ST8-9/21/2005	Northeast Area (roof level)	9/21/2005	1440	Particulate	Direct Read	Met One E-BAM	10.4	No	No	
PM2.5-ST9-9/21/2005	Northwest Area (roof level)	9/21/2005	1440	Particulate	Direct Read	Met One E-BAM	11.7	No	No	
PM2.5-ST10-9/21/2005	North Side Sidewalk Bridge	9/21/2005	1440	Particulate	Direct Read	Met One E-BAM	13	No	No	
PM2.5-ST1-9/22/2005	Southwest Area (street-level)	9/22/2005	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM2.5-ST2-9/22/2005	Southeast Area (street-level)	9/22/2005	1440	Particulate	Direct Read	Met One E-BAM	27.3	No	No	
PM2.5-ST4-9/22/2005	Northwest Area (street-level)	9/22/2005	1440	Particulate	Direct Read	Met One E-BAM	18.2	No	No	
PM2.5-ST5-9/22/2005	Firehouse #10 (roof level)	9/22/2005	1440	Particulate	Direct Read	Met One E-BAM	32.5	No	No	
PM2.5-ST6-9/22/2005	Southwest Area (roof level)	9/22/2005	1440	Particulate	Direct Read	Met One E-BAM	19.5	No	No	
PM2.5-ST7-9/22/2005	Southeast Area (roof level)	9/22/2005	1440	Particulate	Direct Read	Met One E-BAM	16.9	No	No	
PM2.5-ST8-9/22/2005	Northeast Area (roof level)	9/22/2005	1440	Particulate	Direct Read	Met One E-BAM	18.2	No	No	
PM2.5-ST9-9/22/2005	Northwest Area (roof level)	9/22/2005	1440	Particulate	Direct Read	Met One E-BAM	19.5	No	No	
PM2.5-ST10-9/22/2005	North Side Sidewalk Bridge	9/22/2005	1440	Particulate	Direct Read	Met One E-BAM	22.1	No	No	
PM2.5-ST1-9/23/2005	Southwest Area (street-level)	9/23/2005	1440	Particulate	Direct Read	Met One E-BAM	32.5	No	No	
PM2.5-ST2-9/23/2005	Southeast Area (street-level)	9/23/2005	1440	Particulate	Direct Read	Met One E-BAM	33.8	No	No	
PM2.5-ST4-9/23/2005	Northwest Area (street-level)	9/23/2005	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM2.5-ST5-9/23/2005	Firehouse #10 (roof level)	9/23/2005	1440	Particulate	Direct Read	Met One E-BAM	24.7	No	No	
PM2.5-ST6-9/23/2005	Southwest Area (roof level)	9/23/2005	1440	Particulate	Direct Read	Met One E-BAM	24.7	No	No	
PM2.5-ST7-9/23/2005	Southeast Area (roof level)	9/23/2005	1440	Particulate	Direct Read	Met One E-BAM	24.7	No	No	
PM2.5-ST8-9/23/2005	Northeast Area (roof level)	9/23/2005	1440	Particulate	Direct Read	Met One E-BAM	24.7	No	No	
PM2.5-ST9-9/23/2005	Northwest Area (roof level)	9/23/2005	1440	Particulate	Direct Read	Met One E-BAM	23.4	No	No	
PM2.5-ST10-9/23/2005	North Side Sidewalk Bridge	9/23/2005	1440	Particulate	Direct Read	Met One E-BAM	27.3	No	No	
PM2.5-ST1-9/24/2005	Southwest Area (street-level)	9/24/2005	1440	Particulate	Direct Read	Met One E-BAM	14.3	No	No	
PM2.5-ST2-9/24/2005	Southeast Area (street-level)	9/24/2005	1440	Particulate	Direct Read	Met One E-BAM	16.9	No	No	
PM2.5-ST4-9/24/2005	Northwest Area (street-level)	9/24/2005	1440	Particulate	Direct Read	Met One E-BAM	6.5	No	No	
PM2.5-ST5-9/24/2005	Firehouse #10 (roof level)	9/24/2005	1440	Particulate	Direct Read	Met One E-BAM	9.1	No	No	
PM2.5-ST6-9/24/2005	Southwest Area (roof level)	9/24/2005	1440	Particulate	Direct Read	Met One E-BAM	6.5	No	No	
PM2.5-ST7-9/24/2005	Southeast Area (roof level)	9/24/2005	1440	Particulate	Direct Read	Met One E-BAM	6.5	No	No	
PM2.5-ST8-9/24/2005	Northeast Area (roof level)	9/24/2005	1440	Particulate	Direct Read	Met One E-BAM	6.5	No	No	
PM2.5-ST9-9/24/2005	Northwest Area (roof level)	9/24/2005	1440	Particulate	Direct Read	Met One E-BAM	7.8	No	No	
PM2.5-ST10-9/24/2005	North Side Sidewalk Bridge	9/24/2005	1440	Particulate	Direct Read	Met One E-BAM	6.5	No	No	

CITY_DEP_WORBY_CANNATA_SUBP_000054240

NYC-WTC_000422380