



# ASBESTOS ANALYTICAL REPORT

**ASBESTOS CONTROL PROGRAM LABORATORY**  
**96-05 HORACE HARDING EXPRESSWAY**  
**CORONA, NEW YORK 11368**  
**(718) 595-6309 FAX# (718) 595-6307**

**ELAP # 11045**

**TEST METHODS: 1) 40 CFR Part 763, Subpart F, App. A**  
**2) Polarized Light Microscopy plus Stratified Point-Counting Method**  
**3) EPA/600/R-93/116**

Incident #: WTC071302  
 Inspector : C. LUTCHMEDIAL  
 Premise : 15 JOHN STREET  
 Boro : Manhattan  
 Analyst : E. BRUTUS

Date Collected: 07/13/02  
 Received: 07/13/02  
 Analyzed: 07/13/02

Client #:

|                   |               |               |                 |
|-------------------|---------------|---------------|-----------------|
| DEP Sample #:     | 20713/A058007 | 20713/A058008 | 20713/A058018   |
| Laboratory #:     | 20713/644     | 20713/645     | 20713/655       |
| Location Sampled: | WINDOW LEDGE  | WINDOW LEDGE  | TOP ELEC. CABLE |
| Color:            | BEIGE         | BEIGE         | GREY            |
| Homogenous:       | Yes           | Yes           | Yes             |
| Asbestos Present: | Yes           | Yes           | Yes             |

Results (%)

|               |      |               |    |               |    |
|---------------|------|---------------|----|---------------|----|
| Chrysotile    | 1.3  | Chrysotile    | <1 | Chrysotile    | <1 |
| Cellulose     | 8    | Cellulose     | 8  | Cellulose     | 5  |
| Fibrous glass | 25   | Fibrous glass | 25 | Fibrous glass | 30 |
| Matrix        | 65.7 | Matrix        | 67 | Matrix        | 65 |

Comments:

Reviewed by: *S. Delaney*  
 Laboratory Director

**This test report may not be reproduced except with the written approval of this laboratory. The test report relates only to the item(s) listed and does not represent a product endorsement by NVLAP or any other U.S. Government agency.**