



ASBESTOS ANALYTICAL REPORT

ASBESTOS CONTROL PROGRAM LABORATORY
96-05 HORACE HARDING EXPRESSWAY
CORONA, NEW YORK 11368
(718) 595-6309 FAX# (718) 595-6307

ELAP # 11045

TEST METHODS: 1) 40 CFR Part 763, Subpart F, App. A
2) Polarized Light Microscopy plus Stratified Point-Counting Method
3) EPA/600/R-93/116

Incident #: WTC071302
 Inspector : C. LUTCHMEDIAL
 Premise : 15 JOHN STREET
 Boro : Manhattan
 Analyst : E. BRUTUS

Date Collected: 07/13/02
 Received: 07/13/02
 Analyzed: 07/13/02

Client #:

DEP Sample #:	20713/A058004	20713/A058005	20713/A058006
Laboratory #:	20713/641	20713/642	20713/643
Location Sampled:	WESTSIDE ROOF	WINDOW LEDGE	WINDOW LEDGE
Color:	BEIGE	BEIGE	BEIGE
Homogenous:	Yes	Yes	Yes
Asbestos Present:	Yes	Yes	Yes

Results (%)

Chrysotile	1	Chrysotile	TRACE	Chrysotile	1.1
Amosite	TRACE	Cellulose	10	Amosite	TRACE
Cellulose	2	Fibrous glass	30	Cellulose	5
Fibrous glass	25	Matrix	60	Fibrous glass	25
Matrix	72			Matrix	68.9

Comments:

Reviewed by:

A. Adalony
 Laboratory Director

This test report may not be reproduced except with the written approval of this laboratory. The test report relates only to the item(s) listed and does not represent a product endorsement by NVLAP or any other U.S. Government agency.